



Government of Nepal
Ministry of Physical Planning and Works
Department of Urban Development and Building Construction
**Earthquake Risk Reduction and Recovery
Preparedness Programme for Nepal**



SEISMIC VULNERABILITY EVALUATION GUIDELINE FOR PRIVATE AND PUBLIC BUILDINGS



May 2011

Acknowledgement

Earthquake Risk Reduction and Recovery Preparedness Programme for Nepal (ERRRP Project) with the financial support of Government of Japan and UNDP- Nepal is engaged in carrying out various activities related to Earthquake safety and recovery preparedness in five municipalities identified and located in 5 different development region of Nepal. This program helped to strengthen the institutional and community level capacity to plan and implement earthquake risk reduction and disaster recovery preparedness in the country through capacity building, public education and awareness, retrofitting demonstration and preparation of study reports on building safety against seismic risk.

This book is expected to be helpful in achieving consistency in assessing the structural performance of existing buildings such as school buildings, hospitals etc. in earthquakes. The document is applicable to the common building types in Nepal with more detailed description of basically two most common types of buildings: *Reinforced Concrete Moment Resisting Frame Building* and *Brick Masonry Building*.

I appreciate and acknowledge the efforts of the project officials and professionals' team in preparing this book. I encourage the users of these guidelines for providing creative comments and suggestions to further improve the content and context to make this book more user-friendly.

Purna Kadariya
Secretary,
Ministry of Physical Planning and Works

Preface

This guideline is prepared by the Earthquake Risk Reduction and Recovery Preparedness Programme for Nepal (ERRRP Project). The objective of the preparation of this book is to render support to professionals and the authorities to implement qualitative and quantitative assessment of structural earthquake vulnerability of public and private buildings in Nepal. This Guideline is mainly targeted but not limited for use by civil engineers and technicians who are involved in seismic vulnerability assessment of buildings.

The seismic evaluation procedure presumes that when an earthquake causes damage to a building, a competent engineer can assess its effects. By determining how the structural damage has changed structural properties, it is feasible to develop further potential actions. The costs associated with these conceptual performance restoration measures quantify the loss associated with the earthquake damage.

Such vulnerability assessment also helps in deciding whether the building needs to be repaired, retrofitted or demolished. This document is expected to be of much use to the professionals working in the Department of Urban Development and Building Construction, who bear primary responsibility of implementing the National Building Code in Nepal. Similarly this book is assumed to be useful to all the stakeholders such as house owners, design engineers, occupants, municipalities etc.

Ashok Nath Uprety
Director General
Department of Urban Development and
Building Construction

Foreword

Nepal is a country that stands at 11th rank in the world with respect to vulnerability to earthquake hazards. In this context UNDP/BCPR (Bureau of Crisis Prevention and Recovery) with the support of Government of Japan initiated an Earthquake Risk Reduction and Recovery Preparedness (ERRRP) program in five high risk South Asian countries: Nepal, Bhutan, Bangladesh, India and Pakistan. ERRRP Project is being implemented by the Ministry of Physical Planning and Works (MPPW) in close coordination with other line ministries and Programme Municipalities. ERRRP project is engaged in carrying out various activities related to Earthquake safe constructions, Earthquake preparedness and recovery planning in five municipalities of Nepal located in different development regions. They are *Biratnagar, Hetauda, Pokhara, Birendranagar* and *Dhangadhi*.

Seismic vulnerability of important existing building stock in Nepal is yet not known. This requires evaluations to determine the likely structural performance of these buildings in large earthquakes. It is of the utmost importance to identify those buildings that are at risk and carry out reconstruction or seismic retrofit. This book provides guidance on seismic evaluation of common building types in Nepal and includes methods of qualitative as well as more detailed analysis and evaluation. It also discusses some feasible retrofitting measures for existing buildings identified as seismically deficient during evaluation process.

The Department of Urban Development and Building construction is the main agency responsible for the implementation of the Building Act. National Building Codes including the *NBC 105: Seismic Design of Buildings in Nepal* are developed as provisioned by the Act. This book is therefore expected to be useful for the department in its undertakings related to seismic assessment of existing buildings.

These guidelines are being prepared in two separate volumes. Volume I covers the process and methodology of vulnerability assessment at a pre-disaster phase whereas volume II shall be used for post disaster damage assessment. This book is prepared based on the experience in assessing hundreds of institutional, private and public buildings, hospital and school buildings and is based on the experiences gained by the project during conduction of similar works in its 5 project municipalities. This book is prepared by the ERRRP project with professional input from the National Society for Earthquake Technology-Nepal (NSET).

Reference of the documents in this book such as FEMA310 “Handbook for the Seismic Evaluation of Buildings”, ATC 40 “Seismic Evaluation and Retrofit of Concrete Buildings”, FEMA 356 “Pre-standard and Commentary for the Seismic Rehabilitation of Buildings” and IITK GSDMA Guideline on “Seismic Evaluation and Strengthening of Existing Buildings” is presented.

The guideline should be useful to those responsible for assessing the earthquake risk of buildings. It is believed that the engineers and practitioners from different government, non-government and other organizations will make use of it and the document will be in a continuous process of revision and improvement for future applications.

We are thankful to the project officials and professionals' team including NSET in preparing this book.

Sagar Krishna Joshi

National Project Manager, ERRRP

Suresh Prakash Acharya

National Project Director, ERRRP

and

Joint Secretary

Ministry of Physical Planning and Works

**Seismic Vulnerability Evaluation Guideline for
Private and Public Buildings**

(Part I: Pre-disaster vulnerability assessment)

Table of Contents

| | | |
|-------|---|----|
| 1. | INTRODUCTION..... | 1 |
| 1.1 | General | 1 |
| 1.2 | Basis and Scope..... | 1 |
| 1.3 | Guideline Dissemination | 1 |
| 2. | APPROACHES FOR DATA COLLECTION FOR VULNERABILITY ASSESSMENT..... | 2 |
| 2.1 | Physical Surveys..... | 2 |
| 2.2 | Interaction with Public Building Staff and Building Owners..... | 2 |
| 3. | QUALITATIVE STRUCTURAL ASSESSMENT | 3 |
| 3.1 | Introduction | 3 |
| 3.2 | Assessment of the Building | 3 |
| 3.2.1 | Identification of Seismicity of the Region | 3 |
| 3.2.2 | Establish Seismic Target Performance Level..... | 3 |
| 3.2.3 | Obtain As-Built Information..... | 3 |
| 3.2.4 | Building Typology Identification..... | 4 |
| 3.2.5 | Determining Fragility of the Identified Building Typology..... | 5 |
| 3.2.6 | Identification of Vulnerability Factors..... | 6 |
| 3.2.7 | Reinterpretation of the Building Fragility Based on Observed Vulnerability Factors..... | 7 |
| 3.3 | Conclusions and Recommendation | 7 |
| 4. | QUANTITATIVE ASSESSMENT..... | 8 |
| 4.1 | Introduction | 8 |
| 4.2 | Review Initial Considerations | 8 |
| 4.3 | Decide Performance Objective..... | 8 |
| 4.4 | Design Basis Earthquake..... | 9 |
| 4.5 | Detail Investigation | 9 |
| 4.5.1 | Non-Destructive Tests..... | 9 |
| 4.6 | Seismic Analysis and Design | 15 |
| 4.7 | Intervention Options for Better Seismic Performance..... | 15 |
| 4.7.1 | General..... | 15 |
| 4.7.2 | Retrofitting Methods | 15 |
| 4.7.3 | Seismic Retrofitting Strategies of Masonry Buildings..... | 17 |
| 4.7.4 | Seismic Retrofitting Strategies of Reinforced Concrete Buildings..... | 22 |
| 4.7.5 | Foundation Intervention | 26 |
| 4.8 | Cost Estimate..... | 27 |
| 4.9 | Comparison of Possible Performance of the Building after Retrofitting..... | 27 |
| 4.10 | Conclusions and Recommendations..... | 27 |

| | | |
|--------|---|----|
| 4.10.1 | Conclusions..... | 27 |
| 4.10.2 | Recommendations..... | 27 |
| 5. | REFERENCES..... | 29 |
| | Annex I: Private and Public Buildings Typology | 30 |
| | Annex II: Seismic Vulnerability Factors and their consequence | 34 |
| | Annex III: Vulnerability Factors Identification Checklist | 50 |
| | Annex IV: Damage Grades of Buildings | 58 |
| | Annex V: Modified Mercally Intensity Scale (MMI Scale) | 60 |
| | ANNEX VI : Example 1: Seismic Evaluation of Reinforced Concrete Moment Resisting Frame Building | 63 |
| | ANNEX VI : Example 2: Seismic Evaluation of Brick Masonry Building..... | 76 |

1. INTRODUCTION

1.1 General

This guideline is for assisting professionals and the authorities in Nepal to implement qualitative and quantitative assessment of structural earthquake vulnerability of public and private buildings in Nepal. The book is based on the experiences gained in Nepal in conducting visual qualitative as well as quantitative assessment of structural vulnerability of about a thousand buildings including about 20 major hospitals and about 600 schools. This guideline is rather based on the adaptation of different available methodologies to the local conditions of Nepal, than on the fundamental research. Efforts have been made to simplify the procedures described in this guideline. It provides step by step suggestions on the procedure of carrying out the seismic vulnerability assessment.

1.2 Basis and Scope

This Guideline is targeted mainly for the civil engineers and technicians who are involved in seismic vulnerability assessment of buildings. However, the government authorities, disaster risk managers and the policy makers, who are concerned with the safety of public and private buildings, may also use this guideline.

There are two phases of seismic vulnerability assessment. The *qualitative assessment* is for planning purpose and for identifying the priorities of intervention in the single building or the buildings complex. The *quantitative assessment* is for identification of retrofitting option and to examine the extent of intervention that would require in the building with consideration of technical, economic and practical feasibility. This guideline includes only some methods of detailed assessment and it is not meant to replace other methods of detailed structural vulnerability assessment.

1.3 Guideline Dissemination

The guideline has the potential to improve the current situation of earthquake vulnerability of our community if appropriately implemented by concerned authorities. This guideline should reach to engineers and practitioners who are working in the construction field. They should use this document effectively and efficiently.

Guidelines are more likely to be effective if they are disseminated by an active tutoring. The distribution of printed guidelines alone is found to be ineffective in achieving expected change in practice. Hence, to ensure better understanding and best use of the guideline, training for the users is recommended.

Guidelines must obviously be made as widely available as possible in order to facilitate implementation. It is necessary to have wide circulations among engineers and practitioners working in the field of earthquake engineering. It thus requires an integrated effort by the concerned authorities like local government, municipalities, NGO's, INGO's and other related organisations towards dissemination of publication in wider range.

Further, dissemination and implementation of a guideline should be monitored and evaluated. The guideline also needs thorough review by experts in the field. This should undergo mandatory updating procedure to transform it into pre-standard and then to building standard.

2. APPROACHES FOR DATA COLLECTION FOR VULNERABILITY ASSESSMENT

2.1 Physical Surveys

Acquisition of building data pertaining to the building is the first step in the evaluation process. The data shall be obtained preferably prior to the initial site visit and confirmed later during the visit. Construction documents like as-built drawing and Structural drawing shall be required for preliminary evaluation. Site condition and soil data shall also be collected if possible. However, if these documents are not available prior to the visit, all necessary information shall be collected during the site visit. The general information required is about building dimensions, construction age, and description of structural system (framing, lateral load resisting system, diaphragm system, basement and foundation system).

During the visits, the investigation of the interior of the structural members may require. In many buildings the structure is concealed by architectural finishes, and the inspector may need to get into attic, crawl over the spaces, and plenums to investigate. Some intrusive testing may require for determining the quality of material and allowable stresses. Even if structural drawings are available, some exposure of critical reinforcement may be necessary to verify conformity with the drawings. Photographs of building exterior and interiors may also be useful for the evaluation.

The evaluation should be based on facts, as opposed to assumptions, to the greatest extent possible. However, prudent engineering judgment may avoid huge efforts and cost of detailed investigation.

2.2 Interaction with Public Building Staff and Building Owners

Generally it is difficult to obtain as-built or design drawings for most of the public buildings. For the private buildings also, the structural drawings are generally not prepared or are not available. Therefore, it is necessary to interact with the public buildings authorities and other staff for the public buildings and to the house owner for private buildings. It is also necessary to involve them in the process to get their buy-in on the outcome of the assessment and, more importantly, on the proposed mitigation actions, in case of public buildings. This approach will also help in sensitizing authorities and raising awareness of staff on the seismic safety issue. This is very important, as there is general lack of awareness and commitment on the issue. The approach with following considerations is, thus, suggested for effective evaluation, which induces the development and implementation of doable mitigation actions.

- The assessment shall not solely rely on secondary information and shall involve primary data collection and confirmation of available information with the active participation of the authority and owners. The authority shall also be involved in the process of identification of mitigation options.
- The assessment work shall be taken as an awareness raising and educative tool to promote overall earthquake safety of buildings as well as collective safety of personnel.

3. QUALITATIVE STRUCTURAL ASSESSMENT

3.1 Introduction

This chapter describes the preliminary evaluation process in general terms. Seismic Evaluation of an existing building shall be conducted in accordance with the process outlined in Sections 3.2 and 3.3. This evaluation process is performed to determine whether the building, in its existing condition, has the desired seismic performance capability. A method basically involves review of available drawings and visual evaluation of the building for potential damage it could suffer in the event of an earthquake. It checks the code compliance for seismic design and detailing. The process is basically a qualitative measure to identify the areas of seismic deficiencies in a building before a detailed evaluation. This will help in deciding the retrofitting requirements for the building.

3.2 Assessment of the Building

Qualitative structural assessment of the building shall be done based on review of all available documents and drawings pertaining to the design and construction, design details and visual observation during site visit. If no documents are available, an as-built set of drawing shall be prepared indicating the existing lateral force resisting system. If the records are not available, an attempt can be made to obtain some information based on interviews with those who were involved in the design and construction of the building or familiar with the contemporary methods of construction, and the owners/residents. Different seismic vulnerability factors are checked and expected and performance of the building is estimated for different earthquake intensities. Different steps of the assessment process and their outcomes are described in this section.

3.2.1 Identification of Seismicity of the Region

The region of seismicity of the building shall be identified. This is done locating the building in seismic hazard map of the region in which the building stands. The zone map of Nepal is provided in Nepal National Building Code NBC 105: 1994.

3.2.2 Establish Seismic Target Performance Level

Desired performance level of protection is established prior to conducting seismic evaluation and strengthening. These are classified as:

- Operational
- Immediate occupancy
- Life safety
- Collapse Prevention

A wide range of structural performance level could be desired by individual building owners. The basic objective should be to increase Life Safety Performance Level - reducing the risk of life loss in the largest expected earthquake. Buildings meeting the Life Safety performance level are expected to experience little damage from relatively frequent, moderate earthquakes. But significantly more damage and potential economic loss from the most severe and infrequent earthquakes could affect them. Only the buildings classified as essential facilities (such as hospitals or other medical facilities, fire or rescue and police stations, communication centers, emergency preparedness centers etc.) should be evaluated for Immediate Occupancy Performance Level.

3.2.3 Obtain As-Built Information

Available as-built information for the building shall be obtained and site visit shall be conducted. Information of the building such as age of building, use, soil type and geological condition, structural system, architectural and structural characteristic, presence of earthquake resistant elements and other relevant construction data are to be collected from the archives. Standard checklists shall be prepared for this purpose.

If architectural and structural drawings are not available, evaluation may become difficult as the building structure is usually concealed by architectural finishes. Even if the drawings and structural details are available, it is necessary to verify conformance to the details at site. The structural design engineer, the contractor and the house owner should be consulted, if possible. Building information can be obtained by any of the following processes.

Site visit: A site visit shall be conducted by the evaluating design professional to verify existing data or collect additional data, determine the general condition of the building and verify or assess the site condition.

Interview: Interviews should be conducted with knowledgeable people residing in or nearby the buildings, with those who were involved in the design and construction of the building or with older engineers who have knowledge of contemporary methods of construction in the community or region to understand the building history, used construction materials, construction technologies, and alterations in the buildings as well as general aspects of the building.

Material exploration: For a proper evaluation, the actual condition of the building is to be assessed. The lateral force resisting system should be established. This can be done by implementing non-destructive test such as the use of bar scanner, test hammers and Ultrasonic testing instruments or by destructive tests as drilling in walls, scrapping of plasters and making inspection holes, if necessary, to determine the structural system and the expected strength of structural elements.

3.2.4 Building Typology Identification

The building being evaluated is identified by type of structural system listed in tabular form below. This is based on the lateral force resisting system and the type of diaphragm. A building with more than one type of lateral-force-resisting system shall be classified as a mixed system. A fundamental to this analysis is the grouping of buildings into sets that have similar behavioral characteristic.

Table 1: Common Building Types in Nepal

| No. | Building Types in Kathmandu Valley | Description |
|-----|---|--|
| 1 | Adobe, stone in mud, brick-in-mud (Low Strength Masonry). | <p><i>Adobe Buildings:</i> These are buildings constructed in sun-dried bricks (earthen) with mud mortar for the construction of structural walls. The wall thickness is usually more than 350 mm.</p> <p><i>Stone in Mud:</i> These are stone-masonry buildings constructed using dressed or undressed stones with mud mortar. These types of buildings have generally flexible floors and roof.</p> <p><i>Brick in Mud:</i> These are the brick masonry buildings with fired bricks in mud mortar</p> |
| 2 | Brick in Cement, Stone in Cement | These are the brick masonry buildings with fired bricks in cement or lime mortar and stone-masonry buildings using dressed or undressed stones with cement mortar. |
| 3 | Non-engineered Reinforced Concrete Moment-Resisting-Frame Buildings | <p>These are the buildings with reinforced concrete frames and unreinforced brick masonry infill in cement mortar. The thickness of infill walls is 230mm (9") or 115mm (4 1/2") and column size is predominantly 9"x 9". The prevalent practice in most urban area of Nepal for the construction of residential and commercial complexes generally falls under this category.</p> <p>These Buildings are not structurally designed and supervised by engineers during construction. This category also includes the</p> |

| | | |
|---|---|---|
| | | buildings that have architectural drawings prepared by engineers. |
| 4 | Engineered Reinforced Concrete Moment-Resisting-Frame Buildings | These buildings consist of a frame assembly of cast-in-situ concrete beams and columns. Floor and roof framings consist of cast-in-situ concrete slabs. Lateral forces are resisted by concrete moment frames that develop their stiffness through monolithic beam-column connections. These are engineered buildings with structural design and construction supervision is made by engineers. Some of the newly constructed reinforced concrete buildings are of this type. |
| 5 | Others | Wooden buildings, Mixed buildings like Stone and Adobe, Stone and Brick in Mud, Brick in Mud and Brick in cement etc. are other building type in Kathmandu valley and other part of the country. |

Detailed description of building type is given in **Annex I**

3.2.5 Determining Fragility of the Identified Building Typology

The probable damage to the building structures, that are available in Nepal and the region, at different intensities are derived based on “*The Development of Alternative Building Materials and Technologies for Nepal, Appendix-C: Vulnerability Assessment, UNDP/UNCHS 1994*” and “*European Macro-seismic Scale (EMS 98)*” http://www.gfz-potsdam.de/pb5/pb53/projekt/ems/core/emsa_cor.htm is given in Table 2. Detail description of damage grade is shown in **Annex IV**.

Table 2 (a) Building Fragility: Adobe+ Field Stone Masonry Building

| Shaking Intensity (MMI) | | VI | VII | VIII | IX |
|---|---------|------|-------|-------|-----|
| PGA (%g) | | 5-10 | 10-20 | 20-35 | >35 |
| Damage Grade for different classes of buildings | Weak | DG4 | DG5 | DG5 | DG5 |
| | Average | DG3 | DG4 | DG5 | DG5 |
| | Good | DG2 | DG3 | DG4 | DG4 |

Table 2 (b) Building Fragility: Brick in Mud (General) Building

| Shaking Intensity (MMI) | | VI | VII | VIII | IX |
|---|---------|------|-------|-------|-----|
| PGA (%g) | | 5-10 | 10-20 | 20-35 | >35 |
| Damage Grade for different classes of buildings | Weak | DG3 | DG4 | DG5 | DG5 |
| | Average | DG2 | DG3 | DG4 | DG5 |
| | Good | DG1 | DG2 | DG3 | DG4 |

Table 2 (c) Building Fragility: Brick in Mud (Well Built) + Brick in Cement (Ordinary)

| Shaking Intensity (MMI) | | VI | VII | VIII | IX |
|---|---------|------|-------|-------|-----|
| PGA (%g) | | 5-10 | 10-20 | 20-35 | >35 |
| Damage Grade for different classes of buildings | Weak | DG2 | DG3 | DG4 | DG5 |
| | Average | DG1 | DG2 | DG3 | DG4 |
| | Good | - | DG1 | DG2 | DG3 |

Table 2 (d) Non-Engineered Reinforced Concrete Frame Buildings (≥ 4 storey)

| Shaking Intensity (MMI) | | VI | VII | VIII | IX |
|---|---------|------|-------|-------|-----|
| PGA (%g) | | 5-10 | 10-20 | 20-35 | >35 |
| Damage Grade for different classes of buildings | Weak | DG1 | DG2 | DG4 | DG5 |
| | Average | - | DG1 | DG3 | DG4 |
| | Good | - | DG1 | DG2 | DG3 |

Table 2 (e) Non-Engineered Reinforced Concrete Frame Buildings (≤ 3 storey) + Engineered Reinforced Concrete Buildings + Reinforced Masonry Buildings

| Shaking Intensity (MMI) | | VI | VII | VIII | IX |
|---|---------|------|-------|-------|-----|
| PGA (%g) | | 5-10 | 10-20 | 20-35 | >35 |
| Damage Grade for different classes of buildings | Weak | DG1 | DG2 | DG3 | DG4 |
| | Average | - | DG1 | DG2 | DG3 |
| | Good | - | - | DG1 | DG2 |

3.2.6 Identification of Vulnerability Factors

Different Vulnerability factors associated with the particular type of building are checked with a set of appropriate checklists from FEMA 310, "Handbook for the Seismic Evaluation of Buildings" and "IS Guidelines for Seismic Evaluation and Strengthening of Existing Buildings". Separate checklist is used for each of the common building types. The design professional shall select and complete the appropriate checklist in accordance with **Annex III**. The general purpose of the checklist is to identify potential links in structures that have been observed in past significant earthquakes.

The basic vulnerability factors related to Building system, Lateral force resisting system, Connections and Diaphragms are evaluated based on visual inspection and review of drawings. A list of deficiencies identified by evaluation statements for which the building is found to be compliant and non-compliant shall be compiled upon completion of the checklist. If non-compliant, further investigation is required.

The evaluation statements are based on observed earthquake structural damage during actual earthquakes. Based on past performance of these types of buildings in earthquakes, the behavior of the structure must be examined and understood. However, the checklists will provide insight and information about the structure prior to quantitative evaluation. By quickly identifying the potential deficiencies in the structure, the design professional has a better idea of what to examine and analyze in quantitative evaluation.

Analysis performed as part of this evaluation is limited to quick checks. The evaluation involves a set of initial calculations and identifies areas of potential weaknesses in the building. The checks to be investigated are classified into two groups: *configuration related* and *strength related*. The preliminary evaluation also checks the compliance with the provisions of the seismic design and detailing codes. Quick checks shall be performed in accordance with evaluation statement to verify compliance or non-compliance situation of the statement. Seismic shear force for use in the quick checks shall be computed as per National building seismic code of the region.

The factors that pose less vulnerability to the building during earthquake shaking are listed below:

- Building should be regular in plan, elevation and structural system
- Building should have sufficient redundancy

- Demand Capacity Ratio (DCR) of each structural elements as well as the whole structure should be less than 1
- The building shall contain one complete load path
- Building shall have no damage and deterioration of structural elements and materials itself
- There shall be no hammering between adjacent buildings
- There shall be no diaphragm discontinuity
- Structural elements and the building shall not be slender
- There shall be proper connection between each structural elements and between structural and non-structural elements
- Building should have sufficient ductility
- Building should not be situated on liquefaction susceptible soil, steep and rock fall areas, fault rupture surfaces and soil filled areas
- Non-structural elements should be restrained properly

Reverse of the criteria as mentioned above pose vulnerability to the building.

3.2.7 Reinterpretation of the Building Fragility Based on Observed Vulnerability Factors

After thorough analysis and interpretation of vulnerability factors, the building is categorized into weak, average or good type of that particular building typology. This facilitates in assessing the probable performance of the building at different intensities of earthquake in terms of damage grades viz. negligible, slight, moderate, heavy and very heavy damage or destruction.

The status of damage of Reinforced Concrete and Masonry buildings are classified into five grades as given in **Annex IV**

3.3 Conclusions and Recommendation

The probable performance of the building at large expected earthquakes is identified based on the available information about the building, the architectural and structural information from field visit, and implementation of limited number of destructive and non-destructive field tests.

The evaluation helps in deciding whether the safety provided by the building is adequate. A decision is taken whether the building needs to be repaired, retrofitted or demolished based on the importance, target life, extent of deficiency of the building, the economic viability, the availability of the materials and technical resources and the expected life after retrofit. The stakeholders such as house owners, design engineers, occupants, municipality etc. are responsible in making the decision. The action can be either of the following.

- a) The safety of the building is adequate. The building needs some repair and regular maintenance, ensuring adequate performance during a future earthquake.
- b) The safety of the building is inadequate and hence, retrofit is necessary. The proposed retrofit scheme should be technically feasible and economically viable (Usually retrofitting is considered suitable if the cost of retrofitting is within 30% of the cost of new construction).
- c) The safety of the building is inadequate and the building is in imminent danger of collapse in the event of an earthquake. The retrofit scheme is not economically viable or feasible. Unless the building has historical importance and is of traditional nature, it is recommended to demolish and reconstruct the building rather than retrofitting for better seismic performance.

The seismic life safety provided by a building is judged adequate if the requirements are met and many authorities accept this level of performance for their community. Any non-structural elements that pose life threatening risk to the occupants may either be removed or restrained.

4. QUANTITATIVE ASSESSMENT

4.1 Introduction

This Chapter describes the second phase study of seismic vulnerability assessment which is a quantitative approach and follows qualitative analysis. Before embarking on seismic retrofitting, seismic deficiencies shall have to be identified through a seismic evaluation process using a methodology described in Chapter 3. The first phase assessment is general seismic vulnerability assessment method based on qualitative approach to identify the seismic deficiencies in the building. If the first phase study finds seismic deficiencies in the building and possible seismic performance is not up to the acceptable level/criteria, it recommends either second phase assessment or concludes the evaluation and state that potential deficiencies are identified. The second phase assessment involves a more detailed seismic evaluation with complete analysis of the building for seismic strengthening measures as modifications to correct/reduce seismic deficiencies identified during the evaluation procedure in first phase. Detail information about the building is required for this step of evaluation. Seismic retrofit becomes necessary if the building does not meet minimum requirements of the current Building Code, and may suffer severe damage or even collapse during a seismic event.

The most important issue when beginning to evaluate the seismic capabilities of an existing building is the availability and reliability of structural drawings. Detailed evaluation is impossible without framing and foundation plans, layout of preliminary lateral force elements, reinforcing for concrete structures, and connection detailing. This chapter assumes that sufficient information is available to perform a seismic evaluation that will identify all significant deficiencies.

Quantitative assessment of an existing building shall be conducted in accordance with the process outlined in these sections 4.1 through 4.10.

4.2 Review Initial Considerations

The design professional shall review initial considerations which include structural characteristic of the building, seismic hazard including geological site hazards, results of prior seismic evaluations, areas of structural deficiencies, building use and occupancy requirements, historical status, economic considerations, societal issues, and local jurisdictional requirements. This step of evaluation should focus on the potential deficiencies identified in Section 3.

Seismic hazards other than ground shaking may also exist at the building site. The risk and possible extent of damage from such geologic site hazards should be considered before undertaking a seismic strengthening measure. In some cases it may be feasible to mitigate the site hazard or strengthen the building and still meet the performance level. In other cases, the risk due to site hazard may be so extreme and difficult to control that, seismic strengthening is neither cost-effective nor feasible.

4.3 Decide Performance Objective

The performance objective needs to be defined before analyzing the building for retrofit. The performance objective depends on various factors such as the use of building, cost and feasibility of any strengthening project, benefit to be obtained in terms of improved safety, reduction in property damage, interruption of use in the event of future earthquakes and the limiting damage states. The minimum objective is Life Safety i.e. any part of the building should not collapse threatening safety of occupants during a severe earthquake.

4.4 Design Basis Earthquake

Seismic hazard due to ground shaking shall be based on the location of the building with respect to causative faults, the regional and site-specific geologic characteristics, and a selected earthquake hazard level. Seismic hazard due to ground shaking shall be defined as acceleration response spectra or acceleration time histories on either a probabilistic or deterministic basis. Seismic strengthening of buildings shall comply with the design criteria and procedures as specified in national building codes and standards of earthquake engineering.

A building must have been designed and constructed or evaluated in accordance with the current seismicity of the region

4.5 Detailed Investigation

This includes the following steps:

- a) Obtaining the attributes of the structural materials used in the building.
- b) Determining the type and disposition of reinforcement in structural members.
- c) Locating deteriorated material and other defects, and identifying their causes.

For evaluation of member capacities, precise values of the material strength and the dimensions are desirable. For this, non-destructive and intrusive techniques are employed for determining the strength of the material.

4.5.1 Non-Destructive Tests

The following are the most common types of tests that are used for seismic evaluation of the building.

4.5.1.1 Sounding Test

Description

Tapping on a wall with a dense object, such as a hammer, and listening to the vibrations emitted from the wall can be useful for identifying voids or *delaminations* in concrete and masonry walls. The sound produced from a solid wall will be different from that from a wall with voids or *delaminations* close to the surface. In concrete block masonry walls, sounding can be used to verify that the cells in the blocks have been grouted.

Equipment

The typical equipment required for sounding is a hammer. However, any hard, dense object can be used.

Conducting Test

In areas where the visual observations indicate that the wall may have *delaminations*, the wall can be sounded by tapping with a hammer. *Delaminations* and spalls will generally produce a hollow sound when compared with solid material. The wall should be tapped several times in the suspect area and away from the suspect area, and the sounds compared. It is important to test an area that is undamaged, and is of the same material and thickness to use as a baseline comparison. For a valid comparison, the force exerted by the tapping should be similar for both the suspect and baseline areas. In reinforced masonry construction, sounding can be used to assess whether the cells in the wall have been grouted. Near the ends of a block, the unit is solid for the full thickness of the wall. For most of the length of the block, it is relatively thin at the faces. If the sound near the end of the block is substantially different than at the middle of the cell, the cell is probably not grouted.

Personal Qualification

Sounding of concrete and masonry walls should be performed by an engineer or trained technician. Engineers and technicians should have previous experience in identifying damage to concrete and

masonry structures. Engineers and technicians should also be able to distinguish between sounds emitted from a hammer strike. Prior experience is necessary for proper interpretation of results.

Reporting Requirements

The personnel conducting the tests should provide sketches of the wall indicating the location of the tests and the findings. The sketch should include the following information:

- Mark the location of the test on either a floor plan or wall elevation.
- Report the results of the test, indicating the extent of *delamination*.
- Report the date of the test.
- List the responsible engineer overseeing the test and the name of the company conducting the test.

Limitations

The properties of the wall can influence the usefulness of sounding. The geometry of the wall and the thickness of the wall will affect the results. Sounding is best used away from the perimeter of the wall and on a wall of uniform thickness. The accuracy of information from sounding with a hammer also depends on the skill of the engineer or technician performing the test and on the depth of damage within the thickness of the wall. *Delaminations* up to the depth of the cover for the reinforcing bars (usually about 1 to 2 inches) can usually be detected. Detection of deeper spalls or *delamination* requires the use of other NDE techniques. Sounding cannot determine the depth of the spall or *delamination*.

Tapping on a loose section of material can cause the piece to become dislodged and fall. Avoid sounding overhead. A ladder, scaffold, or other lift device should be used to reach higher elevations of a wall.

4.5.1.2 Rebound Hammer Test

Description

A rebound hammer provides a method for assessing the in-situ compressive strength of concrete. In this test, a calibrated hammer impact is applied to the surface of the concrete. The amount of rebound of the hammer is measured and correlated with the manufacturer's data to estimate the strength of the concrete. The method has also been used to evaluate the strength of masonry.

Equipment

A calibrated rebound hammer is a single piece of equipment that is hand operated

Execution

The person operating the equipment places the impact plunger of the hammer against the concrete and then presses the hammer until the hammer releases. The operator then records the value on the scale of the hammer. Typically three or more tests are conducted at a location. If the values from the tests are consistent, record the average value. If the values vary significantly, additional readings should be taken until a consistent pattern of results is obtained.

Since the test is relatively rapid, a number of test locations can be chosen for each wall. The values from the tests are converted into compressive strength using tables prepared by the manufacturer of the rebound hammer.



Fig 1. (a) Use of Rebound Hammer



Fig 1. (b) Rebound Hammer

Personal Qualification

A technician with minimal training can operate the rebound hammer. An engineer experienced with rebound hammer data should be available to supervise and verify that any anomalous values can be explained.

Reporting Requirements

The personnel conducting the tests should provide sketches of the wall, indicating the location of the tests and the findings. The sketch should include the following information:

- Mark the location of the test marked on either a floor plan or wall elevation.
- Record the number of tests conducted at a given location.
- Report either the average of actual readings or the average values converted into compressive strength along with the method used to convert the values into compressive strength.
- Report the type of rebound hammer used along with the date of last calibration.
- Record the date of the test.
- List the responsible engineer overseeing the test and the name of the company conducting the test.

Limitations

The rebound hammer does not give a precise value of compressive strength, but rather an estimate of strength that can be used for comparison. Frequent calibration of the unit is required (ACI, 1994). Although manufacturers' tables can be used to estimate the concrete strength, better estimates can be obtained by removing core samples at selected locations where the rebound testing has been performed. The core samples are then subjected to compression tests. The rebound values from other areas can be compared with the rebound values that correspond to the measured core compressive strength.

The results of the rebound hammer tests are sensitive to the quality of the concrete on the outer several inches of the wall. More reproducible results can be obtained from formed surfaces rather than from finished surfaces. Surface moisture and roughness can also affect the readings. The impact from the rebound hammer can produce a slight dimple in the surface of the wall. Do not take more than one reading at the same spot, since the first impact can affect the surface, and thus affect the results of a subsequent test.

When using the rebound hammer on masonry, the hammer should be placed at the centre of the masonry unit. The values of the tests on masonry reflect the strength of the masonry unit and the mortar. This method is only useful in assessing the strength of the outer wythe of a multi-wythe wall.

4.5.1.3 Rebar Detection Test

Description

Cover-meter is the general term for a rebar detector used to determine the location and size of reinforcing steel in a concrete or masonry wall. The basic principle of most rebar detectors is the interaction between the reinforcing bar and a low frequency magnetic field. If used properly, many types of rebar detectors can also identify the amount of cover for the bar and/or the size of the bar. Rebar detection is useful for verifying the construction of the wall, if drawings are available, and in preparing as-built data if no previous construction information is available.

Equipment

Several types and brands of rebar detectors are commercially available. The two general classes are those based on the principle of magnetic reluctance and those based on the principle of eddy. The various models can have a variety of features including analogue or digital readout, audible signal, one handed operation, and readings for reinforcing bars and *prestressing* tendons. Some models can store the data on floppy disks to be imported into computer programs for plotting results.

Conducting Test

The unit is held away from metallic objects and calibrated to zero reading. After calibration, the unit is placed against the surface of the wall. The orientation of the probe should be in the direction of the rebar that is being detected. The probe is slid slowly along the wall, perpendicular to the orientation of the probe, until an audible or visual spike in the readout is encountered.

The probe is passed back and forth over the region of the spike to find the location of the maximum reading, which should correspond to the location of the rebar. This location is then marked on the wall. The procedure is repeated for the perpendicular direction of reinforcing.

If size of the bar is known, the cover-meter readout can be used to determine the depth of the reinforcing bar. If the depth of the bar is known, the readout can be used to determine the size of the bar. If neither quantity is known, most rebar detectors can be used to determine both the size and the depth using a spacer technique.

The process involves recording the peak reading at a bar and then introducing a spacer of known thickness between the probe and the surface of the wall. A second reading is then taken. The two readings are compared to estimate the bar size and depth. Intrusive testing can be used to help interpret the data from the detector readings. Selective removal of portions of the wall can be performed to expose the reinforcing bars. The rebar detector can be used adjacent to the area of removal to verify the accuracy of the readings.



Fig 2. (a) Use of Rebar Detector for Verification of Reinforcement Details



Fig 2. (b) Ferro-scan Detector

Personnel Qualifications

The personnel operating the equipment should be trained and experienced with the use of the particular model of cover-meter being used and should understand the limitations of the unit.

Reporting Requirements

The personnel conducting the tests should provide a sketch of the wall indicating the location of the testing and the findings. The sketch should include the following information:

- Mark the locations of the test on either a floor plan or wall elevation.
- Report the results of the test, including bar size and spacing and whether the size was verified.
- List the type of rebar detector used.
- Report the date of the test.
- List the responsible engineer overseeing the test and the name of the company conducting the test.

Limitations

Pulse-velocity measurements require access to both sides of the wall. The wall surfaces need to be relatively smooth. Rough areas can be ground smooth to improve the acoustic coupling. *Couplant* must be used to fill the air space between the transducer and the surface of the wall. If air voids exist between the transducer and the surface, the travel time of the pulse will increase, causing incorrect readings.

Some *couplant* materials can stain the wall surface. Non-staining gels are available, but should be checked in an inconspicuous area to verify that it will not disturb the appearance.

Embedded reinforcing bars, oriented in the direction of travel of the pulse, can affect the results, since the ultrasonic pulses travel through steel at a faster rate that will significantly affect the results. The moisture content of the concrete also has a slight effect (up to about 2 percent) on the pulse velocity.

Pulse-velocity measurements can detect the presence of voids or discontinuities within a wall; however, these measurements cannot determine the depth of the voids.

4.5.1.4 In-Situ Testing In-Place Shear

Description

The shear strength of unreinforced masonry construction depends largely on the strength of the mortar used in the wall. An in-place shear test is the preferred method for determining the strength of existing mortar. The results of these tests are used to determine the shear strength of the wall.

Equipment

- Chisels and grinders are needed to remove the bricks and mortar adjacent to the test area.
- A hydraulic ram, calibrated and capable of displaying the applied load.
- A dial gauge, calibrated to 0.001 inch.

Execution

Prepare the test location by removing the brick, including the mortar, on one side of the brick to be tested. The head joint on the opposite side of the brick to be tested is also removed. Care must be exercised so that the mortar joint above or below the brick to be tested is not damaged.

The hydraulic ram is inserted in the space where the brick was removed. A steel loading block is placed between the ram and the brick to be tested so that the ram will distribute its load over the end face of the brick. The dial gauge can also be inserted in the space.

The brick is then loaded with the ram until the first indication of cracking or movement of the brick. The ram force and associated deflection on the dial gauge are recorded to develop a force-deflection

plot on which the first cracking or movement should be indicated. A dial gauge can be used to calculate a rough estimate of shear stiffness.

Inspect the collar joint and estimate the percentage of the collar joint that was effective in resisting the force from the ram. The brick that was removed should then be replaced and the joints re-pointed.




Fig 3. Test Set up for In-Situ Shear Test

Personnel Qualifications

The technician conducting this test should have previous experience with the technique and should be familiar with the operation of the equipment. Having a second technician at the site is useful for recording the data and watching for the first indication of cracking or movement. The structural engineer or designer should choose test locations that provide a representative sampling of conditions.

Reporting Results

The personnel conducting the tests should provide a written report of the findings to the evaluating engineer. The results for the in-place shear tests should contain, at a minimum, the following information for each test location:

- Describe test location or give the identification number provided by the engineer.
- Specify the length and width of the brick that was tested, and its cross-sectional area.
- Give the maximum mortar strength value measured during the test, in terms of force and stress.
- Estimate the effective area of the bond between the brick and the grout at the collar joint.
- Record the deflection of the brick at the point of peak applied force.
- Record the date of the test.
- List the responsible engineer overseeing the test and the name of the company conducting the test.

Limitations

This test procedure is only capable of measuring the shear strength of the mortar in the outer *wythe* of a multi-*wythe* wall. The engineer should verify that the exterior *wythe* being tested is a part of the structural wall, by checking for the presence of header courses. This test should not be conducted on veneer *wythes*.

Test values from exterior *wythes* may produce lower values when compared with tests conducted on inner *wythes*. The difference can be due to weathering of the mortar on the exterior *wythes*. The exterior brick may also have a reduced depth of mortar for aesthetic purposes.

The test results can only be qualitatively adjusted to account for the presence of mortar in the collar joints. If mortar is present in the collar joint, the engineer or technician conducting the test is not able to discern how much of that mortar actually resisted the force from the ram.

The personnel conducting the tests must carefully watch the brick during the test to accurately determine the ram force at which first cracking or movement occurs. First cracking or movement indicates the maximum force, and thus the maximum shear strength. If this peak is missed, the values obtained will be based only on the sliding friction contribution of the mortar, which will be less than the bond strength contribution.

4.6 Seismic Analysis and Design

The detail seismic evaluation refers to the structural analysis of the building. Structural analysis is a part of the detailed evaluation of an existing building. The method of analysis is to be finalized at this stage based on building data. The evaluation procedure includes an analysis using the methods of Linear/Non Linear Static procedure or Linear/Non Linear Dynamic procedure or special procedure for unreinforced masonry bearing wall buildings with flexible diaphragm being evaluated to the life safety Performance Level. The steps include developing a computational model of the building, applying the external forces, calculating the internal forces in the members of the building, calculating the deformations of the members and building, and finally interpreting the results. The structural analysis is performed using a suitable computer analysis program. The relevant seismic code is referred for lateral load calculation. The model is analyzed for the individual load cases after the computational model is developed and the loads are assigned.

4.7 Intervention Options for Better Seismic Performance

4.7.1 General

Retrofit strategy refers to any option of increasing the strength, stiffness and ductility of the members or of the whole building. The possible intervention options need to be selected based on the building typology and the expected performance of the building after retrofitting. Following considerations ought to be additionally made while selecting probable intervention options:

- (i). Requirements to comply to the Building Code for design, materials and construction
- (ii). Compatibility of the solution with the functional requirements of the structure
- (iii). Possible cost implication
- (iv). Indirect cost of retrofitting such as relocation cost
- (v). Availability of construction technique (materials, equipments and workmanship) in construction industry
- (vi). Enhancement of the safety of the building after intervention of the selected option
- (vii). Aesthetic view of the building

Once these considerations are made, different options of modifying the building to reduce the risk of damage should be studied. The corrective measures include stiffening or strengthening the structure, adding local elements to eliminate irregularities or tie the structure together, reducing the demand on the structure through the use of seismic isolation or energy dissipation devices, and reducing the height or mass of the structure.

4.7.2 Retrofitting Methods

4.7.2.1 General Improvement

Plan Shape

If the building is found irregular and unsymmetrical in plan shape, the plan shape of the building can be improved from earthquake point of view by separating wings and dividing into more regular, uniform and symmetrical shapes.

Elevation Improvement

Buildings may have unbalanced stiffness in plan and elevation. In many buildings, the rooms are added horizontally when and where required without seismic consideration. It makes one part of same house one storey while the rest is two-storied. Separating the two parts or demolition /addition part of the building eliminating upper storey set back from base can solve this problem.

Load Path

Buildings may suffer from the problem of discontinuous load path. It needs more intelligent solutions, re-planning of space to create new and more direct load paths. A complete load path is a basic requirement for all buildings. If there is discontinuity in load path, the building is unable to resist seismic forces regardless of the strength of the existing elements.

Inserting New Walls

To improve effectiveness of existing walls to mitigate *torsional* problem due to non-symmetry in walls in plan, and to improve shear resistance of the buildings, or to provide return walls to existing walls, new walls are added at appropriate locations. It may require closing of some existing openings. Exact location of these walls is determined during detailed study.

Modification of Roofs or Floors

Heavy and brittle roof tiles that can easily dislodge should be replaced with light and corrugated iron and asbestos sheeting. Undesired heavy floor mass, that only induce increased seismic force, need to be removed. False ceiling and heavy ceiling plasters that create a condition of potential hazard of falling during a shaking should either be anchored properly or replaced with light material. Roof truss should be braced by welding or clamping suitable diagonal bracing members in vertical as well as in horizontal planes. Anchors of roof trusses to supporting walls should be improved and the roof thrust on walls should be eliminated.

Strengthening the Arches

Jack arch roofs are common in old masonry buildings for spanning larger distance between walls.

To prevent spreading of arches, it is proposed to install tie rods across them at spring levels or slightly above it by drilling holes on both sides and grouting steel rods in them (Figure 4.a below). However, where it is not possible a lintel consisting of steel channels or I-section, could be inserted just above the arch to take the load and relieve the arch as shown in Figure 4.b.




Fig 4. Strengthening of Arches (IAEE, 1984)

(b)

Reduction in Building Mass

A reduction in mass of the building results in reduction in lateral forces. This can be achieved by removing unaccountable upper stories, replacing heavy cladding, floor and ceiling, removing heavy storage or change in occupancy use.

4.7.3 Seismic Retrofitting Strategies of Masonry Buildings

4.7.3.1 Major Weaknesses Revealed During Earthquakes in Similar Building Typology

The following are the major types of problems and basic damage patterns observed during earthquakes in this type of buildings:

- *Torsional* effect to the building due to Irregular shape of the building
- Non-integrity of wall, floor and roof structures and their components
- Out-of-plane collapse due to lack of anchoring elements on upper parts of the wall of the flexible roof buildings
- Separate orthogonal walls at junctions due to developing cracks
- Collapse of gable wall since it behaves as a free cantilever
- Reduce wall stiffness or storey stiffness due to large opening
- Out-of plane failure of walls due to lack of cross walls
- Collapse of the building due to rapid cracking and disintegrating of various parts due to brittle nature

4.7.3.2 Common Retrofitting Methods for the Masonry Buildings

The concept of retrofitting masonry buildings start from enhancing integrity to the structure by providing proper connections between its resisting elements in such a way that inertia forces generated by the vibration of the building can be transmitted to the members that have ability to resist. Typical important aspects are the connection a) between components of floors and roof; b) between roof or floors and walls; c) between intersecting walls; and d) walls and foundation.

Commonly used improvements methods include eliminating features that are: a) source of weakness or that produce concentrations of stresses in some members, b) abrupt change of stiffness from floor to floor, c) concentration of large masses, and d) large openings in walls without proper peripheral reinforcement. Increasing the lateral strength in one or both directions, by reinforcing or by increasing wall plan areas or the number of walls may be required in some cases.

Avoiding the possibility of brittle mode of failure by providing proper reinforcement and connection of load resisting members is the overall objective in seismic strengthening.

Selected retrofitting options for the masonry buildings, considering the basic principles of retrofitting mentioned above, are described below. These methods are being implemented worldwide and are considered economically and technically viable though other expensive methods are also available.

Jacketing

This method is adopted on buildings constructed with a material that is heavy in weight, weak in strength, and brittle. It helps to basket the wall, hence improve its shear strength and ductility. This method also improves integrity and deformability. Main improvements in different structural elements of the building by this method are as follows:

Walls: To improve strength, deformability and to reduce risk of disintegration, *delamination* of walls resulting in total collapse of the building, thin reinforcement concrete jacketing of all the walls is done. In this alternative, two steel meshes should be placed on either two sides or one side of the wall and both the meshes should be connected by some steel bar connectors passing through the wall. The thickness of the added concrete should be about 40 to 50 mm thick. The concrete used ought to be a micro-concrete i.e. concrete with small aggregates. Selection of one-side jacketing or two-side jacketing depends on the analysis result.

Floors: If the floor is flexible, bracing of the floor elements with steel or timber sections and tying up the floor elements with walls should be done to improve stiffness of the floor system and to obtain integrity between walls and floor.

Roof: If the roof is flexible, similar to floor, bracing of the roof elements with steel or timber sections and tying up the roof elements with walls should be done to improve stiffness of the roof system and to obtain integrity between walls and roof.

False Ceiling: Ceiling may need replacement with a light ceiling system and better anchorage system.




Fig 5.(a) General Scheme of Jacketing



Fig 5. (b) Erection of Reinforcement for Wall Jacketing



Fig 5. (c) Wall Jacketing in Process

Process of Wall Jacketing

Splint and Bandage

The Splint and Bandage system is considered as an economic version of jacketing where reinforcing bars are provided at most critical locations (Figure 6), wherever stress concentrations can develop. Splints are vertical elements provided at corners, wall junctions and jambs of openings in the external faces of the building. The objective is to provide integrity in vertical direction.

The bandages are horizontal elements running around all the walls and building to integrate various walls together thereby preventing potential out of plane collapse of walls. In addition, openings are also surrounded by splints and bandages to prevent initiation and widening of cracks from their corners. Splints are provided in the external face only. The bandages could be provided on both the faces of the walls just at the lintel, eaves and sill level. This method is inferior to jacketing but better than bolting as discussed below in terms of safety enhancement. In splint and bandage system, the

strengthening and stiffening of the floor and roof is made in the same way as discussed above under Section 4.7.3.2 Jacketing.




Fig 6. Process of Retrofitting by Splint and Bandage Method

Bolting/ Pre-stressing

A horizontal compression state induced by horizontal tendons is used to improve the shear strength of in-plane walls. This also considerably improves the connections between orthogonal walls. The easiest way of affecting the pre-stressing is to place two steel rods on the two sides of the wall and strengthening them by turnbuckles (Figure 7). These are done at two levels of each storey viz. a) lintel level and b) just below the floor and roof structure. This method improves the earthquake resistance of the building and will delay the collapse, but it is still much inferior to the jacketing or split and bandage in terms of increasing safety. This method is cheaper and will be effective for small and simple buildings.




Figure 7: Retrofitting of Masonry Building by Pre-stressing

Confinement with Reinforced Concrete Elements

Confinement with reinforced concrete elements (beam and columns) make the existing masonry act as “confined masonry” in the sense that reinforced concrete elements are inserted surrounding the wall panel or middle of the long wall, allowing the entire wall, or its portion, to act as a truss element, where the struts are inclined strip of unreinforced masonry. In this way, brittle and non-ductile wall becomes more ductile and its load carrying capacity increased several times with added confinement of the reinforced concrete elements. It is more suitable for buildings of one to three storey heights with monolithic reinforced concrete slab and horizontal bands over the load bearing walls at the lintel level. However, implementation of this method of retrofitting is more complex and needs special improvements for foundation also.

Base Isolation

What effectively is done in this scheme is that the superstructure is strengthened nominally and is isolated from ground motion by introducing a flexible layer between the structure and the ground. The various types of base isolation devices are i) Laminated rubber bearing ii) Laminated rubber bearing with lead core iii) Sliding bearing and iv) Friction pendulum devices. Base isolation modifies the response characteristics so that the maximum earthquake forces on the building are much lower. The seismic isolation eliminates or significantly reduces not only the structural damage but also non-structural damage and enhances the safety of the building content and architectural components (Figure 8 below). This technique is usually employed for buildings with historic importance and critical facilities and is quite expensive as compared to other methods.




Fig 8. (a) Without Base Isolation (Masonry Building)




Fig 8. (b) With Base Isolation (Masonry Building)

Use of FRP (Fiber Reinforced Polymer)

Seismic resistance of masonry buildings improve significantly by using glass or carbon FRP strips on walls. Strengthening with FRP is a new approach. Both flexural and shear capacity of masonry walls can be enhanced by applying thin films of glass or carbon FRP to the exterior surface of the wall.

Main advantages of Fiber Reinforced Polymer (FRP) retrofitting are:

- Increases out-of-plane flexural strength
- Increases in-plane shear strength
- Increases stiffness at service loads
- Results in monolithic action of all units
- Strengthening of entire wall can be accomplished by treating only a fraction of wall surface area
- Adds very little weight to the wall
- Minimum changes in the member size after repair
- Limited access requirements
- Lower installation cost

- Improved corrosion resistant
- On-site flexibility of use

Even though the materials used in FRP are relatively expensive as compared to the traditional strengthening materials such as steel and concrete, the labor, equipment and construction costs are often lower. It is a promising technique since its application is more easy and rapid with minimum disturbance to the occupants. Application of FRP, with care, provides significant increase in lateral strength but it does not provide as much ductility as the RC wall would provide, because of the brittleness of the material. For effective use, a firm anchorage should be provided between FRP and the wall panel. The possible schemes of layout of FRP wraps are shown in the figure below.




Fig 9. Configurations of FRP Laminates of Masonry Walls

4.7.3.3 Comparison of Common Methods of Retrofitting for Masonry Building

Different options of possible retrofitting technique need to be compared for the building to be assessed considering its structural details and possible failure patterns. In general, the parameters that are considered are the effectiveness of retrofit system, its cost implication, importance of the building, economic and technical feasibility of the project.

Table 3: Comparison of Different Retrofitting Options

| | Retrofitting Options | | | | | |
|------------------------|----------------------------|---|---------------------------------|---|--|---|
| | Jacketing | Splint and Bandage | Bolting/ <i>Prestressing</i> | Confinement with reinforced concrete elements | Base Isolation | Strengthening with FRPs |
| Maximum Nos. of Storey | Suitable up to four storey | Suitable up to three storey, preferable | Suitable up to two storey | Suitable up to three storey | Suitable for low to medium rise buildings with time period | Suitable for low rise buildings up to 2 Stories |

| | | | | | | |
|------------------------------|----------------------------------|----------------|-----------------------------|-------------|---------------------|-------------|
| | | for two storey | | | up to 0.5sec | |
| Architectural Changes | Extensive | Moderate | Less | Significant | Insignificant | Less |
| Intervention time | Long | Moderate | Short | Long | Long | Less |
| Cost | High | Moderate | Low | High | Extensive | High |
| Safety achieved up to MMI IX | Life safety -Immediate Occupancy | Life safety | Brittle collapse prevention | Life safety | Immediate Occupancy | Life safety |

The study should consider the structural system of the building, its major structural problems, importance of the building and different available options of retrofitting to select appropriate retrofitting option. The above table compares different retrofitting options in various aspects. The suitable retrofitting option is adopted for a particular building.

4.7.4 Seismic Retrofitting Strategies of Reinforced Concrete Buildings

4.7.4.1 Major Weaknesses Revealed During Earthquakes in Similar Building Typology

The following are the major types of problems observed during earthquakes in this type of buildings:

- absence of ties in beam column joints
- inadequate confinement near beam column joint
- inadequate lap length and anchorage and splice at inappropriate position
- low concrete strength
- improperly anchored ties (90° hooks)
- inadequate lateral stiffness
- inadequate lateral strength
- irregularities in plan and elevation
- irregular distribution of loads and structural elements
- other most common structural deficiencies such as soft storey effect, short column effect, strong beam-weak column connections etc.

4.7.4.2 Common Retrofitting Methods for the Reinforced Concrete Buildings

Various methodologies are available for analysis and retrofitting of frame structures. Earthquake resistance in RC frame buildings can be enhanced either by:

- a) Increasing seismic capacity of the building

This is a conventional approach to seismic retrofitting which increase the lateral force resistance of the building structure by increasing stiffness, strength and ductility and reducing irregularities. This can be done by two ways

- 1) Strengthening of original structural members

These include strengthening of

- Columns (reinforced concrete jacketing, steel profile jacketing, steel encasement, fiber wrap overlays)
- Beams (reinforced concrete jacketing, steel plate reinforcement, fiber wrap overlays)
- Beam Column joint (reinforced concrete jacketing, steel plate reinforcement, fiber wrap overlays)
- shear wall (increase of wall thickness)
- Slab (increase of slab thickness, improving slab to wall connection)

- *Infilled* partition wall (reinforce *infilled* walls and anchor them into the surrounding concrete frame members).
- 2) Introduction of New structural elements

The lateral force capacity of an existing structure may be increased by adding new structural elements to resist part or all of the seismic forces of the structure, leaving the old structure to resist only that part of the seismic action for which it is judged to be reliable. Newly added structural elements may be

- shear walls in a frame or skeleton structure
- *infilled* walls (reinforced concrete or masonry located in the plane of existing columns and beams)
- wing walls (adding wall segments or wings on each side of an existing column)
- additional frames in a frame or skeleton structure
- trusses and diagonal bracing (steel or reinforced concrete) in a frame or skeleton structure

Establishing sound bond between the old and new concrete is of great importance. It can be provided by chipping away the concrete cover of the original member and roughening its surface, by preparing the surfaces with glues (for instances, with epoxy prior to concreting), by additional welding of bend reinforcement bars or by formation of reinforced concrete or steel dowels.

Perfect confinement by close, adequate and appropriately shaped stirrups and ties contributes to the improvement of the ductility of the strengthening members. Detailed consideration of the possibility of significant redistribution of the internal forces in the structures due to member stiffness changes is very important.

b) Reducing seismic response of the building

Increasing damping in the building by means of energy dissipation devices, reducing mass, or isolating the building from the ground enhance the seismic structural response. A more recent approach includes the use of base isolation and supplemental damping devices in the building. These emerging technologies can be used to retrofit existing RC frame structures; however their high cost and the sophisticated expertise required to design and implement such projects represent impediments for broader application at recent time.

Seismic strengthening measures identified for one RC frame building may not be relevant for another. It is therefore very important to develop retrofit solutions for each building on a case-by-case basis. Most of these retrofit techniques have evolved in viable upgrades. However, issues of costs, invasiveness, and practical implementation still remain the most challenging aspects of these solutions. In the past decade, an increased interest in the use of advanced non-metallic materials or Fiber Reinforced Polymers, FRP has been observed.

The following retrofit strategies for RC buildings are widely used after recent earthquakes in several places:

Reinforced Concrete Jacketing

This method involves addition of a layer of concrete, longitudinal bars and closely spaced ties on existing structural elements. The jacket increases both the flexural strength and shear strength of the column and beam. It helps to basket the member, hence improve its shear strength and ductility. This method also improves integrity and deformability. Main improvements in different structural elements of the building by this method are as follows:

Columns: The jacketing not only increases the flexural strength and shear strength of the column but also increases its ductility. The thickness of the jacket also gives additional stiffness to the concrete column. Since the thickness of the jacket is small, casting self compacting concrete or the use of short Crete are preferred to conventional concrete. During retrofitting, it is preferred to relieve the columns of the existing gravity loads as much as possible, by propping the supported beams.

Beams: Beams are retrofitted to increase their positive flexural strength, shear strength and the deformation capacity near the beam-column joints. The lack of adequate bottom bars and their anchorage at the joints needs to be addressed. Usually the negative flexural capacity is not enhanced since the retrofitting should not make the beams stronger than the supporting columns. The strengthening involves the placement of longitudinal bars and closely spaced stirrups.

Addition of Reinforced Concrete Shear Walls

Adding shear walls is one of the most popular and economical methods to achieve seismic protection. Their purpose is to give additional strength and stiffness to the building and could be added to existing and new buildings. They are positioned after careful planning and judgment by the structural engineer as to how they would affect the seismic forces in a particular building. However, it is desired to ensure an effective connection between the new and existing structure.



Fig 10. (a) Jacketing of RC Column



Fig 10. (b) Addition of Shear Wall and Column Jacketing

Steel Bracing

In this method diagonal braces are provided in the bays of the building. Diagonals stretch across the bay to form triangulated vertical frame and as triangles are able to handle stresses better than a rectangular frame the structure is also supposed to perform better. Braces can be configured as diagonals, X or even V shaped. Braces are of two types, concentric and eccentric. Concentric braces connect at the intersection of beams and columns whereas eccentric braces connect to the beam at some distance away from the beam-column intersection. Eccentric braces have the advantage that in case of buckling the buckled brace does not damage beam- column joint.



Fig. 11. Retrofitting by Diagonal Steel Bracing

Base Isolation

In this method superstructure is isolated from ground motion during earthquake shaking by using flexible layer between the structure and the ground as discussed in Section 4.7.3.2 Base Isolation. The only difference is that these isolators are introduced individually beneath column support (Fig 12), while as in masonry building a flexible layer is introduced throughout the wall stretch at base (Fig 8).




Fig 12. (a) Without Base Isolation (RC Frame Building)




Fig 12. (b) With Base Isolation (RC Frame Building)

Use of FRP (Fiber Reinforced Polymer)

Seismic resistance of frame buildings can be improved significantly by using Fiber Reinforced Polymer overlays on RC elements of the building. Strengthening with FRP is a new approach. FRP is light weight, high tensile strength material and has a major advantage of fast implementation. This method could be effectively used to increase strength and stiffness of RC frames. The effectiveness is strongly dependent on the extent of anchorage between the FRP strips and the frame.

4.7.4.3 Comparison of Common Methods of Retrofitting for Reinforced Concrete Building

Different options of possible retrofitting technique are compared for the assessment of the building considering its structural details and possible failure patterns. In general, the parameters that are considered are the effectiveness of retrofit system, its cost implication, importance of the building, economic and technical feasibility of the project etc.

Table 4: Comparative Chart of Different Retrofitting Options for RC Frame Buildings

| Retrofitting Options for RC frame building | | | | | |
|--|------------------------|---------------------|-------------|--|--|
| | Installing new RC wall | Jacketing | Bracing | Strengthening existing frame and masonry infill with CFRPs | Base Isolation |
| Architectural Changes | Moderate-significant | Moderate | Extensive | Less | Insignificant |
| Intervention time | Long | Long | Moderate | Less | Long |
| Cost | High | High | Moderate | High | Extensive |
| Increase of ductility | Significant | moderate | moderate | small | Not required as earthquake load is cut at foundation level |
| Safety achieved up to MMI IX | Minimum Life Safety | Minimum Life Safety | Life Safety | Life Safety | Immediate Occupancy |

The study should consider the structural system of the building, its major structural problems and different available options of retrofitting.

4.7.5 Foundation Intervention

An engineer should opt for a seismic strengthening measure with minimum work on the foundation. If foundation intervention is desired, the retrofit strategy becomes invariably expensive. In some cases, retrofitting may not be economically and practically viable at all. Foundation treatment usually requires excavation under difficult circumstances. In addition, there are difficulties in pinning or attaching the existing footings to the new elements. And construction is very difficult and expensive. This great cost will occur due to inaccessibility of the existing footings and the great uncertainty regarding the characteristics of the soil and existing footings. Numerous seismic rehabilitation projects have been canceled because of excessive cost.

Before undertaking any structural retrofitting measures and foundation work, an engineer should critically analyze the cost, benefit and feasibility of the project. There are many issues to be considered, these include:

- Foundation failures may result in severe economic loss resulting in damage to structural and non-structural elements. But, failure of foundation may have smaller effect on the Life-safety and collapse prevention limit as large foundation movements are needed to cause structural collapse.

- Seismic strengthening or upgrade of the foundation may result in transmission of larger seismic forces into the structure. Hence, foundation strengthening may increase the cost of structural upgrade since more structural work is required in response to foundation work. In some cases, foundation upgrade may adversely affect the life safety and collapse prevention limit states. The engineer must balance a range of economic, social and technical concerns, when evaluating these issues.
- However, in general the foundation work will reduce the probability of serious economic damage during an earthquake.

4.8 Cost Estimate

After thorough analysis and selection of suitable retrofitting option, if necessary, preliminary cost is estimated. This should include the cost for materials, labor, taxes, contractor's profit and indirect cost such as relocation etc. The tentative cost is calculated per unit area based on the current practice. Further, considering the uncertainty associated with the work, some additional 20% of the total cost needs to be added as unforeseen cost.

As the retrofitting work needs trained mason, wages should be taken from prevailing market rates for special finishing and quality and specially trained manpower. The rates not covered by Government norms should be based on best engineering judgment and past experience.

The decision to repair and strengthening a structure depends not only on technical considerations but also on a benefit cost analysis of the different possible alternatives. It is suggested that the cost of retrofitting of a structure should remain below 25% of the replacement as major justification of retrofitting (*Nateghi and Shahbazian, 1992*).

4.9 Comparison of Possible Performance of the Building after Retrofitting

The probable performance of the building under study is compared in terms of possible damage grades before and after retrofitting. This helps in identifying whether the acceptable level of seismic response in terms of Life safety as minimum requirement is achieved after implementation of retrofitting technique suggested for the building. This is very important as the client knows the level of safety to be attained and the benefit of retrofit scheme.

4.10 Conclusions and Recommendations

4.10.1 Conclusions

The principal objectives of this study are: (i) to identify weak links in the building based on observed behavior in similar buildings in past earthquakes and (ii) to develop possible intervention options to improve their seismic resistance with associated costs and level of incremental seismic safety. The conclusions arrived from the detail analysis are described as:

- Various retrofit options are compared and studied. Out of which, the most suitable retrofit technique is proposed for the particular building type keeping all factors, as mentioned in previous chapters, in consideration. The retrofit option should improve the building response with Life Safety as minimum requirement.
- The cost of retrofitting may differ to some extent if the actual structural strength and details are found different, than those assumed during retrofit design, once walls and roof are opened during field implementation.

4.10.2 Recommendations

To reduce the disastrous effects of earthquakes on buildings, function and life, the following recommendations are made:

- A time-bound program should be implemented to retrofit the building with incorporation of seismic resistant measures as selected.
- Retrofitting is an advanced process and requires a higher level of expertise than that required for design and construction of new buildings. The process requires lots of destructive interventions such as hammering, drilling in walls, and removal of some parts of building. Such activities may cause additional damage if proper attention is not given during implementation. Hence, use of experienced and skilled labor with proper supervision is emphasized.
- Retrofit design may need revision once structural, architectural and ornamental elements of the building are removed for implementation and details differ from those assumed at design stage. Hence, it is suggested to clarify from the contractor's side, before signing of the contract, about such issues and seek flexibility in design details that are required to be implemented at site.
- During retrofitting process, the elements such as floor cornices, *chajjas*, cladding, false ceiling, that add beauty to the building, need to be removed. Prior to implementation of retrofitting plans, designer's advice may be sought for retaining good aesthetic view of the building after retrofitting.
- Supervision during the retrofitting works is very essential as it is a delicate work. Hence, it is extremely important to have proper supervision at the site during retrofitting.

Due consideration is to be given for uniform distribution of furniture and fixtures, equipment and other non-structural elements so that the load distribution is even. The non-structural elements (partitions, furniture, equipment etc.) should be fixed properly for restricting their movement to prevent overturning, sliding and impacting during an earthquake. Masonry walls are recommended to be braced with reinforced concrete mesh or any other means to prevent non-structural damage during earthquakes of large intensity.

5. REFERENCES

1. Arya, A. S. et al; 1986, Guidelines for Earthquake Resistant Non-engineered Construction, International Association for Earthquake Engineering.
2. Applied Technology Council (ATC) 40: Volume 1 and 2: Seismic Evaluation and retrofit of concrete buildings.
3. Bothara, J. K., Pandey, B. H., Guragain, R., 2004, Retrofitting of Low Strength Masonry School Buildings, NZSEE,
4. Building Construction under Seismic conditions in Balkan Region, 1983, Repair and Strengthening of Reinforced Concrete, Stone, Brick-masonry Buildings, UNDP/UNIDO/RER 79/015, Vienna.
5. Central Public Works Department, Indian Building Congress in association with Indian Institute of Technology Madras, Handbook on “Seismic Retrofit of Buildings”, 2008
6. EMS, 1998, *European Macro-seismic Scale*, ONLINE,
http://www.gfz-potsdam.de/pb5/pb53/projekt/ems/core/ems_cor.htm
7. Federal Emergency Management Agency, (FEMA 273), NEHRP Guidelines For The Seismic Rehabilitation Of Buildings, Building Seismic Safety Council, Washington D. C., 1988.
8. Federal Emergency Management Agency, (FEMA 274), NEHRP Commentary On the Guidelines For The Seismic Rehabilitation Of Buildings, Building Seismic Safety Council, Washington D. C., 1988.
9. Federal Emergency Management Agency, (FEMA 356), Pre-standard and Commentary for the Seismic Rehabilitation of Buildings, Building Seismic Safety Council, Washington D. C., 2000.
10. Handbook on Seismic Retrofit of Buildings, Indian Buildings Congress, Indian Institute of Technology Madras.
11. IITK-GSDMA Guidelines for Seismic Evaluation and Strengthening of Existing Buildings
12. IS 1893:2002; Criteria for earthquake resistant design of structures, Bureau of Indian Standard.
13. JICA, 2002, *The Study on Earthquake Disaster Mitigation in the Kathmandu Valley*, Japan International Corporation Agency and Ministry of Home Affairs, GON.
14. NBC 105-1994, Seismic Design of Buildings in Nepal, Govt. of Nepal, Ministry of Housing and Physical Planning, Department of Buildings, Nepal, 1995.
15. NBC 203-1994, Guidelines for Earthquake Resistant Building Construction: Low Strength Masonry, Govt. of Nepal, Ministry of Housing and Physical Planning, Department of Buildings, Nepal, 1995.
16. New Zealand National Society for Earthquake Engineering, 1995, Guidelines for Assessing and Strengthening Earthquake Risk Building: Unreinforced Masonry (Draft Copy), New Zealand National Society for Earthquake Engineering.
17. R. Park and T Paulay, Reinforced Concrete Structures.

6. Annex I: Private and Public Buildings Typology

Type 1 - Adobe, Stone in Mud, Brick-in-Mud (Low Strength Masonry).

These buildings are constructed as mud-based buildings and are mostly found in rural areas. The vulnerability of these types of buildings mainly depends on the inherent structural strength of the wall material together with the technology of construction. Vertical wooden posts and horizontal wooden elements embedded in walls are the expected key earthquake resistant elements in these buildings. The type of floor and factors such as flat or sloping type, heavy or light weight, properly fixed with walls or simply rested, braced or un-braced etc. highly influence the vulnerability of such buildings.

Adobe Buildings: These are buildings constructed using sun-dried bricks (earthen) with mud mortar for the construction of the structural walls. The walls are usually more than 350 mm. thick.

Stone in Mud: These are stone-masonry buildings constructed using dressed or undressed stones with mud mortar. They generally have flexible floors and roofs.

Brick in Mud: These are brick masonry buildings with fired bricks in mud mortar.



Fig 1.1 (a) Adobe Building



Fig 1.1 (b) Brick in Mud Building



Fig 1.1 (c) Stone in Mud Building

Type 2 - Brick in Cement, Stone in Cement

These types of buildings are most common in Nepal. Buildings that are built mostly in rural and outskirts of urban areas belong to this type. Some 15-20 years back, such buildings were built in urban areas as well.



Fig 1.2 (a) Brick in Cement Building



Fig 1.2 (b) Stone in Cement Building

Main features of this type of building are:

- Foundations are usually openly-excavated strip footings built of stone in mud mortar or brickwork in cement mortar up to the ground-level. The plinth masonry above ground-level to the plinth-level is brickwork in cement mortar, the thickness of walls are about half a brick larger than the superstructure walls.
- The superstructure walls are one brick thick constructed in 1:6 cement sand mortar, in general. Bricks are of a good quality, usually with a crushing strength of more than 7.5 N/mm². The construction quality is good with soaking of bricks beforehand and filling of joints with mortar.
- The number of stories usually goes up to three. The floors are of either reinforced concrete or reinforced brick slabs. The roof is also of similar construction although in some cases it is made of sloped RC slabs.
- The use of lintel-level bands was not practiced. Rarely, a peripheral beam was cast with the floor slab. But, however, some newly built buildings do have earthquake resistant features such as horizontal bands at sill, lintel and floor level and vertical band at corners and junction of walls.

Type 3 – Non-Engineered Reinforced Concrete Moment-Resistant-Frames.

This type of building consists of a frame assembly of cast-in-place concrete beams and columns. The floors and roof consist of cast-in-place concrete slabs. Walls consist of infill panels constructed of solid clay bricks. The present trend of building construction in urban areas of Nepal for residential, shop-cum-residential and shop-cum-office-cum-residential buildings is to use reinforced concrete beam-column frames with randomly-placed brick walls in two directions. These buildings are usually built informally. Some of the conspicuous features of such buildings are:

- *Planning:* The column spacing in each direction of the building varies from 3 m to 4.5 m. In most cases, the storey-heights are 2.7 m but sometimes they are up to 3.0 m floor-to-floor. Internal partitions and parapet walls are usually half brick thick while external walls are one brick thick with relatively big openings for windows.
- *Foundations:* Isolated column footings type foundation is provided. The area of footing generally varies from 1.2 m x 1.2 m to 2.0m x 2.0m. The depth varies from 0.9 to 1.2 m below ground level.
- *Columns:* A 230 x 230 mm (9" x 9") column-size is most commonly used for up to five stories and even more, both for face and internal columns. The longitudinal reinforcement commonly used is 4 bars of 16 mm ϕ and 2 bars of 12 mm ϕ of high-strength steel (Fe415) and the ties are usually either 6 mm ϕ plain mild steel (Fe250) or 5 mm ϕ high-strength twisted steel (Fe500) at 200 mm centers.

- *Beams:* A usual rib size is 230 x 230 mm (9" x 9"), with a web projecting below a slab with which it is monolithic, with three to four 12 mm ϕ bars of high-strength bottom steel and two similar bars at the top. Out of the bottom bars, one or two bars are cranked up, making three to four bars near the supports for the hogging moment.
- *Slabs:* The slabs are usually made of reinforced cement concrete or reinforced brick concrete (RBC) 75 to 100 mm (3" to 4") thick, with 10 mm ϕ high-strength steel at 130 mm centers spanning the shorter dimension and the same at 250 centers along the longer span. Alternate bars are bent up near supports to carry the negative moment.



Fig 1.3 Non Engineered Reinforced Concrete Moment Resisting Frame Buildings

The buildings can further be divided into two sub groups, considering the number of stories, as the vulnerability of these types of buildings highly depends on the number of stories.

A: Non engineered reinforced concrete moment resisting frame building with more than three stories.

B: Non engineered reinforced concrete moment resisting frame building less than or equal to three stories.

Type 4 - Engineered Reinforced Concrete Moment-Resistant-Frames

These buildings consist of a frame assembly of cast-in-place concrete beams and columns. Floor and roof framing consists of cast-in-place concrete slabs. Lateral forces are resisted by concrete moment frames that develop their stiffness through monolithic beam-column connections. These buildings are built with little or extensive input from engineers or designers for earthquakes. Some of the newly constructed reinforced concrete buildings in urban areas of Nepal are likely to be of this type. These buildings are categorized in three groups:

Group I - Good type of engineered RC moment resisting frame building. These buildings are properly designed by engineers for expected earthquake. Minimum Column size is of 300 mm X 300 mm or more depending on load induced. Shape of this type of building is regular and ductile detailing is fully enforced at site as per IS 13920.

Group II - Average type of engineered RC moment resisting frame building. These buildings are designed by engineers for earthquake force and column size is usually 230 mm X 300 mm. However, ductile detailing is partially implemented in this type of building.

Group III - Weak type of engineered RC moment resisting frame building typology: These buildings are either not designed by engineers or designed for non seismic load only. Column size is usually 230 mm X 230 mm or 230 mm X 300 mm and ductile detailing is generally not implemented or partially implemented. These buildings have critical deficiencies which can be either of soft storey effect, short column effect, and shape irregularity, inadequate distribution of structural elements or lack of ductile detailing.

The seismic performance of this type of construction depends on the interaction between the frame and the infill panels. The combined behavior is more like that of a shear wall structure than a frame structure. Solidly in-filled masonry panels form diagonal compression struts between the intersections of the frame members. If the walls are offset from the frame and do not fully engage the frame members, the diagonal compression struts will not develop. The strength of the infill panel is limited by the shear capacity of the masonry bed joint or the compression capacity of the strut. The post-cracking strength is determined by an analysis of a moment frame that is partially restrained by the cracked infill. The shear strength of the concrete columns, after cracking of the infill, may limit the semi ductile behavior of the system.



Fig 1.4 Engineered Reinforced Concrete Moment Resisting Frame Buildings

Type 5 - Other

If the building does not fall within one of the categories mentioned above the building may have different seismic behavior depending on its inherent strengths and weaknesses. This is due to use of composite and mixed type of reinforced concrete, masonry units and mortar in the same building.



Fig 1.5 (a) Stone in Mud in Ground Floor and Brick in Mud in First Floor

7. Annex II: Seismic Vulnerability Factors and their consequence

Basic Factors Influencing the Seismic Performance of Buildings

Load Path

The general load path of a building is as follows:

seismic forces originating throughout the building are delivered through structural connections to horizontal diaphragms; the diaphragms distribute these forces to vertical lateral-force-resisting elements such as shear walls and frames; the vertical elements transfer the forces into the foundation; and the foundation transfers the forces into the supporting soil.

There must be a complete lateral-force-resisting system that forms a continuous load path between the foundation, all diaphragm levels, and all portions of the building for proper seismic performance. If there is a discontinuity in the load path, the building is unable to resist seismic forces regardless of the strength of the existing elements. Mitigation with elements or connections is needed to complete the load path to achieve the selected performance level.

Examples of such structures would include a masonry shear wall that does not extend to the foundation, or a column in upper storey that does not continue to foundation.



Fig 2.1 (a) Full Brick Wall on Cantilever Slab Projection

Fig 2.1 (b) Beam Resting on Beam

Load Path Problem

Is there any masonry wall in cantilever?

Any column has started from beam? Not continue from foundation?

Is there any masonry wall, which does not continue to foundation?

If yes, there is problem of clear load path!

Adjacent Buildings and Poundings

If buildings are built without sufficient gap and the interaction has not been considered, the buildings may impact each other, or pound, during an earthquake. Building pounding can alter the dynamic response of both buildings, and impart additional inertial loads on both structures. Buildings that are with the same height and have matching floors will exhibit similar dynamic behavior. If the buildings

pound, floors will impact other floors, so damage due to pounding usually will be limited to nonstructural components. When the floors of adjacent buildings are at different elevations, floors will impact the columns of the adjacent building and can cause structural damage. Since neither building is designed for these conditions, there is a potential for extensive damage and possible collapse.




Fig 2.2 (a): Different Floor Height Buildings Suffer More in Pounding




Fig 2.2 (b): Pounding due to Small Gap of Two Buildings





Fig 2.2 (c): Sufficient Gap Between Two Buildings Prevent from Pounding



Fig 2.2 (d) Sufficient Gap Between Buildings to Avoid Pounding



Fig 2.2 (e) Buildings Attached to Each Other Without Seismic Gap (These buildings are liable to suffer in pounding)



Configuration

Configuration of buildings is related to dimensions, building form, geometric proportions and the locations of structural components. The configuration of a building will influence the seismic performance of a building, particularly regarding the distribution of the seismic loads.

From past earthquake experiences, it can be stated that the buildings with simple configurations and symmetrical are more resistant to earthquake shaking. Good detailing and construction quality are of secondary value if a building has an odd shape that is not properly considered in the design. Although a building with an irregular configuration may be designed to meet all code requirements, buildings of irregular shape generally do not perform as well as regular-shaped buildings in an earthquake. Typical building configuration deficiencies include an irregular geometry, a weakness in a given storey, a concentration of mass, or a discontinuity in the lateral force resisting system.

Vertical irregularities are defined in terms of strength, stiffness, geometry, and mass. These quantities are evaluated separately, but are related and may occur simultaneously. Horizontal irregularities involve the horizontal distribution of lateral forces to the resisting frames or shear walls.



Fig 2.3 (a) U Shaped Building



**Fig 2.3 (b) L-Shaped School Building
Irregularities in Shape**

Redundancy

Redundancy is a fundamental characteristic of lateral force resisting systems with superior seismic performance. Redundancy in the structure will ensure that if an element in the lateral force resisting system fails for any reason, there is another element present that can provide lateral force resistance. Redundancy also provides multiple locations for potential yielding, distributing inelastic activity throughout the structure and improving ductility and energy dissipation. Typical characteristics of redundancy include multiple lines of resistance to distribute the lateral forces uniformly throughout the structure, and multiple bays in each line of resistance to reduce the shear and axial demands on any one element.

A distinction should be made between redundancy and adequacy. The redundancy mentioned here is intended to mean simply "more than one." This should not be interpreted as for large buildings two elements are adequate and for small buildings one is not enough.



Fig 2.4 (a) Single Bay RC Frame Building



Fig 2.4 (b) Slender Building

Problem due to Inadequate Redundancy

Is the building structure single bay in one or both direction?

If yes, there is no redundancy in the building.

Weak Storey

The storey strength is the total strength of all the lateral force-resisting elements in a given storey for the direction under consideration. It is the shear capacity of columns or shear walls. If the columns are flexure-controlled, the shear strength is the shear corresponding to the flexural strength. Weak stories are usually found where vertical discontinuities exist, or where member size or reinforcement has been reduced. It is necessary to calculate the storey strengths and compare them. The result of a weak storey is a concentration of inelastic activity that may result in the partial or total collapse of the storey.

Soft Storey

This condition commonly occurs in buildings in urban areas where ground floor is usually open for parking or shops for commercial purposes. Soft stories usually are revealed by an abrupt change in inter-storey drift. Although a comparison of the stiffness in adjacent stories is the direct approach, a simple first step might be to plot and compare the inter-storey drifts if analysis results are available.

The difference between "soft" and "weak" stories is the difference between stiffness and strength. A column may be slender but strong, or stiff but weak. A change in column size can affect strength and stiffness, and both need to be considered.




Fig 2.5 (a) Soft Storey due to Excessive Floor Height in Ground Storey




Fig 2.5 (b) Soft Storey due to Open Floors



Fig 2.5 (c) Soft Storey Problem due to Lack of Brick Infill in Ground Floor

Geometry

Is there vertical discontinuity of shear walls or columns in ground or any other storey?

Is there open ground or any other storey?

Is the column or floor height of any one storey is more than that of adjacent storey?

If yes, there may be a problem of weak storey or soft storey.

Geometric irregularities are usually detected in an examination of the storey-to-storey variation in the dimensions of the lateral-force-resisting system. A building with upper stories set back from a broader base structure is a common example. Another example is a storey in a high-rise that is set back for architectural reasons. It should be noted that the irregularity of concern is in the dimensions of the lateral-force-resisting system, not the dimensions of the envelope of the building, and, as such, it may not be obvious.




Fig 2.6 (a) Vertical Irregularity in Buildings




Fig 2.6 (b) Shear Walls in Cantilever




Fig 2.6 (c) Excessive Setback



Fig 2.6 (d) Vertically Irregular Building

Are the shear walls or the columns of a storey setback as compared to the adjacent storey?

Are the shear walls or the columns of a storey placed in projected parts as compared to the adjacent stories?

If yes, there is problem of vertical irregularity

Vertical Discontinuities

Vertical discontinuities are usually detected by visual observation. The most common example is a discontinuous columns or masonry shear wall. The element is not continuous to the foundation but stops at an upper level. The shear at this level is transferred through the diaphragm to other resisting elements below.

This issue is a local strength and ductility problem below the discontinuous element, not a global storey strength or stiffness irregularity. The concern is that the wall or frame may have more shear capacity than considered in the design.

Is there any column or shear wall that is not continuing to the foundation? If so, that is vertical discontinuities.

Mass

Mass irregularities can be detected by comparison of the storey weights. The effective mass consists of the dead load of the structure to each level, plus the actual weights of partitions and permanent equipment at each floor. The validity of this approximation depends upon the vertical distribution of mass and stiffness in the building.




Fig 2.7 Mass Irregularity

Are there heavy walls as compared to the adjacent stories?

Are there heavy equipments as compared to that in the adjacent stories?

Is the thickness of the floor diaphragm more than that of the adjacent floor?

Is the mass due to all structural and non-structural components in storey is less or more than 50% of that of the adjacent stories

Torsion

Whenever there is significant torsion in a building, the concern is for additional seismic demands and lateral drifts imposed on the vertical elements by rotation of the diaphragm. Buildings can be designed to meet code forces including torsion, but buildings with severe torsion are less likely to perform well in earthquakes. It is best to provide a balanced system at the start, rather than design torsion into the system.




Fig 2.8 Effect of Torsion in Building

Condition of Materials

Deteriorated structural materials may reduce the capacity of the vertical and lateral force resisting systems. The most common type of deterioration is caused by the intrusion of water. Stains may be a clue to water-caused deterioration where the structure is visible on the exterior, but the deterioration may be hidden where the structure is concealed by finishes. In the latter case, the assessment team may have to find a way into attics, plenums, and crawl spaces in order to assess the structural systems and their condition.

Deterioration of Wood

The condition of the wood in a structure has a direct relationship as to its performance in a seismic event. Wood that is split, rotten or has insect damage may have a very low capacity to resist loads imposed by earthquakes. Structures with timber elements depend to a large extent on the connections between members. If the wood at a bolted connection is split, the connection will possess only a fraction of the capacity of a similar connection in undamaged wood.

Deterioration of Concrete

Deteriorated concrete and reinforcing steel can significantly reduce the strength of concrete elements. This statement is concerned with deterioration such as *spalled* concrete associated with rebar corrosion and water intrusion. Crack in concrete is another problem. *Spalled* concrete over reinforcing bars reduces the available surface for bond between the concrete and steel. Bar corrosion may significantly reduce the cross section of the bar.

Deterioration is a concern when the concrete cover has begun to spall, and there is evidence of rusting at critical locations.



Fig 2.9 (a) Delamination due to Seepage of Water



Fig 2.9 (b) Rusting of Steel Bar

Problem due to Concrete Deterioration

Masonry Units and Joints

Deteriorated or poor quality masonry elements can result in significant reductions in the strength of structural elements. Older buildings constructed with lime mortar may have surface re-pointing but still have deteriorated mortar in the main part of the joint. Mortar that is severely eroded or that can easily be scraped away has been found to have low shear strength, which results in low wall strength.



Fig 2.10 Problem due to Deterioration of Masonry Units and Joints

Unreinforced Masonry Wall Cracks

Diagonal wall cracks, especially along the masonry joints, may affect the interaction of the masonry units, leading to a reduction of strength and stiffness. The cracks may indicate distress in the wall from past seismic events, foundation settlement, or other causes.

Crack width is commonly used as a convenient indicator of damage to a wall, but it should be noted that other factors, such as location, orientation, number, distribution and pattern of the cracks to be equally important in measuring the extent of damage present in the shear walls. All these factors should be considered when evaluating the reduced capacity of a cracked element.



Fig 2.11 Problem due to Crack in Brick Wall

Cracks in Boundary Columns

Small cracks in concrete elements have little effect on strength. A significant reduction in strength is usually the result of large displacements or crushing of concrete. Only when the cracks are large enough to prevent aggregate interlock or have the potential for buckling of the reinforcing steel does the adequacy of the concrete element capacity become a concern.

Columns are required to resist diagonal compression strut forces that develop in infill wall panels. Vertical components induce axial forces in the columns. The eccentricity between horizontal components and the beams is resisted by the columns. Extensive cracking in the columns may indicate locations of possible weakness. Such columns may not be able to function in conjunction with the infill panel as expected.

Factors Associated with Lateral Force Resisting System of Different Buildings Influencing the Seismic Performance

Moment Frames

Moment frames develop their resistance to lateral forces through the flexural strength and continuity of beam and column elements. In an earthquake, a frame with suitable proportions and details can develop plastic hinges that will absorb energy and allow the frame to survive actual displacements that are larger than calculated in an elastic state design.

In modern moment frames, the ends of beams and columns, being the locations of maximum seismic moment, are designed to sustain inelastic behavior associated with plastic hinging over many cycles and load reversals. Frames that are designed and detailed for this ductile behavior are called *Ductile Moment Resisting Frames*.

Moment Frames with Infill Walls

Infill walls used for partitions, cladding or shaft walls that enclose stairs and elevators should be isolated from the frames. If not isolated, they will alter the response of the frames and change the behavior of the entire structural system. Lateral drifts of the frame will induce forces on walls that interfere with this movement. Cladding connections must allow for this relative movement. Stiff infill walls confined by the frame will develop compression struts that will impart loads to the frame and cause damage to the walls. This is particularly important around stairs or other means of egress from the building.

Interfering Walls

When an infill wall interferes with the moment frame, the wall becomes an unintended part of the lateral-force-resisting system. Typically these walls are not designed and detailed to participate in the lateral-force-resisting system and may be subject to significant damage. Interfering walls should be checked for forces induced by the frame, particularly when damage to these walls can lead to falling

hazards near means of egress. The frames should be checked for forces induced by contact with the walls, particularly if the walls are not full height, or do not completely infill the bay.

Wall Connections

Performance of frame buildings with masonry infill walls is dependent upon the interaction between the frame and infill panels. In-plane lateral force resistance is provided by a compression strut developing in the infill panel that extends diagonally between corners of the frame. If gaps exist between the frame and infill, this strut cannot be developed. If the infill panels separate from the frame due to out-of-plane forces, the strength and stiffness of the system will be determined by the properties of the bare frame, which may not be detailed to resist seismic forces. Severe damage or partial collapse due to excessive drift and p -delta effects may occur.

A positive connection is needed to anchor the infill panel for out-of-plane forces. In this case, a positive connection can consist of a fully grouted bed joint in full contact with the frame, or complete encasement of the frame by the brick masonry.



Fig 2.12 (a) Separation of Infill Wall from Frame using Flexible Material



Fig 2.12 (b) Tying of Infill Wall with Frame

Concrete Moment Frames

Concrete moment frame buildings typically are more flexible than shear wall buildings. This flexibility can result in large inter-storey drifts that may lead to extensive nonstructural damage. If a concrete column has a capacity in shear that is less than the shear associated with the flexural capacity of the column, brittle column shear failure may occur and result in collapse.

The following are the characteristics of concrete moment frames that have demonstrated acceptable seismic performance:

- Brittle failure is prevented by providing a sufficient number of beam stirrups, column ties, and joint ties to ensure that the shear capacity of all elements exceeds the shear associated with flexural capacity,
- Concrete confinement is provided by beam stirrups and column ties in the form of closed hoops with 135-degree hooks at locations where plastic hinges will occur.
- Overall performance is enhanced by long lap splices that are restricted to favorable locations and protected with additional transverse reinforcement.
- The strong column/weak beam requirement is achieved by suitable proportioning of the members and their longitudinal reinforcing.

All these detailing result in ductile response of moment-resisting-frame buildings in lateral loading of earthquakes.

Shear Stress Check

The shear stress check provides a quick assessment of the overall level of demand on the structure. The concern is the overall strength of the building.

Axial Stress Check

Columns that carry a substantial amount of gravity load may have limited additional capacity to resist seismic forces. When axial forces due to seismic overturning moments are added, the columns may crush in a non-ductile manner due to excessive axial compression.

Flat Slab Frames

The concern is the transfer of the shear and bending forces between the slab and column, which could result in a punching shear failure and partial collapse. The flexibility of the lateral-force-resisting system will increase as the slab cracks.

Short Captive Columns

Short captive columns tend to attract seismic forces because of high stiffness relative to other columns in a storey. Captive column behavior may also occur in buildings with clerestory windows, or in buildings with partial height masonry infill panels.

If not adequately detailed, the columns may suffer a non-ductile shear failure which may result in partial collapse of the structure.

A captive column that can develop the shear capacity to develop the flexural strength over the clear height will have some ductility to prevent sudden non-ductile failure of the vertical support system.



Fig 2.13 (a) Beam at Mid Height of Column



Fig 2.13 (b) Ventilator Attached to Frame

Problem due to Short Column if not Properly Considered

No Shear Failures

If the shear capacity of a column is reached before the moment capacity, there is a potential for a sudden non-ductile failure of the column, leading to collapse.

Columns that cannot develop the flexural capacity in shear should be checked for adequacy against calculated shear demands. Note that the shear capacity is affected by the axial loads on the column and should be based on the most critical combination of axial load and shear.

Strong Column Weak Beam

When columns are not strong enough to force hinging in the beams, column hinging can lead to storey mechanisms and a concentration of inelastic activity at a single level. Excessive storey drifts may result in instability of the frame due to $P-\Delta$ effects. Good post-elastic behavior consists of yielding distributed throughout the frame. A storey mechanism will limit forces in the levels above, preventing the upper levels from yielding.

The alternative procedure checks for the formation of a storey mechanism. The storey strength is the sum of the shear capacities of all the columns as limited by the controlling action. If the columns are shear critical, a shear mechanism forms at the shear capacity of the columns. If the columns are controlled by flexure, a flexural mechanism forms at a shear corresponding to the flexural capacity.

Beam Bars

The requirement for two continuous bars is a collapse prevention measure. In the event of complete beam failure, continuous bars will prevent total collapse of the supported floor, holding the beam in place by catenaries action. Previous construction techniques used bent up longitudinal bars as reinforcement. These bars transitioned from bottom to top reinforcement at the gravity load inflection point. Some amount of continuous top and bottom reinforcement is desired because moments due to seismic forces can shift the location of the inflection point. Because non-compliant beams are vulnerable to collapse, the beams are required to resist demands at an elastic level.

Column Bar Splices

Column bar splices are typically located in regions of potential plastic hinge formation, just above the floor level. Short splices are subject to sudden loss of bond. Widely spaced ties can result in a spalling of the concrete cover and loss of bond. Splice failures are sudden and non-ductile.

Beam Bar Splices

Lap splices located at the end of beams and in vicinity of potential plastic hinges may not be able to develop the full moment capacity of the beam as the concrete degrades during multiple cycles.

Column Tie Spacing

Widely spaced ties will reduce the ductility of the column, and it may not be able to maintain full moment capacity through several cycles. Columns with widely spaced ties have limited shear capacity and non-ductile shear failures may result.

Stirrup Spacing

Widely spaced stirrups will reduce the ductility of the beam, and it may not be able to maintain full moment capacity through several cycles. Beams with widely spaced stirrups have limited shear capacity and non-ductile shear failures may result.

Joint Reinforcing

Beam-column joints without shear reinforcement may not be able to develop the strength of the connected members, leading to a non-ductile failure of the joint. Perimeter columns are especially vulnerable because the confinement of joint is limited to three sides (along the exterior) or two sides (at a corner).

Joint Eccentricity

Joint eccentricities can result in high *torsional* demands on the joint area, which will result in higher shear stresses.

Stirrup and Tie Hooks

To be fully effective, stirrups and ties must be anchored into the confined core of the member. 90° hooks that are anchored within the concrete cover are unreliable if the cover spalls during plastic hinging. The amount of shear resistance and confinement will be reduced if the stirrups and ties are not well anchored.

Unreinforced Masonry Shear Walls

Shear Stress Check

The shear stress check provides a quick assessment of the overall level of demand on the structure. The concern is the overall strength of the building.

Proportions

Slender unreinforced masonry bearing walls with large height-to-thickness ratios or large length-to-thickness ratio have a potential for damage due to out-of-plane forces which may result in falling hazards and potential collapse of the structure.



Fig 2.14 (a) Long Unsupported Wall




Fig 2.14 (b) Slender Wall

Problem due to Inadequate Proportions of Load Bearing Walls

Position of Openings

Openings attached to load bearing masonry walls and too large openings reduce both out-of-plane and in-plane stability of the building



Fig 2.15 (a) Large Window Openings in Masonry Walls



Fig 2.15 (b) Window Attached to Wall

Problem due to Openings

Masonry Lay-up

When walls have poor collar joints, the inner and outer *wythes* will act independently. The walls may be inadequate to resist out-of-plane forces due to a lack of composite action between the inner and outer *wythes*. Mitigation to provide out-of-plane stability and anchorage of the *wythes* may be necessary to achieve the selected performance level.

Solid Walls

When the walls are of cavity construction, the inner and outer *wythes* will act independently due to a lack of composite action, increasing the potential for damage from out-of-plane forces. Failure of these walls out-of-plane will result in falling hazards and degradation of the strength and stiffness of the lateral force resisting system. Mitigation to provide out-of-plane stability and anchorage of the *wythes* is necessary to achieve the selected performance level.

Earthquake Resistant Element

Unreinforced Masonry walls have very low (almost negligible) tension resisting capacity. Hence, the presence of bands at lintel, sill and roof level, corner stitches, vertical reinforcements at corners and junctions of wall, mitigate the damage due to tension and shear cracks.



Fig 2.16 (a) Vertical Reinforcement and Corner Stitch



Fig 2.16 (b) Presence of Sill Band, Corner Stitch and Lintel Band

Presence of Earthquake Resisting Element

Factors Associated with Diaphragms

General

Diaphragms are horizontal elements that distribute seismic forces to vertical lateral force resisting elements. They also provide lateral support for walls and parapets. Diaphragm forces are derived from the self weight of the diaphragm and the weight of the elements and components that depend on the diaphragm for lateral support. Any roof, floor, or ceiling can participate in the distribution of lateral forces to vertical elements up to the limit of its strength. The degree to which it participates depends on relative stiffness and on connections. In order to function as a diaphragm, horizontal elements must be interconnected to transfer shear, with connections that have some degree of stiffness.

An important characteristic of diaphragms is flexibility, or its opposite, rigidity. In seismic design, rigidity means relative rigidity. Of importance is the in-plane rigidity of the diaphragm relative to the walls or frame elements that transmit the lateral forces to the ground.

Diaphragm Continuity

Split level floors and roofs, or diaphragms interrupted by expansion joints, create discontinuities in the diaphragm. It is a problem unless special details are used, or lateral-force-resisting elements are

provided at the vertical offset of the diaphragm or on both sides of the expansion joint. Such a discontinuity may cause the diaphragm to function as a cantilever element or three-sided diaphragm. If the diaphragm is not supported on at least three sides by lateral-force-resisting elements, torsional forces in the diaphragm may cause it to become unstable.



Fig 2.17 (a) Drop in Floor Slab



Fig 2.17 (b) Large Diaphragm Opening Overlooking a Living Room Below

Problem due to Discontinuity in Floor Diaphragm

Openings at Shear Walls and Exterior Masonry Shear Walls

Large openings at shear walls significantly limit the ability of the diaphragm to transfer lateral forces to the wall. This can have a compounding effect if the opening is near one end of the wall and divides the diaphragm into small segments with limited stiffness that are ineffective in transferring shear to the wall. Large openings may also limit the ability of the diaphragm to provide out-of-plane support for the wall.

Plan Irregularities

Diaphragms with plan irregularities such as extending wings, plan insets, or *E*, *T*, *X*, *L* or *C* shaped configurations have re-entrant corners where large tensile and compressive forces can develop. The diaphragm may not have sufficient strength at these re-entrant corners to resist these tensile forces and local damage may occur.

8. Annex III: Vulnerability Factors Identification Checklist

Vulnerability Factors Identification

Appropriate checklists for different types of buildings are given in this section. Checklists available for certain building types are taken from *FEMA 310, Handbook for the Seismic Evaluation of Buildings*, and *IS Guidelines for Seismic Evaluation and Strengthening of Existing Building*. Checklists for some building types, which are not included in *FEMA 310* and *IS Guidelines* are developed as per Nepal National Building Code. The checklist covers the basic vulnerability factors related to building systems, lateral force resisting systems, connections and diaphragms which will be evaluated mostly based on visual observation.

Structural Assessment Checklist for Type 1 Buildings (Adobe, Stone in Mud, Brick in Mud)

Building System

- C NC N/A SHAPE: The building shall be symmetrical in plan and regular in elevation.
- C NC N/A PROPORTION IN PLAN: The breadth to length ratio of the building shall be within 1:3. The breadth to length ratio of any room or area enclosed by load bearing walls inside the building shall be also within 1:3. The building height shall be not more than three times the width of the building.
- C NC N/A STOREY HEIGHT: The floor to floor height of the building shall be between 2-3 m.
- C NC N/A NUMBER OF STORIES: The building shall be up to two stories only.
- C NC N/A FOUNDATION: The foundation width and depth shall be at least 75cm. Masonry unit shall be of flat-bedded stones or regular-sized well-burnt bricks. Mortar joints shall not exceed 20mm in any case. There shall be no mud-packing in the core of the foundation.
- C NC N/A SLOPING GROUND: The slope of the ground where the building lies shall not be more than 20° (1:3, vertical: horizontal)
- C NC N/A PLUMBLINE: Walls of the foundation and superstructure shall be true to plumb line and the width of the wall shall be uniform.
- C NC N/A WALL CORE: There shall be no mortar packing in the core of the wall.
- C NC N/A THROUGH-STONES: In case of stone building, the walls shall have plenty of through-stones extending the whole width of the walls. The maximum spacing of such through-stones shall be within 1.2 m horizontally and 0.6 m vertically.
- C NC N/A WALL THICKNESS: The minimum wall thickness in mm for different storey heights shall not be less than

| Masonry Type | No of Storey | |
|--------------|--------------|-----|
| | One | Two |
| Stone | 340-450 | 450 |
| Brick | 230 | 350 |

- C NC N/A UNSUPPORTED WALL LENGTH: The maximum length of unsupported wall shall not be more than 12 times its thickness. If the length of unsupported wall is more than 12 times its thickness, buttressing shall be provided.
- C NC N/A HEIGHT OF WALLS: The thickness to height ratio of a wall shall not be more than 1:8 for stone building and 1:12 for brick building.
- C NC N/A OPENINGS IN WALL: The maximum combined width of the openings on a wall between two consecutive cross-walls shall not be more than 35% of the total wall

- length for one-storey building and not more than 25% of the total wall length in two-storey building.
- C NC N/A POSITION OF OPENINGS: Openings shall not be located at corners or junctions of a wall. Openings shall not be placed closer to an internal corner of a wall than half the opening height or 1.5 times the wall thickness, whichever is greater. The width of pier between two openings shall not be less than half of the opening height or 1.5 times the wall thickness, whichever is greater. The vertical distance between two openings shall not be less than 0.6 m or half the width of the smaller opening, whichever is greater.
- C NC N/A LOAD PATH: The structure shall contain at least one rational and complete load path for seismic forces from any horizontal direction so that they can transfer all inertial forces in the building to the foundation.
- C NC N/A VERTICAL DISCONTINUITIES: All vertical elements in the lateral-force-resisting system shall be continuous to the foundation.
- C NC N/A MASS: There shall be no change in effective mass more than 100% from one storey to the next.
- C NC N/A TORSION: The estimated distance between the storey center of mass and the storey centre of stiffness shall be less than 30% of the building dimension at right angles to the direction of loading considered.
- C NC N/A MASONRY UNITS: There shall be no visible deterioration of masonry units.
- C NC N/A WALL CRACKS: There shall be no existing diagonal cracks in wall elements greater than 1/16" or out-of-plane offsets in the bed joint greater than 1/16".
- C NC N/A MASONRY LAY-UP: Filled collar joints of *multiwythe* masonry walls shall have negligible voids.
- C NC N/A VERTICAL REINFORCEMENT: There shall be vertical reinforcement at all corners and T-junctions of masonry walls and it shall be started from foundation and continuous to roof.
- C NC N/A HORIZONTAL BANDS: There shall be steel or wooden bands located at the plinth, sill and lintel levels of the building in each floor.
- C NC N/A CORNER STITCH: There shall be reinforced concrete or wooden elements connecting two orthogonal walls at a vertical distance of at least 0.5 m to 0.7 m.
- C NC N/A GABLE BAND: If the roof is sloped roof, gable band shall be provided to the building.

Lateral Force Resisting System

- C NC N/A REDUNDANCY: The number of lines of walls in each principal direction shall be greater than or equal to 2.

Diaphragms

- C NC N/A DIAGONAL BRACING: All flexible structural elements of diaphragms such as joists and rafters shall be diagonally braced and each crossing of a joist/rafter and a brace shall be properly fixed.
- C NC N/A LATERAL RESTRAINERS: Each joists and rafters shall be restrained by timber keys in both sides of wall.

Geologic Site

- C NC N/A NK AREA HISTORY: Evidence of history of landslides, mud slides, soil settlement, sinkholes, construction on fill, or buried on or at sites in the area are not anticipated.

C NC N/A NK LIQUEFACTION: Liquefaction susceptible, saturated, loose granular soils that could jeopardize the building's seismic performance shall not exist in the foundation soils.

C NC N/A NK SLOPE FAILURE: The building site shall be sufficiently remote from potential earthquake induced slope failures or rock falls to be unaffected by such failures or shall be capable of accommodating any predicted movements without failure

Structural Assessment Checklist for Type 2 Buildings (Brick in Cement Buildings and Stone in Cement Buildings)

Building System

C NC N/A NK LOAD PATH: The structure shall contain at least one rational and complete load path for seismic forces from any horizontal direction so that they can transfer all inertial forces in the building to the foundation.

C NC N/A NK REDUNDANCY: The number of lines of vertical lateral load resisting elements in each principal direction shall be greater than or equal to 2. Similarly, the number of lines of shear walls in each direction shall be greater than or equal to 2.

C NC N/A NK GEOMETRY: No change in the horizontal dimension of lateral force resisting system of more than 50% in a storey relative to adjacent stories, excluding penthouses and mezzanine floors, should be made.

C NC N/A NK MEZZANINES/LOFT/SUBFLOORS: Interior mezzanine/loft/sub-floor levels shall be braced independently from the main structure, or shall be anchored to the lateral-force-resisting elements of the main structure.

C NC N/A NK WEAK STORY: The strength of the vertical lateral force resisting system in any storey shall not be less than 70% of the strength in an adjacent story.

C NC N/A NK SOFT STORY: The stiffness of the vertical lateral load resisting system in any storey shall not be less than 60% of the stiffness in an adjacent story above or less than 70% of the average stiffness of the three storey above.

C NC N/A NK VERTICAL DISCONTINUITIES: All vertical elements in the lateral force resisting system shall be continuous from the root to the foundation.

C NC N/A NK MASS: There shall be no change in effective mass more than 100% from one storey to the next. Light roofs, penthouse, and mezzanine floors need not be considered.

C NC N/A NK TORSION: The estimated distance between the storey center of mass and the storey centre of stiffness shall be less than 30% of the building dimension at right angles to the direction of loading considered.

C NC N/A NK ADJACENT BUILDINGS: The clear horizontal distance between the building under consideration and any adjacent building shall be greater than 4 % of the height of the shorter building, except for buildings that are of the same height with floors located at the same levels.

C NC N/A NK DETERIORATION OF CONCRETE: There should be no visible deterioration of the concrete or reinforcing steel in any of the vertical or lateral force resisting elements.

C NC N/A NK MASONRY UNITS: There shall be no visible deterioration of masonry units.

C NC N/A NK MASONRY JOINTS: The mortar shall not be easily scraped away from the joints by hand with a metal tool, and there shall be no areas of eroded mortar.

C NC N/A NK UNREINFORCED MASONRY WALL CRACKS: There shall be no existing diagonal cracks in wall elements greater than 1/8" for Life Safety and 1/16" for Immediate Occupancy or out-of-plane offsets in the bed joint greater than 1/8" for Life Safety and 1/16" for Immediate Occupancy.

Lateral Load Resisting System

C NC N/A NK SHEAR STRESS IN SHEAR WALLS: Average shear stress in masonry shear walls, τ_{wall} shall be calculated as per 6.5.2 of IITK- GSDMA guidelines for seismic evaluation and strengthening of buildings. For unreinforced masonry load bearing wall building, the average shear stress, τ_{wall} shall be less than 0.10 MPa.

C NC N/A NK HEIGHT TO THICKNESS RATIO: The unreinforced masonry wall height-to-thickness ratios shall be less than the following.

Top storey of multi storey building: 9

First storey of multi storey building: 15

All other conditions: 13

C NC N/A NK MASONRY LAY UP: Filled collar joints of multi *wythe* masonry walls shall have negligible voids.

C NC N/A NK WALL ANCHORAGE: Walls shall be properly anchored to diaphragms for out of plane forces with anchor spacing of 1.2 m or less.

C NC N/A NK CONNECTIONS: Diaphragms shall be reinforced and connected to transfer of loads to the shear walls.

C NC N/A NK OPENINGS IN DIAPHRAGMS NEAR SHEAR WALLS: Diaphragm openings immediately adjacent to the shear walls shall be less than 25% of the wall length.

C NC N/A NK OPENINGS IN DIAPHRAGMS NEAR EXTERIOR MASONRY SHEAR WALLS: Diaphragm opening immediately adjacent to exterior masonry shear walls not be greater than 2.5 m.

C NC N/A NK PLAN IRREGULARITIES: There shall be tensile capacity to develop the strength of the diaphragm at re-entrant corners or other location of plan irregularities.

C NC N/A NK DIAPHRAGM REINFORCEMENT AT OPENINGS: There shall be reinforcing around all diaphragm opening larger than 50% of the building width in either major plan dimension.

C NC N/A NK VERTICAL REINFORCEMENT: There shall be vertical reinforcement at all corners and T-junctions of masonry walls and it shall be started from foundation and continuous to roof.

C NC N/A NK HORIZONTAL BANDS: There shall be steel or wooden bands located at the plinth, sill and lintel levels of the building in each floor.

C NC N/A NK CORNER STITCH: There shall be reinforced concrete or wooden elements connecting two orthogonal walls at a vertical distance of at least 0.5m to 0.7m.

C NC N/A NK GABLE BAND: If the roof is slopped roof, gable band shall be provided to the building.

C NC N/A NK DIAGONAL BRACING: If there is flexible diaphragms such as joists and rafters shall be diagonally braced and each crossing of a joist/rafter and a brace shall be properly fixed.

C NC N/A NK LATERAL RESTRAINERS: For flexible roof and floor, each joists and rafters shall be restrained by timber keys in both sides of wall.

Additional Factors for Stone Buildings

C NC N/A NUMBER OF STOREYS: The number of storeys of the stone building shall be limited to 2.

C NC N/A UNSUPPORTED WALL LENGTH: The maximum unsupported length of a wall between cross-walls shall be limited to 5m.

Geologic Site

C NC N/A NK AREA HISTORY: Evidence of history of landslides, mud slides, soil settlement, sinkholes, construction on fill, or buried on or at sites in the area are not anticipated.

C NC N/A NK LIQUEFACTION: Liquefaction susceptible, saturated, loose granular soils that could jeopardize the building's seismic performance shall not exist in the foundation soils.

C NC N/A NK SLOPE FAILURE: The building site shall be sufficiently remote from potential earthquake induced slope failures or rock falls to be unaffected by such failures or shall be capable of accommodating any predicted movements without failure

Structural Assessment Checklist for Type 3 and 4 Reinforced Concrete Moment-Resisting-Frame Buildings

Building System

C NC N/A NK LOAD PATH: The structure shall contain at least one rational and complete load path for seismic forces from any horizontal direction so that they can transfer all inertial forces in the building to the foundation.

C NC N/A NK REDUNDANCY: The number of lines of vertical lateral load resisting elements in each principle direction shall be greater than or equal to 2.

C NC N/A NK GEOMETRY: No change in the horizontal dimension of lateral force resisting system of more than 50% in a storey relative to adjacent stories, excluding penthouses and mezzanine floors, should be made.

C NC N/A NK MEZZANINES/LOFT/SUBFLOORS: Interior mezzanine/loft/sub-floor levels shall be braced independently from the main structure, or shall be anchored to the lateral-force-resisting elements of the main structure.

C NC N/A NK WEAK STORY: The strength of the vertical lateral force resisting system in any storey shall not be less than 70% of the strength in an adjacent story.

- C NC N/A NK SOFT STORY: The stiffness of vertical lateral load resisting system in any storey shall not be less than 60% of the stiffness in an adjacent story or less than 70% of the average stiffness of the three storey above.
- C NC N/A NK VERTICAL DISCONTINUITIES: All vertical elements in the lateral force resisting system shall be continuous from the root to the foundation.
- C NC N/A NK MASS: There shall be no change in effective mass more than 100% from one storey to the next. Light roofs, penthouse, and mezzanine floors need not be considered.
- C NC N/A NK TORSION: The estimated distance between the storey center of mass and the storey centre of stiffness shall be less than 30% of the building dimension at right angles to the direction of loading considered.
- C NC N/A NK ADJACENT BUILDINGS: The clear horizontal distance between the building under consideration and any adjacent building shall be greater than 4 % of the height of the shorter building, except for buildings that are of the same height with floors located at the same levels.
- C NC N/A NK FLAT SLAB FRAMES: The lateral-force-resisting system shall not be a frame consisting of columns and a flat slab/plate without beams.
- C NC N/A NK SHORT COLUMNS: The reduced height of a columns due to surrounding parapet, infill wall, etc. shall not be less than five times the dimension of the column in the direction of parapet, infill wall, etc. or 50% of the nominal height of the typical columns in that storey.
- C NC N/A NK DETERIORATION OF CONCRETE: There should be no visible deterioration of the concrete or reinforcing steel in any of the vertical or lateral force resisting elements.
- C NC N/A NK CRACKS IN BOUNDARY COLUMNS: There shall be no existing diagonal cracks wider than 3 mm in concrete columns that encase masonry infills.
- C NC N/A NK MASONRY UNITS: There shall be no visible deterioration of masonry units.
- C NC N/A NK MASONRY JOINTS: The mortar shall not be easily scraped away from the joints by hand with a metal tool, and there shall be no areas of eroded mortar.
- C NC N/A NK CRACKS IN INFILL WALLS: There shall be no existing diagonal cracks in infill walls that extend throughout a panel, are greater than 3mm, or have out of plane offsets in the bed joint greater than 3 mm.

Lateral Load Resisting System

- C NC N/A NK SHEAR STRESS IN RC FRAME COLUMNS: The average shear stress in concrete columns τ_{col} , computed in accordance with 6.5.1 of IITK- GSDMA guidelines for seismic evaluation and strengthening of buildings shall be lesser of 0.4MPa and $0.10 \sqrt{f_{ck}}$
- C NC N/A NK SHEAR STRESS IN SHEAR WALLS: Average shear stress in concrete and masonry shear walls, τ_{wall} shall be calculated as per 6.5.2 of IITK- GSDMA guidelines for seismic evaluation and strengthening of buildings. For concrete shear walls, τ_{wall} shall be less than 0.4 MPa . For unreinforced masonry load bearing wall building wall buildings, the average shear stress, τ_{wall} shall be less than 0.10 MPa.

- C NC N/A NK SHEAR STRESS CHECK FOR RC MASONRY INFILL WALLS: The shear stress in the reinforced masonry shear walls be less than 0.3 MPa and the shear stress in the unreinforced masonry shear walls shall be less than 0.1 MPa.
- C NC N/A NK AXIAL STRESS IN MOMENT FRAMES: The maximum compressive axial stress in the columns of moments frames at base due to overturning forces alone (F_o) as calculated using 6.5.4 equation of IITK- GSDMA guidelines for seismic evaluation and strengthening of buildings shall be less than $0.25f_{ck}$
- C NC N/A NK NO SHEAR FAILURES: Shear capacity of frame members shall be adequate to develop the moment capacity at the ends, and shall be in accordance with provision of IS: 13920 for shear design of beams and columns.
- C NC N/A NK CONCRETE COLUMNS: All concrete columns shall be anchored into the foundation.
- C NC N/A NK STRONG COLUMN/WEAK BEAM: The sum of the moments of resistance of the columns shall be at least 1.1 times the sum of the moment of resistance of the beams at each frame joint.
- C NC N/A NK BEAM BARS: At least two longitudinal top and two longitudinal bottom bars shall extend continuously throughout the length of each frame beam. At least 25% of the longitudinal bars located at the joints for either positive or negative moment shall be continuous throughout the length of the members.
- C NC N/A NK COLUMNS BAR SPLICES: Lap splices shall be located only in the central half of the member length. It should be proportions as a tension splice. Hoops shall be located over the entire splice length at spacing not exceeding 150 mm centre to centre. Not more than 50% of the bars shall preferably be spliced at one section. If more than 50 % of the bars are spliced at one section, the lap length shall be $1.3L_d$ where L_d is the development length of bar in tension as per IS 456:2000
- C NC N/A NK BEAM BAR SPLICES: Longitudinal bars shall be spliced only if hoops are located over the entire splice length, at a spacing not exceeding 150mm. The lap length shall not be less than the bar development length in tension. Lap splices shall not be located (a) within a joint, (b) within a distance of $2d$ from joint face, and (c) within a quarter length of the member where flexural yielding may occur under the effect of earthquake forces. Not more than 50% of the bars shall be spliced at one section.
- C NC N/A NK COLUMN TIE SPACING: The parallel legs of rectangular hoop shall be spaced not more than 300mm centre to centre. If the length of any side of the hoop exceeds 300mm, the provision of a crosstie should be there. Alternatively, a pair of overlapping hoops may be located within the column. The hooks shall engage peripheral longitudinal bars.
- C NC N/A NK STIRRUP SPACING: The spacing of stirrups over a length of $2d$ at either end of a beam shall not exceed (a) $d/4$, or (b) 8 times the diameter of the smallest longitudinal bar; however, it need not be less than 100 mm. The first hoop shall be at a distance not exceeding 50 mm from the joint face. In case of beams vertical hoops at the same spacing as above shall also be located over a length equal to $2d$ on either side of a section where flexural yielding side of a section where flexural yielding may occur under the effect of earthquake forces. Elsewhere, the beam shall have vertical hoops at a spacing not exceeding $d/2$.

C NC N/A NK JOINT REINFORCING: Beam- column joints shall have ties spaced at or less than 150 mm.

C NC N/A NK STIRRUP AND TIE HOOKS: The beam stirrups and column ties shall preferably be anchored into the member cores with hooks of 135°

C NC N/A NK JOINT ECCENTRICITY: There shall be no eccentricities larger than 20% of the smallest column plan dimension between girder and column centerlines. This statement shall apply to the Immediate Occupancy Performance Level only.

C NC N/A NK WALL CONNECTIONS: All infill walls shall have a positive connection to the frame to resist out-of-plane forces.

C NC N/A NK INTERFERING WALLS: All infill walls placed in moment frames shall be isolated from structural elements.

Diaphragms

C NC N/A NK DIAPHRAGM CONTINUITY: The diaphragms shall not be composed of split-level floors. In wood buildings, the diaphragms shall not have expansion joints.

C NC N/A NK PLAN IRREGULARITIES: There shall be tensile capacity to develop the strength of the diaphragm at re-entrant corners or other locations of plan irregularities. This statement shall apply to the Immediate Occupancy Performance Level only.

C NC N/A NK DIAPHRAGM REINFORCEMENT AT OPENINGS: There shall be reinforcing around all diaphragms openings larger than 50% of the building width in either major plan dimension. This statement shall apply to the Immediate Occupancy Performance Level only.

Geologic Site

C NC N/A NK AREA HISTORY: Evidence of history of landslides, mud slides, soil settlement, sinkholes, construction on fill, or buried on or at sites in the area are not anticipated.

C NC N/A NK LIQUEFACTION: Liquefaction susceptible, saturated, loose granular soils that could jeopardize the building's seismic performance shall not exist in the foundation soils.

C NC N/A NK SLOPE FAILURE: The building site shall be sufficiently remote from potential earthquake induced slope failures or rock falls to be unaffected by such failures or shall be capable of accommodating any predicted movements without failure.

9. Annex IV: Damage Grades of Buildings

Classification from European Macro-seismic Scale (EMS 98)

Table 4.1 Classification of Damage to Masonry Buildings











| | |
|---|--|
|  <p>Grade 1: Negligible to slight damage</p> | <p>Structural damage : No Non-structural damage: Slight</p> <ul style="list-style-type: none"> • Hair-line cracks in very few walls. • Fall of small pieces of plaster only. • Fall of loose stones from upper parts of buildings in very few cases. |
|  <p>Grade 2: Moderate damage</p> | <p>Structural damage : Slight Non-structural damage: Moderate</p> <ul style="list-style-type: none"> • Cracks in many walls. • Fall of fairly large pieces of plaster. • Partial collapse of chimneys. |
|  <p>Grade 3: Substantial to heavy damage</p> | <p>Structural damage: Moderate Non-structural damage: Heavy</p> <ul style="list-style-type: none"> • Large and extensive cracks in most walls. • Roof tiles detach. • Chimneys fracture at the roof line; failure of individual non-structural elements (partitions, gable walls). |
|  <p>Grade 4: Very heavy damage</p> | <p>Structural damage: Heavy Non-structural damage: Very heavy</p> <ul style="list-style-type: none"> • Serious failure of walls; partial structural failure of roofs and floors. |
|  <p>Grade 5: Destruction</p> | <p>Structural damage: very heavy</p> <ul style="list-style-type: none"> • Total or near total collapse. |

Table 4.2 Classification of Damage to RC Frame Buildings

| | |
|---|---|
|  <p>Grade 1: Negligible to slight damage</p> | <p>Structural damage : No Non-structural damage: Slight</p> <ul style="list-style-type: none"> • Fine cracks in plaster over frame members or in walls at the base. • Fine cracks in partitions and infill. |
|  <p>Grade 2: Moderate damage</p> | <p>Structural damage : Slight Non-structural damage: Moderate</p> <ul style="list-style-type: none"> • Cracks in columns and beams of frames and in structural walls. • Cracks in partition and infill walls; fall of brittle cladding and plaster. • Falling of mortar from the joints of wall panels. |
|  <p>Grade 3: Substantial to heavy damage</p> | <p>Structural damage: Moderate Non-structural damage: Heavy</p> <ul style="list-style-type: none"> • Cracks in columns and beam column joints of frames at the base and at joints of coupled walls. • Spalling of concrete cover, buckling of reinforced bars. • Large cracks in partition and infill walls, failure of individual infill panels. |
|  <p>Grade 4: Very heavy damage</p> | <p>Structural damage: Heavy Non-structural damage: Very heavy</p> <ul style="list-style-type: none"> • Large cracks in structural elements with compression failure of concrete and fracture of <i>rebars</i>; bond failure of beam reinforced bars; tilting of columns. • Collapse of a few columns or of a single upper floor. |
|  <p>Grade 5: Destruction</p> | <p>Structural damage: very heavy</p> <ul style="list-style-type: none"> • Collapse of ground floor or parts (e.g. wings) of buildings. |

10. Annex V: Modified *Mercally* Intensity Scale (MMI Scale)

| Intensity | Description of Effect |
|------------|--|
| I | <p>Very Weak Intensity</p> <ul style="list-style-type: none"> • Can only be noticed or felt by people who are in the right situation and circumstance • Furniture's or things which are not correctly positioned may move or be slightly displaced • Slight shaking or vibrations will form on water or liquid surfaces in containers |
| II | <p>Slightly Weak Intensity</p> <ul style="list-style-type: none"> • Can be noticed or felt by people who are resting inside homes • Things that are hanged on walls would slightly sway, shake or vibrate • The shaking or vibrations on water or liquid surfaces in containers would be highly noticeable |
| III | <p>Weak Intensity</p> <ul style="list-style-type: none"> • Can be noticed and felt by more people inside homes or buildings especially those situated at high levels. Some may even feel dizzy. The quake at this stage can be described as if a small truck has passed nearby. • Things that are hanged on walls would sway, shake or vibrate a little more strongly. • The shaking or vibrations on water or liquid surfaces in containers would be more vigorous and stronger |
| IV | <p>Slightly Strong Intensity</p> <ul style="list-style-type: none"> • Can be noticed and felt by most people inside homes and even those outside. Those who are lightly asleep may be awakened. The quake at this stage can be described as if a heavy truck has passed nearby. • Things that are hanged on walls would sway, shake or vibrate strongly. Plates and glasses as well as doors and windows would also vibrate and shake. Floors and walls of wooden houses or structures would slightly squeak. Stationary vehicles would slightly shake. • The shaking or vibrations on water or liquid surfaces in containers would be very strong. It is possible to hear a slight reverberating sound from the environment |
| V | <p>Strong Intensity</p> <ul style="list-style-type: none"> • Can be felt and noticed by almost all people whether they are inside or outside structures. Many will be awakened from sleep and be surprised. Some may even rush out of their homes or buildings in fear. The vibrations and shaking that can be felt inside or outside structures will be very strong. • Things that are hanged on walls would sway, shake or vibrate much more |

| | |
|-------------|--|
| | <p>strongly and intensely. Plates and glasses would also vibrate and shake much strongly and some may even break. Small or light weight objects and furniture would rock and fall off. Stationary vehicles would shake more vigorously.</p> <ul style="list-style-type: none"> • The shaking or vibrations on water or liquid surfaces in containers would be very strong which will cause the liquid to spill over. Plant or tree stem, branches and leaves would shake or vibrate slightly. |
| VI | <p>Very Strong Intensity</p> <ul style="list-style-type: none"> • Many will be afraid of the very strong shaking and vibrations that they will feel, causing them to lose their sense of balance, and most people to run out of homes or building structures. Those who are in moving vehicles will feel as if they are having a flat tire. • Heavy objects or furniture would be displaced from original positions. Small hanging bells would shake and ring. Outer surfaces of concrete walls may crack. Old or fragile houses, buildings or structures would be slightly damaged. • Weak to strong landslides may occur. The shaking and vibrations of plant or tree stem, branches and leaves would be strong and highly noticeable. |
| VII | <p>Damaging Intensity</p> <ul style="list-style-type: none"> • Almost all people will be afraid of the very strong shaking and vibrations. Those who are situated at high levels of buildings will find it very hard to keep standing. • Heavy objects or furniture would fall and topple over. Large hanging bells will sound vigorously. Old or fragile houses, buildings or structures would most definitely be destroyed, while strong or new structures would be damaged. dikes, dams, fishponds, concrete roads and walls may crack and be damaged. • Liquefaction (formation of quicksand), lateral spreading (spreading of soil surface creating deep cracks on land) and landslides will occur. Trees and plants will vigorously shake and vibrate. |
| VIII | <p>Highly Damaging Intensity</p> <ul style="list-style-type: none"> • Will cause confusion and chaos among the people. It makes standing upright difficult even outside homes / structures. • Many big buildings will be extremely damaged. Landslides or lateral spreading will cause many bridges to fall and dikes to be highly damaged. It will also cause train rail tracks to bend or be displaced. Tombs will be damaged or be out of place. Posts, towers and monuments may bend or completely be destroyed. Water and canal/drainage pipes may be damaged, bend, or break. • Liquefaction and lateral spreading causes structures to sink, bend or be completely destroyed, especially those situated on hills and mountains. For places near or situated at the earthquake epicenter, large stone boulders may be thrown out of position. Cracking, splitting, fault rupture of land may be seen. Tsunami-like waves will be formed from water surfaces whether from rivers, ponds or dams/dikes. Trees and plant life will very vigorously move |


| | |
|------------|--|
| | and sway in all directions. |
| IX | <p>Destructive Intensity</p> <ul style="list-style-type: none"> • People would be forcibly thrown/fall down. Chaos, fear and confusion will be extreme. • Most building structures would be destroyed and intensely damaged. Bridges and high structures would fall and be destroyed. Posts, towers and monuments may bend or completely be destroyed. Water and canal/drainage pipes may be damaged, bend, or break. • Landslides, liquefaction, lateral spreading with sand boil (rise of underground mixture of sand and mud) will occur in many places, causing the land deformity. Plant and trees would be damaged or uprooted due to the vigorous shaking and swaying. Large stone boulders may be thrown out of position and be forcibly darted to all directions. Very strong tsunami-like waves will be formed from water surfaces whether from rivers, ponds or dams/dikes. |
| X | <p>Extremely Destructive Intensity</p> <ul style="list-style-type: none"> • Overall extreme destruction and damage of all man-made structures • Widespread landslides, liquefaction, intense lateral spreading and breaking of land surfaces will occur. Very strong and intense tsunami-like waves formed will be destructive. There will be tremendous change in the flow of water on rivers, springs, and other water-forms. All plant life will be destroyed and uprooted. |
| XI | <p>Devastative Intensity</p> <ul style="list-style-type: none"> • Severe damage even to well built buildings, bridges, water dams and railway lines; highways become useless; underground pipes destroyed. |
| XII | <p>Extremely Destructive Intensity (Landscape changes)</p> <ul style="list-style-type: none"> • Practically all structures above and below ground are greatly damaged or destroyed. |

11. ANNEX VI: Example 1: Seismic Evaluation of Reinforced Concrete Moment Resisting Frame Building



1.1 Building Description

| | | |
|--------------------------------|---|--|
| Building Type | : | Residential Building |
| No. of Stories | : | Three |
| Storey Height | : | 3 m |
| Floor/Roof | : | RCC 125 mm thick Slab |
| Parapet Wall Height | : | 1 m |
| Earthquake Zone | : | 1 (NBC 105) |
| | | Seismic Zone V according to IS code |
| Importance Factor | : | 1.0 (Residential Building) |
| Building Dimension | : | 9.0 m X 9.0 m |
| | | Two bay each of 4.5 m span in both direction |
| Lateral load resisting element | : | 9 Columns of 230 mm X 230 mm size reinforced with 4 nos. 16 mm dia vertical bars and 8 mm dia. Stirrups @ 150 mm c/c throughout the length of column |
| | | Beam in every floor is of size 230 mm X 350 mm including slab thickness reinforced with |
| | | 4 nos. 16 mm dia. (Top bars) |
| | | 3 nos. 16 mm dia. (Bottom bars) |
| | | 8 mm dia. Stirrup @ 150 mm c/c throughout |

1.2 Building Drawing




Ground Floor Plan




1st and 2nd Floor Plan




Front Elevation



Side Elevation



Back Elevation



Side Elevation

The following is a sample of quick check calculations based on *FEMA 310* for the seismic evaluation of building and *IITK-GSDMA Guidelines for seismic evaluation and strengthening of buildings*.

1.3 Assumptions:

- Unit weight of RCC = 25 kN/m³
- Unit weight of brick = 19 kN/m³
- Live load = 2.5 kN/m²
- Weight of plaster and floor finish = 1.0 kN/m²
- Grade of concrete = M20 for all other structural elements
- Grade of steel = Fe 415
- Lateral load is solely carried by frame elements. Stiffness of the walls is not considered.

1.4 Calculation for Shear Stress check

Table 6.1.1 Summary of lumped load calculation

| Level | Dead Load | Live load | 25% Live Load | Seismic weight |
|-------|-----------|-----------|---------------|----------------|
| 3 | 659.54 | 121.50 | 30.38 | 689.92 |
| 2 | 833.91 | 202.50 | 50.63 | 884.53 |
| 1 | 833.91 | 202.50 | 50.63 | 884.53 |
| | | | | 2458.98 |

1.5 Calculation of base shear (Using IS 1893: 2002)

The total design lateral force or design seismic base shear is given by

$$V_b = A_h W$$

Where,

W = Seismic weight of the building = 2458.98 kN

A_h = The design horizontal seismic force coefficient = $Z I S_a / 2 R g$

Where A_h will not be taken less than $Z/2$

Z = Zone factor = 0.36 (for Seismic Zone V)

I = Importance factor = 1.0

R = Response Reduction Factor = 3 for Ordinary RC Moment Resisting Frame

S_a/g = Average response acceleration coefficient, that depends upon natural period and damping of the structure

$T_a = 0.09h / \sqrt{d}$ The approximate fundamental natural period of vibration of building in seconds

h = Height of building in m = 9m

d = Base dimension of the building at the plinth level in m along the consideration direction of the lateral force.

When $d = 9.0$ m $T_a = 0.27$ sec

For medium soil

$S_a/g = 2.5$ for $0.10 \leq T \leq 0.55$

$A_h = 0.15$

Base shear $V_b = 368.85$ kN

1.6 Distribution of base shear and calculation of shear stress in RC Columns

The design base shear (V_b) is distributed along the height of the building as per the following expression:

$$Q_i = V_b (W_i h_i / \sum W_i h_i)$$

Where Q_i = Design lateral force at floor i

W_i = Seismic weight of floor i

h_i = Height of floor i measured from base

Table 6.1.2 Base Shear Distribution

| Floor | Total weight W_i (kN) | Height h_i (m) | $W_i h_i$ | Q_i (kN) | Storey Shear V_j (kN) |
|-------|----------------------------|---------------------|-----------|---------------|----------------------------|
| 3 | 689.92 | 9.00 | 6209.24 | 161.63 | 161.63 |
| 2 | 884.53 | 6.00 | 5307.19 | 138.15 | 299.77 |
| 1 | 884.53 | 3.00 | 2653.60 | 69.07 | 368.85 |
| | 3055.02 | | 14170.03 | 368.85 | |

(Using IITK-GSDMA Guidelines for Seismic Evaluation and Strengthening of Buildings, 6.5.1)

Average shearing stress in columns is given as

$$\tau_{col} = (n_c / (n_c - n_f)) * (V_j / A_c) < \min \text{ of } 0.4 \text{ Mpa and } 0.1 \sqrt{f_{ck}}$$

For ground storey columns,

n_c = Total no of columns resisting lateral forces in the direction of loading

n_f = Total no. of frames in the direction of loading

A_c = Summation of the cross-section area of all columns in the storey under consideration

V_j = Maximum storey shear at storey level 'j'

Table 6.1.3 Shear Stress at Storey Levels

| Storey | n_c | n_{f2} | n_{f1} | A_c (m ²) | Storey shears V_j (kN) | Shear stress | |
|--------|-------|----------|----------|----------------------------|-----------------------------|-------------------------|-------------------------|
| | | | | | | $\tau_{col 1}$ (Mpa) | $\tau_{col 2}$ (Mpa) |
| 3.00 | 9.00 | 3.00 | 3.00 | 0.48 | 161.63 | 0.51 | 0.51 |
| 2.00 | 9.00 | 3.00 | 3.00 | 0.48 | 299.77 | 0.94 | 0.94 |
| 1.00 | 9.00 | 3.00 | 3.00 | 0.48 | 368.85 | 1.15 | 1.15 |

But $\tau_{col} > \min \text{ of } 0.4 \text{ Mpa and } 0.1 \sqrt{f_{ck}}$

Hence, the check is not satisfied

1.7 Calculation of Shear capacity of column using capacity design method

Checking Shear Capacity of Center Column

Shear capacity of column required = $1.4(M^l + M^r)/h_{st}$

The Longitudinal Beam of size 230 x 350 is reinforced with 4-16 \varnothing (804 mm², i.e 1.1%) at top and 3-16 (603 mm², i.e 0.83 %) at bottom.

Where,

$b = 230$ mm; $d = 317$ mm

The hogging and sagging moment capacities are evaluated as 76 kN-m and 57 kN-m respectively.

The shear force in column corresponding to these moments

$$V_u = 1.4 (M_u^{bl} + M_u^{br})/h_{st} = 1.4 \times (76 + 57)/3.0 = 62.1 \text{ kN}$$

Center Column is of size 230mm x 230mm

$b = 230$ mm; $d = 192$ mm

$$A_s = 804 \text{ mm}^2 \text{ (4-16}\varnothing\text{)}$$

$$f_{ck} = 20 \text{ N/mm}^2$$

$$f_y = 415 \text{ N/mm}^2;$$

From SP: 16 Table 61, for $P_t = 1.52$ %, $\tau_c = 0.56 \text{ N/mm}^2$

$$\text{Shear capacity of concrete section} = 0.56 * 230 * 230 / 1000 = 29.62 \text{ kN}$$

$$\text{Shear to be carried by stirrups } V_{us} = 62.1 - 29.62 = 32.48 \text{ kN}$$

From table 62, SP -16: for 8mm dia. stirrups @ 150mm c/c

For rectangular stirrups

$$V_{us} / d = 2.42 \text{ kN/cm}$$

$$V_{us} \text{ provided} = 2.42 * 19.2 = 46.5 \text{ kN} > 32.48 \text{ kN}$$

Hence, the check is satisfied for Center Column

1.8 Check for Confining Links in Column

The area of cross section, A_{sh} , of the bar forming rectangular hoop, to be used as special confining reinforcement shall not be less than

$$A_{sh} = 0.18 S h (f_{ck}/f_y) (A_g/A_k - 1) \text{ as per IS 13920: 1993}$$

Where,

h = longer dimension of the rectangular confining hoop measured to its outer face

A_k = area of confined concrete core in the rectangular hoop measured to its outside dimensions.

The size of inner core $h = 230 - 60 + 16 = 186$ (Considering cover of 30mm)

$$A_g = 230 * 230 = 52900$$

$$A_k = 186 * 186 = 34596$$

Hence,

$$50 = 0.18 S 186 (20/415) (52900/34596 - 1.0)$$

$$S \text{ required} = 58.6 \text{ mm}$$

But need not be less than 75 mm

1.9 Axial Stress check

1.9.1 The Axial Stress due to Gravity Loads as per FEMA 310

Permissible axial stress = $0.1 f_c' = 2.0 \text{ N/mm}^2$

The axial stress due to gravity loads in center column Ground Floor = 440KN

The axial stress due to gravity loads in column

= Load on column (N) / Cross section Area of Column

= $440 \times 1000 / (230 \times 230)$

= $8.32 \text{ N/mm}^2 > 2.0 \text{ N/mm}^2$

Hence, the check is not satisfied for Center Column

1.9.2 Axial Stress in Moment Frames

Axial force in columns of moment frames at base due to overturning forces,

$$F_o = 2/3 [V_B/n_f] [H/L]$$

Where,

n_f = Total no. of frames in the direction of loading = 3

V_B = Base shear = 368.85 KN

H = height above the base to the roof level = 9 m

L = Total length of the frame = 9 m

$$F_o = 2/3 [368.85/3] [9/9] = 81.97 \text{ KN}$$

Axial stress $\sigma = 81.97 \times 1000 / 230 / 230 = 1.55 \text{ MPa}$

$$\sigma_{all} = 0.25 f_{ck} = 0.25 \times 20 = 5 \text{ MPa}$$

Therefore,

$$\sigma < \sigma_{all}$$

Hence, the check is satisfied

1.10 Check for Strong Column Weak Beam

1.10.1. Checking Capacity of Center Column at Ground Floor

The Longitudinal Beam of size 230 x 350 is reinforced with 4-16 \varnothing (804 mm², i.e 1.1%) at top and 3-16 (603 mm², i.e 0.83 %) at bottom.

Where,

$$b = 230 \text{ mm}; \quad d = 317 \text{ mm}$$

The hogging and sagging moment capacities are evaluated as 76 kN-m and 57 kN-m respectively.

Factored column axial load = 705 kN ($1.2DL + 1.2LL + 1.2EQL$)

$$P_u / f_{ck} * b * D = (705 \times 1000) / (20 * 230 * 230) = 0.67$$

The column is reinforced with 4-16

$$A_{sc} = 804 \text{ mm}^2; \quad p_t = 1.52\%$$

$$p_t / f_{ck} = 1.52 / 20 = 0.076$$

Using SP-16; Chart 45

Moment carrying capacity of column is negligible as the axial load is very high

$$\Sigma Mb = 76 + 57 = 133 \text{ KN-m} \gg \Sigma Mc$$

Hence, strong column weak beam requirement is not satisfied for Center Column

1.10.2. Checking Capacity of Center Column of Peripheral Frame at Ground Floor

The Longitudinal Beam of size 230 x 350 is reinforced with 4-16 \varnothing (804 mm², i.e 1.1%) at top and 3-16 (603 mm², i.e 0.83 %) at bottom.

Where,

$$b = 230 \text{ mm}; \quad d=317 \text{ mm}$$

The hogging and sagging moment capacities are evaluated as 76 kN-m and 57 kN-m respectively.

Factored column axial load = 500 kN (1.5 DL+1.5EQL)

$$P_u / f_{ck} * b * D = (500 * 1000) / (20 * 230 * 230) = 0.47$$

The column is reinforced with 4-16mm \varnothing

$$A_{sc} = 804 \text{ mm}^2; \quad p_t = 1.52\%$$

$$p_t / f_{ck} = 1.52 / 20 = 0.076$$

Using SP-16; Chart 45

$$M_u / f_{ck} * b * D^2 = 0.075$$

$$M_u = 18.25 \text{ KN-m}$$

$$\Sigma Mb = 133 \text{ KN-m}$$

$$\Sigma Mc = 18.25 + 18.25 = 36.5 \text{ KN-m} \ll 1.1 \Sigma Mb$$

Hence, strong column weak beam requirement is not satisfied for center column of peripheral wall

1.11 Check for Out-of-Plane Stability of Brick Masonry Walls

| Wall type | Wall thickness | Recommended Height/ Thickness ratio (0.24 < Sx ≤ 0.35) | Actual Height/ Thickness ratio in building | Comments |
|-----------------------|----------------|--|--|----------|
| Wall in first storey, | 230 mm | 18 | 2650/230=11.52 | Pass |
| | 115 mm | 18 | 2650/115 = 23.04 | Fail |
| All other walls | 230 mm | 16 | 2650/230=11.52 | Pass |
| | 115mm | 16 | 2650/115 = 23.04 | Fail |

1.12 Pushover Analysis

1.12.1 General

Seismic Evaluation of existing RC Building is generally performed by Pushover Analysis to verify the adequacy of the structural system. Pushover Analysis is the available method which is a simplified method of Non-Linear Static Process. One of the Non-Linear Static Processes is the capacity spectrum method that uses the interaction of the capacity (Pushover) curve and a reduced response spectrum to estimate maximum displacement. This method provides a graphical representation of the global force-

displacement capacity curve of the structure (i.e. Pushover) and compares it to the response spectra representations of the earthquake demand. It is a very useful tool in the evaluation and retrofit design of existing concrete buildings. The procedure help demonstrate how buildings really work by identifying modes of failure and the potential for progressive collapse. In order to provide reliable seismic performance, a building must have a complete lateral force resisting system, capable of limiting earthquake-induced lateral displacements to levels at which the damage sustained by the building's element will be within acceptable levels for the intended performance objective as shown in fig below.




Fig 6.1.1 Typical Capacity Curve

1.12.2 Pushover Analysis of the Building

Pushover Analysis is carried out to determine the structural response of the building. For this, hinge properties for the RC members of the building are calculated using the method given in the book “Reinforced Concrete Structures”, R. Park and T. Paulay. Hinge properties are given in Table 6.1.4 below. References of hinge properties are given in Fig 6.1.2, 6.1.3 and 6.1.4.

Table 6.1.4 Calculated Plastic Hinge Properties for RC Members of the Frame

| Flexural Hinge | Properties | M_y (Negative) (KN.m) | M_y (Positive) (KN.m) | θ_y (rad) | M_u/M_y | θ_u/θ_y |
|------------------|---------------------|----------------------------|----------------------------|------------------|----------------|---------------------|
| | $M-\theta$ Beams | | 87 | 66 | 0.012 | 1.05 |
| $P-M$ Columns | Properties | P_b (KN) | P_c/P_b | P_t/P_b | M_o (KNm) | M_b/M_o |
| | | 420 | 3.2 | 0.79 | 29 | 1.86 |

| | | | | | | |
|-------------|------------------------|------------|--|----------------------|---------------|--|
| Shear Hinge | Properties | V_u (KN) | | Properti es | V_u (KN) | |
| | V- Δ Columns | 87 | | V- Δ Beams | 141 | |
| | | | | | | |




Fig 6.1.2 Typical Axial load Moment (P - M) Hinge Assigned to Column Members




Fig 6.1.3 Typical Moment Rotation (M - θ) Hinge Assigned to Beam Members




Fig 6.1.4 Typical Shear Force Deformation (V- Δ) Hinge Assigned to Beam and Column Members

1.12.3 Results of Pushover Analysis

Capacity Spectrum i.e. spectral acceleration vs. Spectral displacement curve and Base Shear vs. Spectral displacement curve for the building is plotted as shown in Fig. below. Analysis results show that the capacity of the existing building does not meet the seismic demand of the region. Hence retrofitting is recommended for the building under consideration.




Fig 6.1.5 Capacity Spectrum (Comparison of Demand and Capacity Curve)




Fig 6.1.6 Capacity Curve of Existing Building

ANNEX VI: Example 2: Seismic Evaluation of Brick Masonry Building

The analysis and design presented here is approximate and is in very simplified version. The goal of this exercise is just to give an orientation for the retrofit design of unreinforced masonry building.

2.1 Building Description

| | | |
|---------------------|---|---------------------------------------|
| Building Type | : | School Building |
| No. of Stories | : | Two |
| Storey Height | : | 9' 10" (3 m) |
| Wall | : | Brick in 1:5 Cement Sand mortar |
| Floor/Roof | : | RCC 100 mm thick Slab |
| Parapet Wall Height | : | 0.9' (1 m) |
| Earthquake Zone | : | 1 (NBC 105) |
| Importance Factor | : | 1.5 (Educational Building) |
| Building Dimension | : | 29' 9" (9.068 m) X 35' 10" (10.922 m) |

2.2 Design Loads


Dead Loads




| | | |
|--------------|---|----------------------|
| Masonry Wall | : | 19 kN/m ³ |
| RCC Slab | : | 25 kN/m ³ |



Live Loads

| | | |
|-----------------|---|--|
| Floor Live Load | : | 3 kN/m ² (IS : 875 (Part 2) – 1987 Table 1) |
| Roof Live Load | : | 1.5 kN/m ² |

2.3 Building Drawings







2.4 Load Calculation

Table 6.2.1 Unit Weight of the Elements

| S.No | Description | Thk. (m) | Density kN/m ³ | Finishing Thk. (m) | Density kN/m ³ | Intensity kN/m ² |
|------|------------------|----------|---------------------------|--------------------|---------------------------|-----------------------------|
| 1 | Self Wt. of Slab | 0.1 | 25 | 0.05 | 20 | 3.5 |
| 2 | Wall (9" Thk.) | 0.23 | 19 | 0.025 | 20 | 4.87 |

Table 6.2.2 Load Calculation For Ground Floor

| Floor | Description | Wt. | Height | Area (m ²) | Centroid | | WEIGHT (KN) |
|-------|--------------------|----------------------|--------|------------------------|----------|-------|-------------|
| | | (KN/m ³) | H (m) | | X (m) | Y (m) | |
| G.F | Walls | 19 | 3.0 | 12.263 | 4.523 | 5.718 | 699.00 |
| G.F | Walls above window | 19 | 0.6 | 2.967 | 4.447 | 4.359 | 33.82 |
| G.F | slab | 3.5 | | 119.158 | 3.883 | 5.323 | 417.05 |
| G.F | sloped slab | | | | | | |
| G.F | Live Load | 3 | | 119 | | | 357 |
| G.F | Live Load | 3 | | 119 | | | 357 |









Table 6.2.3 Load Calculation For First Floor

| Floor | Description | Wt. | Height | Area | Centroid | | WEIGHT |
|-------|--------------------|----------------------|--------|---------|----------|-------|--------|
| | | (KN/m ³) | H (m) | | X (m) | Y (m) | |
| 1 F | Walls | 19 | 3.00 | 10.890 | 4.870 | 6.353 | 620.75 |
| 1 F | Walls below window | 19 | 0.90 | 1.955 | 6.056 | 5.109 | 33.44 |
| 1 F | Walls above window | 19 | 0.60 | 1.955 | 6.056 | 5.109 | 22.29 |
| 1 F | Parapet wall | 19 | 1.00 | 2.983 | 0.268 | 4.978 | 56.68 |
| 1 F | slab | 3.5 | | 119.158 | 3.883 | 5.323 | 417.05 |
| 1 F | slope slab | | | | | | |





2.5 Lumped Mass Calculation

| Table 6.2.4 Load Calculation for 1st Lump | | | | | |
|--|---------|----------|----------|------------|------------|
| | WEIGHT | <i>X</i> | <i>Y</i> | <i>W*X</i> | <i>W*Y</i> |
| | (KN) | (m) | (m) | (KN-m) | (KN-m) |
| G.F Walls | 349.50 | 4.52 | 5.72 | 1581 | 1998 |
| F.F Walls | 310.38 | 4.87 | 6.35 | 1512 | 1972 |
| GF wall above windows | 33.82 | 4.45 | 4.36 | 150 | 147 |
| FF wall below windows | 33.44 | 6.06 | 5.11 | 202 | 171 |
| Parapet Wall (1st Floor) | 56.68 | 0.27 | 4.98 | 15 | 282 |
| G.F slab | 417.05 | 3.88 | 5.32 | 1619 | 2220 |
| Dead load | 1200.88 | | | 5080 | 6791 |

Live Load (25%)

89.37

Mass Center

4.23 5.65 m

| Table 6.2.5 Load Calculation for 2nd Lump | | | | | |
|--|--------|----------|----------|------------|------------|
| | WEIGHT | <i>X</i> | <i>Y</i> | <i>W*X</i> | <i>W*Y</i> |
| | (KN) | (m) | (m) | (KN-m) | (KN-m) |
| 1F Wall | 310.38 | 4.87 | 6.35 | 1512 | 1972 |

$$T_1 = 0.06 H^{3/4} \quad \text{for concrete frames}$$

(b) For other structures:

$$T_1 = 0.09 H/\sqrt{D}$$

2.7 Quick Calculations for Critical Checks

The following is a sample of quick check calculations based on FEMA 310, IS 1893: 2002 & Using IITK-GSDMA Guidelines for Seismic Evaluation and Strengthening of Buildings for the seismic evaluation of building under consideration.

2.7.1. Calculation for Shear Stress check

2.7.1.1 Summary of Lumped Load Calculation

Table 6.2.6 Lumped Weights of the Building at the Storey Levels

| Storey | Dead Load (kN) | 25% of Live Load (kN) | Total W_i (kN) |
|-----------|----------------|-----------------------|------------------|
| 2 | 749.72 | 0 | 749.72 |
| 1 | 1200.88 | 89.37 | 1290.25 |
| Summation | | | 2039.50 |

2.7.1.2 Calculation of Seismic Base Shear (Using IS 1893: 2002)

The total design lateral force or design seismic base shear is given by

$$V_b = A_h W$$

Where,

$$A_h = \text{design horizontal seismic coefficient} = (ZI/2R) * (S_a/g)$$

d = Base dimension of the building at the plinth level in m = 9.07 m and 10.92 m

h = Height of building in m, = 6m

$$T = 0.09 * h / d^{0.5} = 0.18 \text{ sec for } d = 9.07 \text{ m}$$

$$= 0.16 \text{ sec for } d = 10.92 \text{ m}$$

$S_a/g = 2.5$ (for soft soil, $0.1 \leq T \leq 0.55$)

Z = Seismic zone factor = 0.36

I = Importance factor = 1.5 (For Educational Building)

R = Response reduction factor = 1.5; Unreinforced load bearing masonry wall building

Hence, $A_h = (0.36 \times 1.5 \times 2.5) / (2 \times 1.5) = 0.45$ kN and

For the Assumed Building,

Using NBC Code,

$Z = 1$ (zone 1)

$I = 1.5$ (Educational Building)

$$T = (0.09 \times H) / (D^{0.5}) = (0.09 * 6) / (9.068^{0.5}) = 0.18$$

$C = 0.08$ for Subsoil Type III

$K = 4$ (for structures of minimal ductility)

$$C_d = CZIK = 0.08 \times 1.5 \times 1 \times 4 = 0.48$$

Now let us take Base Shear Coefficient $A_h = 0.45$

Total Base Shear $V_b = 2039.50 \times 0.45 = 917.78 \text{ kN}$

Here, Linear Distribution of Base Shear is adopted as per NBC Code,

i.e. $Q_i = V_b \times [W_i h_i / \sum W_i h_i]$

Where Q_i = Design lateral force at floor i

W_i = Seismic weight of floor i

h_i = Height of floor i measured from base

Table 6.2.7 Storey Shears at Different Stories of the Building

| Storey | Total W_i (kN) | H_i (m) | $W_i h_i$ (kN m) | Q_i (kN) | Storey Shear (kN) |
|-----------|------------------|-----------|------------------|------------|-------------------|
| 2 | 749.72 | 6 | 4498.32 | 493.42 | 493.42 |
| 1 | 1290.25 | 3 | 3870.75 | 424.58 | 917.78 |
| Summation | 2039.50 | | 8369.07 | 917.78 | |

(Using IITK-GSDMA Guidelines for Seismic Evaluation and Strengthening of Buildings, 6.5.1)

Shear stress in Shear walls is given as

$$\tau_{wall} = (V_j/A_w)$$

For unreinforced masonry load bearing wall building, the average shear stress, τ_{wall} shall be less than 0.1 Mpa

Where

V_j = Storey shear for piers

A_w = Area of shear wall in the direction of the loading

Average Shear stress in X direction walls

| Storey | Storey Shear (V_j) KN | Area of Shear Wall (A_w) Sq.m | Stresses N/mm ² |
|--------|------------------------------|--------------------------------------|-------------------------------|
| 1 | 917.78 | 7.010 | 0.13 |

Average Shear stress in Y direction walls

| Storey | Storey Shear (V_j) KN | Area of Shear Wall (A_w) Sq.m | Stresses N/mm ² |
|--------|------------------------------|--------------------------------------|-------------------------------|
| 1 | 917.78 | 6.010 | 0.15 |

Hence, the check is not satisfied. (As $\tau_{wall} > 0.1 \text{ Mpa}$)

2.7.2. Check for Torsion

2.7.2.1 Checking Eccentricity between Centre of Mass and Centre of Stiffness at Ground Floor

Table 6.2.8 Calculation of Stiffness Center (Walls Along Dir. X)

| Col No. | Col ID | D (mm) | B (mm) | Area (mm ²) | I _{yy} (mm ⁴) | Y _i (mm) | I _y * Y _i | $K_{ey} = (12EI/H^3) / (1+3D^2/H^2)$ | K _{ey} * Y _i |
|-------------|-----------|--------|--------|-------------------------|------------------------------------|---------------------|---------------------------------|--------------------------------------|----------------------------------|
| 1 | Rect. - 1 | 9068 | 229 | 2076572 | 1.423E+13 | 10807.5 | 1.538E+17 | 4977529.351 | 5.3795E+10 |
| 2 | Rect. - 2 | 3835 | 229 | 878215 | 1.076E+12 | 7226.5 | 7.778E+15 | 1812217.714 | 1.3096E+10 |
| 3 | Rect. - 3 | 4318 | 229 | 988822 | 1.536E+12 | 7226.5 | 1.11E+16 | 2116180.012 | 1.5293E+10 |
| 4 | Rect. - 4 | 3835 | 229 | 878215 | 1.076E+12 | 3670.5 | 3.951E+15 | 1812217.714 | 6651745119 |
| 5 | Rect. - 5 | 4318 | 229 | 988822 | 1.536E+12 | 3670.5 | 5.639E+15 | 2116180.012 | 7767438733 |
| 6 | Rect. - 6 | 1041 | 229 | 238389 | 2.153E+10 | 114.5 | 2.465E+12 | 157168.3707 | 17995778.5 |
| 7 | Rect. - 7 | 1270 | 229 | 290830 | 3.909E+10 | 114.5 | 4.476E+12 | 252639.8734 | 28927265.5 |
| 8 | Rect. - 8 | 1435 | 229 | 328615 | 5.639E+10 | 114.5 | 6.457E+12 | 332304.6978 | 38048887.9 |
| 9 | Rect. - 9 | 1359 | 229 | 311211 | 4.79E+10 | 114.5 | 5.484E+12 | 294619.0231 | 33733878.1 |
| Summation = | | | | 6979691 | 1.962E+13 | | 1.823E+17 | 13871056.77 | 9.6721E+10 |

Stiffness Center Y = 6972.872 mm

E = 22360 N/mm²

H = 3000 mm




Table 6.2.9 Calculation of Stiffness Center (Walls Along Dirⁿ. Y)


| Col No. | Col ID | B (mm) | D (mm) | Area (mm ²) | I _{xx} (mm ⁴) | X _i (mm) | I _x * X _i | $K_{ex} = (12EI/H^3) / (1+3D^2/H^2)$ | K _{ex} * X _i |
|---------|-----------|--------|--------|-------------------------|------------------------------------|---------------------|---------------------------------|--------------------------------------|----------------------------------|
| 1 | Rect. - 1 | 229 | 1143 | 261747 | 2.85E+10 | 114.5 | 3.263E+12 | 197280.4977 | 22588617 |
| 2 | Rect. - 2 | 228 | 2667 | 608076 | 3.604E+11 | 4864 | 1.753E+15 | 1062570.962 | 5.168E+09 |
| 3 | Rect. - 3 | 229 | 1067 | 244343 | 2.318E+10 | 8953.5 | 2.076E+14 | 166999.9054 | 1.495E+09 |
| 4 | Rect. - 4 | 229 | 2077 | 475633 | 1.71E+11 | 114.5 | 1.958E+13 | 696985.1444 | 79804799 |
| 5 | Rect. - 5 | 229 | 2642 | 602376 | 3.504E+11 | 3721 | 1.304E+15 | 1046706.446 | 3.895E+09 |

| | | | | | | | | | |
|-------------|------------|-----|------|---------|-----------|--------|-----------|-------------|-----------|
| 6 | Rect. - 6 | 229 | 2083 | 477007 | 1.725E+11 | 8953.5 | 1.544E+15 | 700651.8336 | 6.273E+09 |
| 7 | Rect. - 7 | 229 | 2642 | 602376 | 3.504E+11 | 4864 | 1.704E+15 | 1046706.446 | 5.091E+09 |
| 8 | Rect. - 8 | 229 | 1835 | 420215 | 1.179E+11 | 114.5 | 1.35E+13 | 552106.3994 | 63216183 |
| 9 | Rect. - 9 | 229 | 2439 | 556092 | 2.757E+11 | 3721 | 1.026E+15 | 918414.1572 | 3.417E+09 |
| 10 | Rect. - 10 | 229 | 2133 | 488457 | 1.852E+11 | 8953.5 | 1.658E+15 | 731321.3911 | 6.548E+09 |
| 11 | Rect. - 11 | 229 | 1295 | 296555 | 4.144E+10 | 114.5 | 4.745E+12 | 264182.707 | 30248920 |
| 12 | Rect. - 12 | 229 | 432 | 98496 | 1.532E+09 | 3721 | 5.7E+12 | 14331.26592 | 53326640 |
| 13 | Rect. - 13 | 229 | 2616 | 596448 | 3.401E+11 | 4864 | 1.654E+15 | 1030219.465 | 5.011E+09 |
| 14 | Rect. - 14 | 229 | 1067 | 244343 | 2.318E+10 | 8953.5 | 2.076E+14 | 166999.9054 | 1.495E+09 |
| Summation = | | | | 5972164 | 2.441E+12 | | 1.111E+16 | 8595476.527 | 3.864E+10 |

Stiffness Center $X = 4495.8$ mm

$E = 22360$ N/mm²

$H = 3000$ mm



Now,

The Location of centre of stiffness at ground floor $CS (K_x, K_y) = (4.49$ m, 6.97 m)

2.7.2.2 Calculation of Mass Center

Referring the calculation done in table 6.2.4,

Lumped mass in Ground Floor (M_1) = 1200.88 kN

Mass Center in that storey $X_1 = 4.32$ m

Mass Center in that storey $Y_1 = 5.65$ m

Similarly, referring the calculation done in table 6.2.5,

Lumped mass in First Floor (M_2) = 749.72 kN

Mass Center in that storey $X_2 = 4.36$ m

Mass Center in that storey $Y_2 = 5.74$ m

Now, Effective Mass Center can be calculated as,

$$\begin{aligned} X_{eff} = \Sigma M x X / \Sigma M &= [M_1 x X_1 + M_2 x X_2] / (M_1 + M_2) \\ &= [1200.88 x 4.32 + 749.72 x 4.36] / (1200.88 + 749.72) \\ &= 4.33 \text{ m} \end{aligned}$$

Similarly,

$$\begin{aligned} Y_{eff} = \Sigma M x Y / \Sigma M &= [M_1 x Y_1 + M_2 x Y_2] / (M_1 + M_2) \\ &= [1200.88 x 5.65 + 749.72 x 5.74] / (1200.88 + 749.72) \\ &= 5.68 \text{ m} \end{aligned}$$

Location of effective mass center at ground floor (W_x, W_y) = (4.33 m, 5.68 m)

Calculated eccentricity along X direction $e_x = |4.49 - 4.33| = 0.16$ m

Calculated eccentricity along Y direction, $e_y = |6.97 - 5.68| = 1.29$ m

Permissible eccentricity along X direction e_x (30% of 9.07 m length along X -dir) = 2.72 m

Permissible eccentricity along Y direction, e_y (30% of 10.92 m length along Y -dir) = 3.27 m

Hence, the check is satisfied.


2.8 Stress Calculation of the building

2.8.1 Out of Plane Bending of the Wall,

Here, Linear Distribution of Base Shear is adopted as per NBC Code,

$$\text{i.e. } Q_i = V_b X [W_i h_i / \Sigma W_i h_i]$$

Referring table 6.2.4,



Lateral coefficient in 2nd storey,

$$C = 493.42/749.72 = 0.63 > 0.45$$

Lateral coefficient in 1st storey,

$$C = 424.58/1290.25 = 0.33 < 0.45$$

Check Stress for, $C = 0.66$ in the 2nd storey

Special care should be taken for upper storey walls, particularly the top one.

2.8.2 Stress check at Lintel Level

The stress is checked for the horizontal bending of the wall,

Maximum Span of wall in the building = 5 m

Wall below lintel level = 2.2 m

Load carried by the lintel level band,

$$q = (2.2/2 + 0.8/2) \times 4.87 \times 0.63 = 4.6 \text{ kN/m}$$

Bending Moment,

$$M = wl^2/10 = 4.6 \times 5^2/10 = 11.5 \text{ kN m}$$

So a bandage is required to resist the calculated moment in the lintel level of the wall.


2.8.3 Stress check below Lintel Level,

Let us consider the unit width of the wall,

$$\text{Lateral load} = 1 \times 4.87 \times 0.63 = 3.07 \text{ kN/m}$$

$$M = wl^2/12 = 3.07 \times 2.2^2/12 = 1.24 \text{ kNm/m strip}$$

$$\text{Bending Stress, } f_b = M/Z$$



$$= 1.24 \times 10^6 / (230^2 \times 1000 / 6)$$

$$= 0.14 \text{ MPa}$$

Vertical load on wall at mid height of wall below

Lintel level,

$$= (2.2/2 + 0.8) \times 4.87 + 4.77 \times 3.5 \quad (\text{wall+slab})$$

$$= 25.94 \text{ kN}$$

Slab trapezoidal load is considered,

$$\text{Slab Area} = (4.521 + (4.521 - 3.353)) \times (3.353/2) / 2 = 4.77 \text{ m}^2$$

$$\text{Stress due to Vertical Load } f_a = 4.77 \times 1000 / (4521 \times 230) = 0.0046 \text{ MPa}$$

Combined Vertical Stress on the Wall,

$$f = f_a + f_b \text{ and } f_a - f_b$$

$$= 0.14 + 0.0046 = 0.1446 \text{ (Compression)}$$

$$= 0.14 - 0.0046 = 0.1354 \text{ (Tension)}$$

Permissible Bending Stress for $M_f = 0.07 \text{ N/mm}^2$

As the tensile stress exceeds the permissible value, some extra bandage should be provided below the lintel level also.

2.8.4 In-plane Analysis of the Piers

Effect of cross walls is ignored in pier analysis. It can be incorporated by considering effective areas of piers at L or T sections. The commonly used rules for establishing flange width of L or T section can be used in the case.

The analyses have been done without the consideration of the torsion. However most of the buildings are *torsionally* active and it is strongly advised to analyze the buildings considering torsion as well.

As the floor is the rigid RCC slab so due to rigid diaphragm action, it is assumed that the loads are distributed proportionate to the stiffness of the pier sections. It is also assumed that, the effective height of the pier section will be the equivalent height of the door or window whichever is present in that pier section.

Table 6.2.10 Pier Analysis (In Direction X)

| Pier No. | Length | width | Height | Area | M_f | Stiffness | Prop. | Lateral Load | M | Z | $F_b = M/Z$ |
|----------|--------|-------|--------|-------|--------|-----------|-------|--------------|--------|-------|-------------|
| P1 | 9.068 | 0.23 | 3 | 2.086 | 14.292 | 0.277 | 0.294 | 269.453 | 404.18 | 3.152 | 0.13 |
| P2 | 3.835 | 0.23 | 3 | 0.882 | 1.081 | 0.098 | 0.103 | 94.944 | 142.42 | 0.564 | 0.25 |
| P3 | 4.318 | 0.23 | 3 | 0.993 | 1.543 | 0.115 | 0.122 | 111.695 | 167.54 | 0.715 | 0.23 |
| P4 | 3.835 | 0.23 | 3 | 0.882 | 1.081 | 0.098 | 0.103 | 94.944 | 142.42 | 0.564 | 0.25 |
| P5 | 4.318 | 0.23 | 3 | 0.993 | 1.543 | 0.115 | 0.122 | 111.695 | 167.54 | 0.715 | 0.23 |
| P6 | 1.041 | 0.23 | 1.37 | 0.239 | 0.022 | 0.042 | 0.045 | 41.138 | 28.18 | 0.042 | 0.68 |
| P7 | 1.27 | 0.23 | 1.37 | 0.292 | 0.039 | 0.060 | 0.063 | 58.191 | 39.86 | 0.062 | 0.64 |
| P8 | 1.435 | 0.23 | 1.37 | 0.330 | 0.057 | 0.073 | 0.077 | 70.759 | 48.47 | 0.079 | 0.61 |
| P9 | 1.359 | 0.23 | 1.37 | 0.313 | 0.048 | 0.067 | 0.071 | 64.956 | 44.49 | 0.071 | 0.63 |
| Sum | | | | | | 0.944 | 1.000 | 917.775 | | | |




Table 6.2.11 Overturning Moment

| Piers | Centroid | M_I | Propor. | $Q1$ | $Q2$ | M |
|----------------|----------|-------|---------|--------|--------|---------|
| Pier in Grid 4 | 4.534 | 14.29 | 0.27 | 116.31 | 135.08 | 1159.43 |
| Pier in Grid 3 | 4.555 | 14.21 | 0.27 | 115.63 | 134.29 | 1152.60 |
| Pier in Grid 2 | 4.555 | 14.21 | 0.27 | 115.63 | 134.29 | 1152.60 |
| Pier in Grid 1 | 4.672 | 9.47 | 0.18 | 77.06 | 89.50 | 768.15 |
| Summation | | 52.17 | 1 | 424.62 | 493.15 | |

| Piers | Pier Section | | | | | | | |
|----------------|--------------|-------|-------|-------|-------|-------|-------|-------|
| | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 |
| Pier in Grid 4 | -0.36 | -0.36 | -0.36 | -0.36 | -0.36 | -0.36 | -0.36 | -0.36 |
| Pier in Grid 3 | -0.36 | -0.36 | -0.36 | -0.36 | -0.36 | -0.36 | -0.36 | -0.36 |
| Pier in Grid 2 | -0.36 | -0.36 | -0.36 | -0.36 | -0.36 | -0.36 | -0.36 | -0.36 |
| Pier in Grid 1 | -0.36 | -0.36 | -0.36 | -0.36 | -0.36 | -0.36 | -0.36 | -0.36 |

Table 6.2.12 Vertical Stresses

| Piers | Wall Load | Openings | Wall Load | Slab | Roof Slab | Slab Load | Total (kN) | f_a (Mpa) |
|----------------|-----------|----------|-----------|-------|-----------|-----------|------------|-------------|
| Pier in Grid 4 | 61.66 | 0.00 | 300.30 | 11.65 | 11.65 | 81.52 | 381.82 | 0.18 |
| Pier in Grid 3 | 52.59 | 3.84 | 237.44 | 23.29 | 23.29 | 163.04 | 400.48 | 0.21 |
| Pier in Grid 2 | 52.59 | 3.84 | 237.44 | 23.29 | 23.29 | 163.04 | 400.48 | 0.21 |
| Pier in Grid 1 | 61.66 | 8.04 | 261.15 | 11.65 | 11.65 | 81.52 | 342.67 | 0.29 |

Table 6.2.13 Combination of Stresses at the Bottom of Pier

| Grid | End | Bending | Overturn | Vertical | Net Stress | X | Total T |
|--------|-------|---------|----------|----------|------------|---------|-----------|
| Grid 4 | A | -0.13 | -0.37 | -0.18 | -0.68 | 2860.73 | 102967.11 |
| | B | 0.13 | 0.37 | -0.18 | 0.31 | | |
| Grid 3 | A | -0.25 | -0.37 | -0.21 | -0.83 | 246.77 | 660.76 |
| | and B | 0.25 | -0.02 | -0.21 | 0.02 | | |
| Grid 2 | C | -0.23 | 0.06 | -0.21 | -0.39 | 2161.12 | 97015.34 |
| | D | 0.23 | 0.37 | -0.21 | 0.39 | | |
| Grid 1 | A | -0.68 | -0.36 | -0.29 | -1.33 | 99.47 | 1603.62 |
| | B | 0.68 | -0.25 | -0.29 | 0.14 | | |
| | C | -0.64 | -0.12 | -0.29 | -1.06 | 313.10 | 12479.60 |
| | D | 0.64 | -0.01 | -0.29 | 0.35 | | |
| | E | -0.61 | 0.07 | -0.29 | -0.84 | 531.59 | 30144.51 |
| | F | 0.61 | 0.17 | -0.29 | 0.49 | | |
| | G | -0.63 | 0.29 | -0.29 | -0.63 | 725.02 | 59667.93 |
| | H | 0.63 | 0.38 | -0.29 | 0.72 | | |

Table 6.2.14 Pier Analysis (In Direction Y)

| Pier No. | Length | width | Height | Area | M_t | Stiffness | Prop. | Lateral Load | M | Z | $F_b=M/Z$ |
|----------|--------|-------|--------|-------|-------|-----------|-------|--------------|--------|-------|-----------|
| P1 | 1.143 | 0.23 | 1.37 | 0.263 | 0.029 | 0.050 | 0.062 | 56.783 | 38.90 | 0.050 | 0.78 |
| P2 | 2.667 | 0.23 | 2.134 | 0.613 | 0.364 | 0.095 | 0.117 | 107.341 | 114.53 | 0.273 | 0.42 |
| P3 | 1.059 | 0.23 | 1.37 | 0.244 | 0.023 | 0.044 | 0.054 | 49.550 | 33.94 | 0.043 | 0.79 |
| P4 | 2.077 | 0.23 | 1.37 | 0.478 | 0.172 | 0.123 | 0.152 | 139.635 | 95.65 | 0.165 | 0.58 |
| P5 | 2.642 | 0.23 | 2.134 | 0.608 | 0.353 | 0.093 | 0.115 | 105.910 | 113.01 | 0.268 | 0.42 |
| P6 | 2.083 | 0.23 | 1.37 | 0.479 | 0.173 | 0.123 | 0.153 | 140.162 | 96.01 | 0.166 | 0.58 |
| P7 | 2.642 | 0.23 | 2.134 | 0.608 | 0.353 | 0.093 | 0.115 | 105.910 | 113.01 | 0.268 | 0.42 |
| P8 | 1.835 | 0.23 | 1.37 | 0.422 | 0.118 | 0.104 | 0.129 | 118.263 | 81.01 | 0.129 | 0.63 |

| | | | | | | | | | | | |
|-----|-------|------|-------|-------|-------|-------|-------|---------|--------|-------|------|
| P9 | 2.438 | 0.23 | 2.134 | 0.561 | 0.278 | 0.083 | 0.103 | 94.221 | 100.53 | 0.228 | 0.44 |
| P10 | 2.134 | 0.23 | 1.37 | 0.491 | 0.186 | 0.127 | 0.158 | 144.637 | 99.08 | 0.175 | 0.57 |
| P11 | 1.295 | 0.23 | 1.37 | 0.298 | 0.042 | 0.062 | 0.076 | 70.138 | 48.04 | 0.064 | 0.75 |
| P12 | 0.432 | 0.23 | 2.134 | 0.099 | 0.002 | 0.002 | 0.002 | 1.972 | 2.10 | 0.007 | 0.29 |
| P13 | 2.616 | 0.23 | 2.134 | 0.602 | 0.343 | 0.092 | 0.114 | 104.422 | 111.42 | 0.262 | 0.42 |
| P14 | 1.067 | 0.23 | 1.37 | 0.245 | 0.023 | 0.044 | 0.055 | 50.232 | 34.41 | 0.044 | 0.79 |
| Sum | | | | | | 0.808 | 1.000 | 917.775 | | | |

Table 6.2.15 Overturning Moment

| Piers | Centroid | M_I | Propor. | $Q1$ | $Q2$ | M |
|----------------|----------|----------|---------|--------|--------|---------|
| Pier in Grid A | 5.416 | 16.37171 | 0.25 | 107.15 | 124.44 | 1068.10 |
| Pier in Grid B | 3.350 | 11.04113 | 0.17 | 72.26 | 83.92 | 720.33 |
| Pier in Grid C | 5.323 | 21.98968 | 0.34 | 143.92 | 167.14 | 1434.62 |
| Pier in Grid D | 5.449 | 15.47732 | 0.24 | 101.29 | 117.64 | 1009.75 |
| Summation | | 64.87984 | 1 | 424.62 | 493.15 | |

| Piers | Pier Section | | | | | | | |
|----------------|--------------|------|------|-------|-------|-------|-------|-------|
| | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 |
| Pier in Grid A | 0.35 | 0.27 | 0.17 | 0.05 | -0.05 | -0.19 | -0.28 | -0.36 |
| Pier in Grid B | 0.22 | 0.19 | 0.13 | -0.03 | -0.09 | -0.26 | | |
| Pier in Grid C | 0.35 | 0.18 | 0.11 | -0.06 | -0.19 | -0.37 | | |
| Pier in Grid D | 0.36 | 0.29 | 0.19 | 0.05 | -0.05 | -0.19 | -0.29 | -0.36 |

Table 6.2.16 Vertical Stresses

| Piers | Wall Load | Openings | Wall Load | Slab | Roof Slab | Slab Load | Total (kN) | f_a (Mpa) |
|----------------|-----------|----------|-----------|-------|-----------|-----------|------------|-------------|
| Pier in Grid A | 74.27 | 12.60 | 300.33 | 17.29 | 17.29 | 121.05 | 421.38 | 0.31 |
| Pier in Grid B | 41.91 | 11.52 | 148.02 | 21.77 | 21.77 | 152.36 | 300.38 | 0.24 |
| Pier in Grid C | 63.35 | 11.52 | 252.42 | 21.77 | 21.77 | 152.36 | 404.77 | 0.22 |
| Pier in Grid D | 74.27 | 12.60 | 300.33 | 17.29 | 17.29 | 121.05 | 421.38 | 0.29 |

Table 6.2.17 Combination of Stresses at the Bottom of Pier

| Grid | End | Bending | Overturn | Vertical | Net Stress | x | Total T |
|--------|-----|---------|----------|----------|------------|--------|-----------|
| Grid A | 1 | -0.75 | -0.36 | -0.31 | -1.42 | 125.25 | 2186.22 |
| | 2 | 0.75 | -0.28 | -0.31 | 0.15 | | |
| | 3 | -0.63 | -0.19 | -0.31 | -1.12 | 248.65 | 7635.71 |

| | | | | | | | |
|--------|---|-------|-------|-------|-------|-------------------|----------|
| | 4 | 0.63 | -0.05 | -0.31 | 0.27 | | |
| | 5 | -0.58 | 0.05 | -0.31 | -0.84 | 447.81 | 22735.30 |
| | 6 | 0.58 | 0.17 | -0.31 | 0.44 | | |
| | 7 | -0.78 | 0.27 | -0.31 | -0.82 | 647.68 | 61013.35 |
| | 8 | 0.78 | 0.35 | -0.31 | 0.82 | | |
| Grid B | 1 | -0.29 | -0.26 | -0.24 | -0.79 | (No Tension Zone) | |
| | 2 | 0.29 | -0.09 | -0.24 | -0.03 | | |
| | 3 | -0.44 | -0.03 | -0.24 | -0.71 | 416.58 | 16050.43 |
| | 4 | 0.44 | 0.13 | -0.24 | 0.34 | | |
| | 5 | -0.42 | 0.19 | -0.24 | -0.47 | 599.32 | 27841.33 |
| | 6 | 0.42 | 0.22 | -0.24 | 0.40 | | |
| Grid C | 1 | -0.42 | -0.37 | -0.22 | -1.01 | 14.36 | 18.73 |
| | 2 | 0.42 | -0.19 | -0.22 | 0.01 | | |
| | 3 | -0.42 | -0.06 | -0.22 | -0.71 | 392.29 | 13898.90 |
| | 4 | 0.42 | 0.11 | -0.22 | 0.31 | | |
| | 5 | -0.42 | 0.18 | -0.22 | -0.47 | 698.55 | 43800.92 |
| | 6 | 0.42 | 0.35 | -0.22 | 0.55 | | |
| Grid D | A | -0.79 | -0.36 | -0.29 | -1.43 | 167.99 | 4124.99 |
| | B | 0.79 | -0.29 | -0.29 | 0.21 | | |
| | C | -0.57 | -0.19 | -0.29 | -1.04 | 232.52 | 6102.48 |
| | D | 0.57 | -0.05 | -0.29 | 0.23 | | |
| | E | -0.58 | 0.05 | -0.29 | -0.82 | 476.97 | 26136.71 |
| | F | 0.58 | 0.19 | -0.29 | 0.48 | | |
| | G | -0.79 | 0.29 | -0.29 | -0.79 | 673.80 | 66468.65 |
| | H | 0.79 | 0.36 | -0.29 | 0.86 | | |

**Seismic Vulnerability Evaluation Guideline for
Private and Public Buildings**
(Part II: Post-disaster damage assessment)

Table of Contents

| | | |
|-------|--|----|
| 1. | Introduction..... | 1 |
| 1.1 | Purpose..... | 1 |
| 1.2 | Basis and Scope | 1 |
| 1.3 | Guideline Dissemination..... | 1 |
| 2. | Damage Assessment Process | 2 |
| 2.1 | General..... | 2 |
| 2.2 | Human Resources | 3 |
| 3. | Rapid Evaluation..... | 4 |
| 3.1 | General..... | 4 |
| 3.2 | Safety Precaution | 4 |
| 3.3 | Steps for Rapid Evaluation | 5 |
| 3.4 | Posting Safety Status..... | 7 |
| 3.4.1 | Inspected | 7 |
| 3.4.2 | Limited Entry or Restricted Use | 8 |
| 3.4.3 | Unsafe | 9 |
| 3.5 | Limitations of Rapid Evaluation | 10 |
| 4. | Detail Evaluation | 10 |
| 4.1 | Understanding the Characteristics of Damaging Earthquake | 10 |
| 4.2 | Review of Existing Building Data | 11 |
| 4.3 | Assessing the Consequences of the Damaging Earthquake | 11 |
| 4.4 | Assessing Pre-existing Conditions..... | 11 |
| 4.5 | Survey the Building from Outside | 12 |
| 4.6 | Examine the site for Geotechnical Hazards | 12 |
| 4.7 | Inspect the structural system from inside the building..... | 12 |
| 4.8 | Inspect the Buildings in Critical Locations..... | 13 |
| 4.8.1 | Earthquake Damage Patterns in Masonry Buildings | 13 |

| | | |
|----------|---|----|
| 4.8.1.1 | Corner Separation | 13 |
| 4.8.1.2 | Diagonal Cracking | 13 |
| 4.8.1.3 | Out of Plane Failure flexural failure | 16 |
| 4.8.1.4 | In-plane flexural failure | 18 |
| 4.8.1.5 | Delamination of Walls | 21 |
| 4.8.2 | Earthquake Damage Patterns in Reinforced Concrete Frame Buildings | 22 |
| 4.8.2.1 | Beam-Column Joint Failure | 22 |
| 4.8.2.2 | Lap-splice Damage | 23 |
| 4.8.2.3 | Short Column Damage..... | 24 |
| 4.8.2.4 | Soft-story damage | 25 |
| 4.8.2.5 | Shear/flexure cracks in column and beam members..... | 27 |
| 4.8.2.6 | Damage to Infill-Wall | 28 |
| 4.9 | Conduct Test | 29 |
| 4.9.1 | Sounding Test | 29 |
| 4.9.2 | Rebar Detection Test..... | 31 |
| 4.9.3 | In-Situ Testing In-Place Shear | 33 |
| 4.10 | Detail Evaluation | 34 |
| 4.11 | Identification of Damage Levels..... | 35 |
| 4.11.1.1 | Earthquake damage grades of Masonry buildings with flexible floor and roof..... | 35 |
| 4.11.1.2 | Earthquake damage grades of Masonry buildings with rigid floor and roof..... | 37 |
| 4.11.1.3 | Earthquake damage grades of Reinforced Concrete Buildings..... | 39 |
| 5. | References..... | 42 |
| | ANNEXES | 44 |
| | Annex I: Examples of Rapid Evaluation..... | 44 |
| | Annex II: Examples of Detailed Evaluated Buildings | 46 |
| | Annex III: Rapid Evaluation Form | 47 |
| | Annex IV: Detail Evaluation Form..... | 48 |

1. Introduction

1.1 Purpose

The purpose of this document is to provide practical criteria and guidance for evaluating earthquake damage to buildings with primary lateral-force-resisting systems consisting of reinforced concrete frame and masonry buildings which are prevalent in Nepal. The procedures in this manual are intended to characterize the observed damage caused by the earthquake in terms of the loss in building performance capability. The intended users of this document are primarily practicing engineers with experience in concrete and masonry design and construction with basic understanding of earthquake resistant design and construction. Information in this document also may be useful to building owners, and government agencies. However the users should consult with a qualified engineer for interpretation or specific application of this document.

1.2 Basis and Scope

The evaluation procedure assumes that when an earthquake causes damage to a building, a competent engineer can assess the effects, at least partially, through visual inspection augmented by investigative tests, structural analysis, and knowledge of the building construction. By determining how the structural damage has changed structural properties, it is feasible to develop potential actions (performance restoration measures) that, if implemented, would restore the damaged building to a condition such that its future earthquake performance would be essentially equivalent to that of the building in its pre-event condition. The costs associated with these conceptual performance restoration measures quantify the loss associated with the earthquake damage.

The theoretical basis of this guideline is based on different documents from *Federal Emergency Management Agency* (FEMA) and Applied Technology Council (ATC) namely ATC 20, FEMA 154, FEMA 273, FEMA 274, FEMA 306, FEMA 307, FEMA 308, FEMA 356, ATC 40 etc and the experience of damage assessment of the buildings after *Kashmir* earthquake in Pakistan.

There are four levels of damage assessment:

- Windshield: Overall scope of damage
- Rapid : Assessment sufficient for most buildings
- Detailed: Closer assessment of difficult or complex buildings
- Engineering : Consultant engaged by owner

This guideline covers the rapid and detailed assessment procedures. Process for windshield will be different as it is the overall damage assessment from air i.e. helicopter survey, the last one needs quantitative assessment of individual buildings.

The damage assessment methodology suggested in this guideline is not for grant distribution but different grades of damage identified after detail evaluation can be utilized as a basis for grant dispersion also.

1.3 Guideline Dissemination

The guideline has the potential to improve the situation of earthquake disaster affected area through proper planning if appropriately implemented by concerned authorities. This guideline should reach to engineers and practitioners who are working in the field of construction and disaster and make use of the document effectively and efficiently.

However, distribution of printed guidelines alone has been shown to be ineffective in achieving change in practice. Guidelines are more likely to be effective if they are disseminated by means of an active education. Hence, training for guideline users should be carried out in parallel so that they are in a position to better understand the issue and make best use of the guidelines.

Guidelines must obviously be made as widely available as possible in order to facilitate implementation. It is necessary to have wide circulations among engineers and practitioners working in the field of earthquake engineering. It thus requires an integrated effort by the concerned authorities like local government, municipalities, NGO's, INGO's and other related organisations towards dissemination of publication in wider range.

Further dissemination and implementation of a guideline should be monitored and evaluated. The guideline also needs thorough review by experts in the field. This should undergo mandatory updating procedure to transform it into pre-standard and then to building standard.

2. Damage Assessment Process

2.1 General

This system of overall safety evaluation of earthquake damaged buildings is based on experience of such assessment in Pakistan after *Kashmir* earthquake. The purpose of rapid evaluation is similar to ATC-20.




Figure 1: Flowchart showing damage assessment process

The purpose of rapid evaluation is rapid assessment for safety. It is to identify quickly which buildings are obviously unsafe, apparently safe and questionable.

In detailed Evaluation, buildings are inspected more thoroughly, with more investigation into the vertical and lateral load resisting systems. The purpose of detailed evaluations is not only to identify the level of safety but also to identify the buildings that can be restored and retrofitted or need to demolish. Only limited buildings that are difficult to recommend for retrofit or demolition will be recommended for detailed quantitative assessment.

However, after detail retrofit design and cost estimation, if the retrofitting cost is higher, it might be suggested for reconstruction. General recommendation for feasibility of retrofitting is up to 30% of the reconstruction cost of the same size building. Rapid evaluation methodology is described in **chapter 3** and the detail evaluation in **chapter 4** of this guideline.

2.2 Human Resources

All engineers, architects, sub-engineers can conduct the rapid evaluation once trained on rapid evaluation process and methodology. It is recommended that they are trained during normal time now and conduct refresher course after the earthquake again just before going to the field. Concerned

department needs to prepare the roster of trained professionals and their experience so that a right team is sent for different type of evaluation.

Engineers with structural engineering background and trained on detail evaluation methodology can conduct the detail evaluation for buildings. Engineers with lifelines background and trained on detail evaluation of lifelines can conduct the detail evaluation of lifelines.

| Engineers/ Architect Sub-engineers (Building Inspectors) | Engineers with Structures Background | Engineers with Lifeline Background |
|---|---|---|
| Rapid Evaluation of All Occupancies | Rapid Evaluation of All Occupancies Detail Evaluation of All Occupancies | Detailed Evaluation of Bridges, Roads, Airports, Treatment Plants, Pipelines, Reservoirs, Water Tanks and Dams |

3. Rapid Evaluation

3.1 General

The objective of the Rapid Evaluation is to quickly inspect and evaluate buildings in the damaged area with a minimum manpower available at the time of emergency. The rapid evaluation can be done by civil, structural, geotechnical engineers and architects with experience on building construction and trained on rapid evaluation methodology.

General situation during emergency is:

- Usually a scarcity of skilled manpower available to conduct building- by- building inspections
- Utilization of the talents and experiences of professionals involved in building construction
- Once all buildings in a given area have been inspected and those that are apparently unsafe have been posted, the remaining structures, the so called gray-area buildings are left for a detailed assessment by a structural engineer

Rapid evaluation is done just after the earthquake to assess the safety of buildings to judge whether people can enter the building or not. It can be done by visual inspection.

3.2 Safety Precaution

All possible safety precautions should be exercised as building under study could be in dilapidated condition and could loss its stability in whole or in parts causing casualty. The team must comprise at least two personnel, both trained in assessment works. The team personnel must wear safety hats when assessing the buildings. Before entering a house, its condition should be well assessed as the

house could be in dangerous state. Wherever the uncertainty exists and team is in doubt, it is better to be conservative.

3.3 Steps for Rapid Evaluation

The initial steps in the visual observation of earthquake damage are to identify the location of the wall in the building and to determine the dimensions of the wall (height, length, and thickness). A tape measure is used for quantifying the overall dimensions of the wall. A sketch of the wall elevation should then be prepared. The sketch should include sufficient detail to depict the dimensions of the wall, it should be roughly to scale, and it should be marked with the wall location. Observable damage such as cracks, *spalling* and exposed reinforcing bars should be indicated on the sketches. Sketches should be made in sufficient detail to indicate the approximate orientation and width of cracks. Crack width is measured using the crack comparator or tape measure at representative locations along significant cracks. Avoid holes and edge spalls when measuring crack widths. Crack widths typically do not change abruptly over the length of a crack. If the wall is accessible from both sides, the opposite side of the wall should be checked to evaluate whether the cracks extend through the thickness of the wall and to verify that the crack widths are consistent.

Photographs can be used to supplement the sketches. If the cracks are small, they may not show up in the photographs, except in extreme close-up shots. Paint, markers, or chalk can be used to highlight the location of cracks in photographs. However, photographs with highlighted crack should always be presented with a written disclaimer that the cracks have been highlighted and that the size of the cracks cannot be inferred from the photograph.

During a visual inspection, the engineer should carefully examine the wall for the type of damage and possible causes. Indications that the cracks or spalls may be recent or that the damage may have occurred prior to the earthquake should be noted. Visual observation of the nonstructural elements in the building can also be very useful in assessing the overall severity of the earthquake, the inter-story displacements experienced by the building, and the story accelerations. Full-height nonstructural items such as partitions and facades should be inspected for evidence of inter-story movement such as recent scrapes, cracked windows, or crushed wallboard.

Following steps are recommended for conducting rapid evaluation of earthquake damaged building.

I. Study the house from outside, take a walk around the house and do visual inspection

Visual inspection from outside and inside of the building is the only method applicable for rapid evaluation of buildings. Generally, earthquake damage to concrete and masonry walls (common building types in Nepal) is visible on the exposed surface. Observable types of damage include cracks, spalls and *delaminations*, permanent lateral displacement, and buckling or fracture of reinforcements.

II. Enter the house to do assessment inside if it is safe to do so

Enter the building if entering the house is safe. Inspect the house from inside as done from outside. Identify cracks, spalls and *delaminations*, joints opening, permanent lateral displacement, and buckling or fracture of reinforcements. Come out of the houses as soon as possible.

III. Fill-up the form, note the observations

Rapid evaluation form is given in **Annex III** of this guideline. The key information to be collected is:

- 1) Information about evaluator

- 2) Building Description: Owners’ name, Address, contact no, total plinth area, type of construction, Type of floor, type of roof, primary occupancy etc.
- 3) Damage conditions
- 4) Estimated building damage ratio
- 5) Safety status (Posting)
- 6) Further Actions

When filling the form, the evaluators must use:

General knowledge of construction - the evaluator must be able to look at any particular load carrying system and rapidly identify the system, know how it works, and the corresponding load path. For the frame buildings, beam-column system is the primary load carrying system while as for masonry structures, the walls are the main elements of the system.

Professional experience - the evaluator must have practical experience working with the various types of buildings and their load carrying systems. This experience may come from designing and detailing systems, reviewing the designs and details prepared by others, or inspecting the actual construction of the systems.

Good judgment - above all, evaluators must be able to look at a damaged or potentially damaged system and, based on their knowledge and experience, make a judgment on the ability of that system to withstand another event of approximately equal magnitude.

IV. Rapid Evaluation

Six main parameters are evaluated during rapid evaluation process. Safety of the building is judged primarily based on these six parameters. If the building has any of condition 1, 2, 3 or 5 as per the Table 1, the building is categorized as unsafe. If the building has condition 4 or 6, it can be termed as unsafe or area unsafe.

Table 1: Criteria for building being unsafe

| S.N. | Conditions | Posting |
|------|--|-----------------------|
| 1 | Building has collapsed, partially collapsed, or moved off its foundation | Unsafe |
| 2 | Building or any story is significantly out of plumb | Unsafe |
| 3 | Obvious severe damage to primary structural members, severe cracking of walls, severe cracking of columns, beam-column joints, buckling of reinforcement bars, or other signs of severe distress present | Unsafe |
| 4 | Obvious parapet, chimney, or other falling hazard present | Area Unsafe |
| 5 | Large fissures in ground, massive ground movement, or slope displacement present | Unsafe |
| 6 | Other hazard present (e.g. fallen power line, fallen tree) | Unsafe or Area Unsafe |

If these entire six factors give positive result the building is obviously safe. The remaining buildings with damage but do not fall under these six factors are questionable buildings and based on conditions limited entry or restricted use.

As the purpose of the rapid assessment is to identify the buildings’ safety rapidly, all the buildings that are done rapid assessment should undergo detail assessment explained in **Section 4** of this guideline.

Photo 1-4 below show different types of damage resulting to unsafe building.



3.4 Posting Safety Status

Three kinds of posting similar to ATC-20 are recommended in this guideline also. Posting classifications, colour and description of the posting is given in **Table 2** below.

Table 2: Posting Classifications

| Posting Classification | Color | Description |
|------------------------------|---------------|--|
| INSPECTED | Green | No apparent hazard found, although repairs may be required. Original lateral load capacity not significantly decreased. No restriction on use or occupancy |
| LIMITED ENTRY/Restricted Use | Yellow | Dangerous condition believed to be present. Entry by owner permitted only for emergency purposes and only at own risk. No usage on continuous basis. Entry by public not permitted. Possible major aftershock hazard |
| UNSAFE | Red | Extreme hazard may collapse. Imminent danger of collapse from an aftershock. Unsafe for occupancy or entry, except by authorities. |

3.4.1 Inspected

Inspected posting means habitable, minor or no damage - this *green* placard is used to identify buildings that have been inspected but in which no serious damage has been found. These structures are in a condition that allows them to be lawfully reoccupied; however, repairs may be necessary

INSPECTED

NO RESTRICTIONS ON USE OR OCCUPANCY

This structure has been inspected (as indicated below) and no apparent structural hazard has been found. Report any unsafe conditions to local authorities; reinspection may be required.

Exterior Only
 Exterior and Interior

Facility Name and Address:

Date _____
Time _____

This facility was inspected under emergency conditions for:

(Jurisdiction)
on the date and time noted.

Inspector ID/Agency:

Do Not Remove This Placard until
Authorized by Governing Authority.

Following are the main criteria for posting this classification:

- Observed damage, if any, does not appear to pose a safety risk
- Vertical or lateral capacity not significantly decreased
- Repairs may be required
- Lawful entry, occupancy and use permitted

3.4.2 Limited Entry or Restricted Use

Limited entry or restricted use means damage which represents some degree of threat to occupants. Restricted Use is intended for buildings that have been damaged; yet the damage does not totally preclude occupying the structure. It can mean that parts of a structure could be occupied, or it could be used to denote those buildings that can be entered for a brief period of time only to remove possessions. The use of a Restricted Use placard will minimize the number of buildings which will require additional safety assessments because restrictions can be placed on the use and occupancy of the structure until such a time as the owner can retain an architect or engineer to develop the necessary repair program.

RESTRICTED USE

Caution: This structure has been inspected and found to be damaged as described below:

Entry, occupancy, and lawful use are restricted as indicated below:

Do not enter the following areas: _____

Brief entry allowed for access to contents: _____

Other restrictions: _____

Facility name and address: _____

Date _____

Time _____

(**Caution:** Aftershocks since inspection may increase damage and risk.)

This facility was inspected under emergency conditions for: _____

(Jurisdiction)

Inspector ID / Agency _____

Do Not Remove, Alter, or Cover this Placard until Authorized by Governing Authority

Following are the main criteria for posting this classification:

- Some risk from damage in all or part of building
- Restricted on
 - duration of occupancy
 - areas of occupancy
 - Usage
- Restrictions enforced by owner / manager

3.4.3 Unsafe

UNSAFE posting means not habitable, significant threat to life safety. The red ATC-20 Unsafe placard is used on those structures with the most serious damage. Typically, these are structures that represent a threat to life-safety should they be occupied. It is important to note that this category does not mean the building must be demolished. This placard carries the statement, "THIS IS NOT A DEMOLITION ORDER" to clarify that the building simply is not safe enough to occupy. In the vast majority of cases, structures posted unsafe can be repaired to a safe and usable condition.

UNSAFE
DO NOT ENTER OR OCCUPY

Warning:
This structure has been seriously damaged and is unsafe. Do not enter. Entry may result in death or injury.

Comments: _____

Facility Name and Address: _____

Date _____
Time _____

This facility was inspected under emergency conditions for: _____
(Jurisdiction)
on the date and time noted.

Inspector ID/Agency: _____

Do Not Remove This Placard until Authorized by Governing Authority.

Following are the main criteria for posting this classification:

- Falling, collapse, or other hazard
- Does not necessarily indicate that demolition is required
- Owner must mitigate hazards to satisfaction of jurisdiction to gain entry

3.5 Limitations of Rapid Evaluation

The rapid evaluation is carried out just after an earthquake for the purpose of safety evaluation of the buildings so that people can decide to occupy or not enter the building following an earthquake. The result whatever comes from the rapid evaluation **MUST NOT BE USED FOR DEMOLITION** as many buildings that are assigned as UNSAFE might be possible to restore and retrofit.

4. Detail Evaluation

Detailed assessment is conducted after some time of an earthquake to assess level of damage in detail. Main purpose of this assessment is to assess compensation to household, planning for reconstruction activity or to assess level of intervention required for repair and retrofitting.

4.1 Understanding the Characteristics of Damaging Earthquake

During the evaluation of damage to concrete or masonry wall buildings, information on the characteristics of the damaging earthquake can lead to valuable insight on the performance characteristics of the structure. For example, if the ground motion caused by the earthquake can be estimated quantitatively, the analysis techniques can provide an estimate of the resulting maximum displacement of the structure. This displacement, in conjunction with the theoretical capacity curve, indicates an expected level of component damage. If the observed component damage is similar to that predicted, the validity of the theoretical model is verified in an approximate manner. If the damage differs, informed adjustments can be made to the model.

4.2 Review of Existing Building Data

The data collection process begins with the acquisition of documents describing the pertinent conditions of the building. Review of construction drawings simplifies field work and leads to a more complete understanding of the building. Original architectural and structural construction drawings are central to an effective and efficient evaluation of damage. Potential sources of these and other documents include the current and previous building owners, building departments, and the original architects or engineers. Drawings may also be available from architects or engineers who have performed prior evaluations for the building. In addition to construction drawings, it is helpful to assemble the following documents if possible:

- Site seismicity/geotechnical reports
- Structural calculations
- Construction specifications
- As Built Drawings
- Foundation reports
- Prior building assessments

Review of the existing building information serves several purposes. If reviewed before field investigations, the information facilitates the analytical identification of structural components. This preliminary analysis also helps to guide the field investigation to components that are likely to be damaged. Existing information can also help to distinguish between damage caused by the earthquake and pre-existing damage. Finally, the scope of the field inspection and testing program depends on the accuracy and availability of existing structural information. For example, if structural drawings reliably detail the size and placement of reinforcing, expensive and intrusive tests to verify conditions in critical locations may be unnecessary.

4.3 Assessing the Consequences of the Damaging Earthquake

Methods for inspecting and testing concrete and masonry wall buildings for earthquake damage fall into two general categories, nondestructive and intrusive. Nondestructive techniques do not require any removal of the integral portions of the components. In some cases, however, it may be necessary to remove finishes in order to conduct the procedure. In contrast, intrusive techniques involve extraction of structural materials for the purpose of testing or for access to allow inspection of portions of a component.

4.4 Assessing Pre-existing Conditions

Interpretation of the findings of damage observations requires care and diligence. When evaluating damage to a concrete or masonry wall, an engineer should consider all possible causes in an effort to distinguish between that attributable to the damaging earthquake and that which occurred earlier (pre-existing conditions).

Since the evaluation of earthquake damaged buildings is typically conducted within weeks or months of the event, cracking and spalling caused by earthquakes is normally relatively recent damage. Cracks associated with drying shrinkage or a previous earthquake, on the other hand, would be relatively old. General guidance for assessing the relative age of cracks based on visual observations is as follows.

Recent cracks typically have the following characteristics:

- Small, loose edge spalls
- Light, uniform color of concrete or mortar within crack
- Sharp, uneroded edges
- Little or no evidence of carbonation

Older cracks typically have the following characteristics:

- Paint or soot inside crack
- Water, corrosion, or other stains seeping from crack
- Previous, undisturbed patches over crack
- Rounded, eroded edges
- Deep carbonation

Evaluating the significance of damage requires an understanding of the structural behavior of the wall during the earthquake. The evaluating engineer must consider the implications of the observations with respect to the overall behavior of the building and the results of analytical calculations. The behavior must be correlated with the damage. If the observed damage is not reasonably consistent with the overall seismic behavior of the structure, the crack may have been caused by an action other than the earthquake.

4.5 Survey the Building from Outside

- Begin the survey by walking around the exterior of the building
- Try to determine the structural system
- Examine the structure for vertical discontinuities
- Examine the structure for irregular configuration in plan
- Look for cracking of exterior walls, glass frames etc., which are symptoms of excessive drift
- Examine non-structural elements
- Look for new fractures in the foundation or exposed lower wall of buildings
- Different Inspection and test required to conduct.

4.6 Examine the site for Geotechnical Hazards

- Examine the site for fissures, bulged ground, and vertical movements
- In hillside areas, examine the area for landslide displacement and debris encroaching onto the site
- Since geotechnical hazards can extend in area to include several or more buildings, undamaged buildings in an unstable area may be posted limited entry or unsafe

4.7 Inspect the structural system from inside the building

- Before entering the building, look for falling hazards and consider the danger of collapse
- Enter building
- Check the structural system

- Look in stairwells, basements, mechanical rooms etc. to view the structural system
- Examine the vertical load carrying system
- Examine the lateral load carrying system
- Check the different types of buildings using checklist

4.8 Inspect the Buildings in Critical Locations


Different types of buildings may suffer different types of damage. Masonry buildings have certain types of damage patterns and reinforced concrete buildings have other types. The buildings need to evaluate in detail with those identified damage patterns from past earthquakes. Different types of damage patterns for masonry and reinforced concrete buildings are given in this section for the reference.

4.8.1 Earthquake Damage Patterns in Masonry Buildings

4.8.1.1 Corner Separation

Separation of orthogonal walls due to in-plane and out-of-plane stresses at corners is one of the most common damage patterns in masonry buildings. Separations in both sides of a wall result to an unstable condition leading to out-of-plane failure. The failure is due to lack of lateral support at two ends of the wall during out of plane loading.

This type of failure significantly reduces the lateral load carrying system of the building if all the corners are separated. The decision for restoration/retrofitting and demolition depends on extent of such damage. If only limited numbers or portion of the walls is separated, the buildings can be restored and retrofitted. If all/most of the corners are separated it is difficult to restore the original capacity by restoration and retrofitting.



4.8.1.2 Diagonal Cracking

Diagonal cracking of piers either starting from corners of openings or in solid walls is another common type of damage to unreinforced masonry walls. The major reasons of the failure are either bed joint sliding or diagonal tension.

Bed joint sliding: In this type of behavior, sliding occurs on bed joints. In this type of damage, sliding on a horizontal plane, and a stair-stepped diagonal crack where the head joints open and close to allow for movement on the bed joint. Pure bed joint sliding is a ductile mode with significant hysteretic energy absorption capability. If sliding continues without leading to a more brittle mode such as toe crushing, then gradual degradation of the cracking region occurs until instability is reached.

Diagonal Tension: Typical diagonal tension cracking—resulting from strong mortar, weak units, and high compressive stress—can be identified by diagonal cracks (“X” cracks) that propagate through the units. In many cases, the cracking is sudden, brittle, and vertical load capacity drops quickly. The cracks may then extend to the toe and the triangles above and below the crack separate.

Significance of diagonal cracking for these two types of cases is given in Table 3 and Table 4 respectively (Ref: FEMA 306, Chapter 7).

Table 3: Level and description of damage to masonry wall pier in diagonal cracking on bed joint sliding mode

| LEVEL OF DAMAGE | DESCRIPTION OF DAMAGE | TYPICAL PERFORMANCE RESTORATION MEASURES |
|----------------------|---|---|
| Insignificant-Slight | <ol style="list-style-type: none"> Hairline cracks/spalled mortar in head and bed joints either on a horizontal plane or in a stair stepped fashion has been initiated, but no offset along the crack has occurred and the crack plane or stair-stepping is not continuous across the pier. No cracks in masonry units. | Not necessary for restoration of structural performance. (Measures may be necessary for restoration of nonstructural characteristics.) |
| Moderate | <ol style="list-style-type: none"> Horizontal cracks/spalled mortar at bed joints indicating that in-plane offset along the crack has occurred and/or opening of the head joints up to approximately 1/4”, creating a stair-stepped crack pattern. 5% of courses or fewer have cracks in masonry units. | <ul style="list-style-type: none"> Replacement or enhancement is required for full restoration of seismic performance. For partial restoration of performance: <ul style="list-style-type: none"> Repoint spalled mortar and open head joints. |
| Heavy | <ol style="list-style-type: none"> Horizontal cracks/spalled mortar on bed joints indicating that in-plane offset along the crack has occurred and/or opening of the head joints up to approximately 1/2”, creating a stair-stepped crack pattern. 5% of courses or fewer have cracks in masonry units. | <ul style="list-style-type: none"> Replacement or enhancement is required for full restoration of seismic performance. For partial restoration of performance: <ul style="list-style-type: none"> Repoint spalled mortar and open head joints. Inject cracks and open head joints. |
| Extreme | Vertical load-carrying ability is threatened. | Replacement or enhancement required. |

| | | |
|--|--|--|
| | <ul style="list-style-type: none"> • Stair-stepped movement is so significant that upper bricks have slid off their supporting brick. • Cracks have propagated into a significant number of courses of units. • Residual set is so significant that portions of masonry at the edges of the pier have begun or are about to fall. | |
|--|--|--|

Table 4: Level and description of damage to masonry wall pier in diagonal cracking on Diagonal Tension mode

| LEVEL OF DAMAGE | DESCRIPTION OF DAMAGE | TYPICAL PERFORMANCE RESTORATION MEASURES |
|----------------------|---|--|
| Insignificant-Slight | Hairline diagonal cracks in masonry units in fewer than 5% of courses. | Not necessary for restoration of structural performance. (Measures may be necessary for Restoration of nonstructural characteristics.) |
| Moderate | <ol style="list-style-type: none"> 1. Diagonal cracks in pier, many of which go through masonry units, with crack widths below 1/4”. 2. Diagonal cracks reach or nearly reach corners. 3. No crushing/spalling of pier corners. | <ul style="list-style-type: none"> • Repoint spalled mortar. • Inject cracks. |
| Heavy | <ol style="list-style-type: none"> 1. Diagonal cracks in pier, many of which go through masonry units, with crack widths over 1/4”. Damage may also include: <ul style="list-style-type: none"> • Some minor crushing/spalling of pier corners and/or • Minor movement along or across crack plane. | Replacement or enhancement is required for full restoration of seismic performance. For partial restoration of performance: <ul style="list-style-type: none"> • Replace/drypack damaged units. • Repoint spalled mortar. • Inject cracks. |
| Extreme | Vertical load-carrying ability is threatened <ul style="list-style-type: none"> • Significant movement or rotation along crack plane. • Residual set is so significant that portions of masonry at the edges of the pier have begun or are about to fall. | Replacement or enhancement is required |



Photo7: Diagonal cracking of masonry piers starting from corner of openings



Photo 8: Diagonal cracking of solid wall



Photo 9: Diagonal cracking of solid wall (Bed joint sliding mode)

4.8.1.3 Out of Plane Failure flexural failure

Out-of-plane failures are common in URM buildings. Usually they occur due to the lack of adequate wall ties, bands or cross walls. When ties are adequate, the wall may fail due to out-of-plane bending between floor levels. In case of long walls, without cross walls, the failure mode is out of plane bending horizontally. One mode of is rigid-body rocking motion occurring on three cracks: one at the top of the wall, one at the bottom, and one at mid-height. As rocking increases, the mortar and masonry units at the crack locations can be degraded, and residual offsets can occur at the crack planes. The ultimate limit state is that the walls rock too far and overturn. Important variables are the vertical stress on the wall and the height-to-thickness ratio of the wall. Thus, walls at the top of buildings and slender walls are more likely to suffer damage.

Table 5 compares different level of damages for out-of-plane flexural mode of failure (Ref: FEMA 306, Chapter 7). Photos 10 to 11 show the out of plane failure of masonry walls.

Table 5: Out-of-plane flexural failure of masonry wall

| LEVEL OF DAMAGE | DESCRIPTION OF DAMAGE | TYPICAL PERFORMANCE RESTORATION MEASURES |
|-----------------|-----------------------|--|
|-----------------|-----------------------|--|

| | | |
|-----------------------------|---|---|
| <p>Insignificant-Slight</p> | <ol style="list-style-type: none"> 1. Hairline cracks at floor/roof lines and mid-height of stories. 2. No out-of-plane offset or spalling of mortar along cracks. | <p>Not necessary for restoration of structural performance. (Measures may be necessary for restoration of nonstructural characteristics.)</p> |
| <p>Moderate</p> | <ol style="list-style-type: none"> 1. Cracks at floor/roof lines and mid-height of stories may have mortar spalls up to full depth of joint and possibly: <ul style="list-style-type: none"> • Out-of-plane offsets along cracks of up to 1/8". | <p>Repoint spalled mortar:</p> |
| <p>Heavy</p> | <ol style="list-style-type: none"> 1. Cracks at floor/roof lines and mid-height of stories may have mortar spalls up to full depth of joint. 2. Spalling and rounding at edges of units along crack plane. 3. Out-of-plane offsets along cracks of up to 1/2". | <p>Replacement or enhancement is required for full restoration of seismic performance. For partial restoration of out-of-plane performance:</p> <ul style="list-style-type: none"> • Replace/dry pack damaged units • Re-point spalled mortar |
| <p>Extreme</p> | <ol style="list-style-type: none"> 1. Vertical-load-carrying ability is threatened: <ul style="list-style-type: none"> • Significant out-of-plane or in-plane movement at top and bottom of piers "walking"). • Significant crushing/spalling of bricks at crack locations. | <p>Replacement or enhancement required.</p> |



Photo 10: Out of plane failure of stone wall

Photo 11: Out of plane failure of block wall

4.8.1.4 In-plane flexural failure

There are two types of failure mode for in-plane flexural failure. One with “Flexural Cracking/Toe Crushing/Bed Joint Sliding” and another with “Flexural Cracking/Toe Crushing” (Ref: FEMA 306)

Flexural Cracking/Toe Crushing/Bed Joint Sliding: This type of moderately ductile behavior has occurred in relatively short walls with L/h_{eff} ratio of about 1.7, in which bed joint sliding and toe crushing strength capacities are similar. Damage occurs in the following sequence. First, flexural cracking occurs at the heel of the wall. Then diagonally-oriented cracks appear at the toe of the wall, typically accompanied by spalling and crushing of the units. In some cases, toe crushing is immediately followed by a steep inclined crack propagating upward from the toe. Next, sliding occurs along a horizontal bed joint near the base of the wall, accompanied in some cases by stair stepped bed joint sliding at upper portions of the wall. With repeated cycles of loading, diagonal cracks increase. Finally, crushing of the toes or excessive sliding, leads to failure.

Flexural Cracking/Toe Crushing: This type of behavior typically occurs in stockier walls with $L/h_{eff} > 1.25$. Based on laboratory testing, four steps can usually be identified. First, flexural cracking happens at the base of the wall, but it does not propagate all the way across the wall. This can also cause a series of horizontal cracks to form above the heel. Second, sliding occurs on bed joints in the central portion of the pier. Third, diagonal cracks form at the toe of the wall. Finally, large cracks form at the upper corners of the wall. Failure occurs when the triangular portion of wall above the crack rotates off the crack or the toe crushes so significantly that vertical load is compromised. Note that, for simplicity, the figures below only show a single crack, but under cyclic loading, multiple cracks stepping in each direction are possible.

Significance of in-plane flexural cracking for these two types of cases is given in Table 6 and Table 7 respectively.

Table 6: In-plane flexural failure of masonry wall (Flexural Cracking/Toe Crushing/Bed Joint Sliding Case)


| LEVEL OF DAMAGE | DESCRIPTION OF DAMAGE | TYPICAL PERFORMANCE RESTORATION MEASURES |
|----------------------|---|--|
| Insignificant-Slight | <ol style="list-style-type: none"> 1. Horizontal hairline cracks in bed joints at the heel of the wall. 2. Possibly diagonally-oriented cracks and minor spalling at the toe of the | Not necessary for restoration of structural performance. (Measures may be necessary for restoration of nonstructural characteristics.) |

| | | |
|----------|--|---|
| | wall. | |
| Moderate | <ol style="list-style-type: none"> 1. Horizontal cracks/spalled mortar at bed joints at or near the base of the wall indicating that in-plane offset along the crack has occurred up to approximately 1/4". 2. Possibly diagonally-oriented cracks and spalling at the toe of the wall. Cracks extend upward several courses. 3. Possibly diagonally-oriented cracks at upper portions of the wall which may be in the units. | <ul style="list-style-type: none"> • Replace/dry pack damaged units. • Repoint spalled mortar and open head joints. • Inject cracks and open head joints. • Install pins and drilled dowels in toe regions. |
| Heavy | <ol style="list-style-type: none"> 1. Horizontal bed joint cracks near the base of the wall similar to Moderate, except width is up to approximately 1/2". 2. Possibly extensive diagonally-oriented cracks and spalling at the toe of the wall. Cracks extend upward several courses. 3. Possibly diagonally-oriented cracks up to 1/2" at upper portions of the wall. | <ul style="list-style-type: none"> • Replace/dry pack damaged units. • Repoint spalled mortar and open head joints. • Inject cracks and open head joints. • Install pins and drilled dowels in toe regions. |
| Extreme | <p>Vertical load-carrying ability is threatened</p> <ul style="list-style-type: none"> • Stair-stepped movement is so significant that upper bricks have slid off their supporting brick. • Toes have begun to disintegrate. • Residual set is so significant that portions of masonry at the edges of the pier have begun or are about to fall. | Replacement or enhancement required. |

Table 7: In-plane flexural failure of masonry wall (Flexural Cracking/Toe Crushing/)

| LEVEL OF DAMAGE | DESCRIPTION OF DAMAGE | TYPICAL PERFORMANCE RESTORATION MEASURES |
|------------------------|---|--|
| Insignificant-Moderate | <ol style="list-style-type: none"> 1. Horizontal hairline cracks in bed joints at the heel of the wall. 2. Horizontal cracking on 1-3 cracks in the central portion of the wall. No offset along the crack has occurred and the crack plane is not continuous | Not necessary for restoration of structural performance. (Measures may be necessary for restoration of nonstructural characteristics.) |

| | | |
|---------|--|---|
| | <p>across the pier.</p> <p>3. No cracks in masonry units.</p> | |
| Heavy | <p>1. Horizontal hairline cracks in bed joints at the heel of the wall.</p> <p>2. Horizontal cracking on 1-3 cracks in the central portion of the wall. Some offset along the crack may have occurred.</p> <p>3. Diagonal cracking at the toe of the wall, likely to be through the units, and some of units may be spalled.</p> | <p>Replacement or enhancement is required for full restoration of seismic performance.</p> <p>For partial restoration of performance:</p> <ul style="list-style-type: none"> • Repoint spalled mortar. • Inject cracks |
| Extreme | <p>1. Horizontal hairline cracks in bed joints at the heel of the wall.</p> <p>2. Horizontal cracking on 1 or more cracks in the central portion of the wall. Offset along the crack will have occurred.</p> <p>3. Diagonal cracking at the toe of the wall, likely to be through the units, and some of units may be spalled.</p> <p>4. Large cracks have formed at upper portions of the wall. In walls with aspect ratios of $L/h_{eff} > 1.5$, these cracks will be diagonally oriented; for more slender piers, cracks will be more vertical and will go through units.</p> | <p>Replacement or enhancement is required for full restoration of seismic performance.</p> <p>For partial restoration of performance:</p> <ul style="list-style-type: none"> • Replace/dry pack damaged units. • Repoint spalled mortar. • Inject cracks. • Install pins and drilled dowels in toe regions. |






Figure 2: Illustrations on in-plane flexural failure of masonry wall (Flexural Cracking/Toe Crushing/Bed Joint Sliding Case)




Fig 3: Illustrations on in-plane flexural failure of masonry wall (Flexural Cracking/Toe Crushing)

4.8.1.5 Delamination of Walls

Delamination of two wyths of masonry walls is another type of damage. This type of damage can be tested by sounding test described in section 4.9.1. At the last stage of this type of damage one wyth of the wall get collapsed. Phot 11 and 12 show the delamination of walls during earthquakes.



4.8.2 Earthquake Damage Patterns in Reinforced Concrete Frame Buildings


4.8.2.1 Beam-Column Joint Failure

This type of failure is caused by weak connections of the framing elements. Distress is caused by over-strength of the members framing into the connection, leading to very high principal tension stresses. Table 8 gives different level of connection damage.

Table 8: Beam-column joint damage

| LEVEL OF DAMAGE | DESCRIPTION OF DAMAGE | TYPICAL PERFORMANCE RESTORATION MEASURES |
|----------------------|--|---|
| Insignificant-Slight | Slight X hairline cracks in joint | Inject Cracks |
| Moderate | X-cracks in joint become more extensive and widen to about 1/8". | Inject Cracks |
| Heavy | <ul style="list-style-type: none"> Extensive X-cracks in joint widen to about 1/4". Exterior joints show cover concrete spalling off from back of joint. Some side cover may also spall off. | <ul style="list-style-type: none"> Remove spalled and loose concrete. Remove and replace buckled or fractured reinforcing. Provide additional ties over the length of the replaced bars. Patch concrete. Inject cracks. |
| Extreme | Significant loss of load carrying capacity <ul style="list-style-type: none"> Ties broken Concrete came out Bars Buckled | Restore/replacement |

Illustrations and photographs of Beam-Column Joint damage are given below. Illustrations are from FEMA 306.




4.8.2.2 Lap-splice Damage

Lack of sufficient lap length, in hinge zones, leads to eventual slippage of splice bars. The cover spalls off due to high compression stresses, exposing the core concrete and damaged lap splice zone. Table 9 gives different level of connection damage.

Table 9: Lap Splice Damage

| LEVEL OF DAMAGE | DESCRIPTION OF DAMAGE | TYPICAL PERFORMANCE RESTORATION MEASURES |
|----------------------|---|--|
| Insignificant-Slight | Flexural cracks at lap level. Slight hairline vertical cracks. | Inject cracks in frame. |
| Moderate | Tensile flexural cracks at floor slab level with some evidence of toe crushing over the bottom 1/2". Longitudinal splitting cracks loosen the cover concrete. | Inject cracks in frame. |
| Heavy | Significant spalling of the cover concrete over the length of the lap splice, exposing the core and reinforcing steel | Remove spalled and loose concrete. Provide additional ties over the length of the exposed bars. Patch concrete. Apply composite overlay to damaged region of column. |
| Extreme | Significant loss of load carrying capacity <ul style="list-style-type: none"> • Cover spalled • Core concrete cracked • Ties Broken • Reinforced bars slipped | Restore/replacement |

Illustrations and photographs of lap-splice damage are given below. Illustrations are from FEMA 306.



4.8.2.3 Short Column Damage

Short columns tend to attract seismic forces because of high stiffness relative to other columns in a story. Short column behavior may also occur in buildings with clerestory windows, or in buildings with partial height masonry infill panels.

If not adequately detailed, the columns may suffer a non-ductile shear failure which may result in partial collapse of the structure. A short column that can develop the shear capacity to develop the flexural strength over the clear height will have some ductility to prevent sudden non-ductile failure of the vertical support system.

Photos 15, 16 and 17 show the short column damage of the columns.



Photo 15: Slight-moderate damage



Photo 16: Heavy Damage



Photo 17: Extreme Damage

4.8.2.4 Soft-story damage

This condition commonly occurs in buildings in urban areas where ground floor is usually open for parking or shops for commercial purposes. Soft stories usually are revealed by an abrupt change in inter-story drift. Although a comparison of the stiffness in adjacent stories is the direct approach, a simple first step might be to plot and compare the inter-story drifts.

The photos 18 show the soft story damage of the columns.




Figure 4: Soft-story failure mechanism




Figure 5: Soft-story failure in a building with masonry infill



Photo 18: Earthquake damage due to soft story

4.8.2.5 Shear/flexure cracks in column and beam members

Column and beam members of reinforced concrete buildings sustain two basic types of failure, namely:

a) Flexure/Bending Failure: As the column/beam deform under increased loading, it can fail in two possible ways. If relatively more steel is present on the tension face, concrete crushes in compression; this is a brittle failure and is therefore undesirable. If less steel is present on the tension face, the steel yields first and redistribution occurs in the beam and eventually the concrete crushes in compression; this is a ductile failure.

b) Shear Failure: A column/beam may also fail due to shearing action. A shear crack is inclined at 45° to the horizontal. Closed loops stirrups and ties are provided to avoid such shearing action. Shear damage occurs when the area of these stirrups is insufficient. Shear failure is brittle, and therefore, has larger impact if this type of damage observed.



Photo 19: Shear cracks in beam near to support and at mid span



Photo 20: Shear crack in beam near to support



Photo 21: Shear crack in column



Photo 22: Buckling of column bars

4.8.2.6 Damage to Infill-Wall

Masonry infill panel in between concrete frames get damaged in in-plane and out-of plane. The out-of-plane failure pattern is discussed here.

Table 10 gives different level of infill wall damage (Ref: FEMA 306).

Table 10: Infill panel damage

| LEVEL OF DAMAGE | DESCRIPION OF DAMAGE | TYPICAL PERFORMANCE RESTORATION MEASURES |
|----------------------|---|--|
| Insignificant-Slight | Flexural cracking in the mortar beds around the perimeter, with hairline cracking in mortar bed at mid-height of panel. | Re-point spalled mortar. |
| Moderate | Crushing and loss of mortar along top, mid-height, bottom and side mortar beds. Possibly some in-plane damage, as evidenced by hair-line X-cracks in the central panel area. | Apply <i>shotcrete</i> , <i>ferro-cement</i> , or composite overlay to the infill. |
| Heavy | Severe corner-to-corner cracking with some out-of plane dislodgment of masonry. Top, bottom and mid height mortar bed is completely crushed and/or missing. There is some out-of-plane dislodgment of masonry. Concurrent in-plane damage should also be expected, as evidenced by extensive X-cracking | Remove and replace infill. |
| Extreme | The infill panel has failed in out of plane | Rebuilt infill wall |




Figure 6: Illustration of infill panel damage.



Photo 23: Moderate-Heavy Damage to Infill wall



Photo 24: Extreme Damage to Infill wall

4.9 Conduct Test

4.9.1 Rebound Hammer Test

Description

A rebound hammer provides a method for assessing the in-situ compressive strength of concrete. In this test, a calibrated hammer impact is applied to the surface of the concrete. The amount of rebound of the hammer is measured and correlated with the manufacturer's data to estimate the strength of the concrete. The method has also been used to evaluate the strength of masonry.


Equipment

A calibrated rebound hammer is a single piece of equipment that is hand operated

Execution

The person operating the equipment places the impact plunger of the hammer against the concrete and then presses the hammer until the hammer releases. The operator then records the value on the scale of the hammer. Typically three or more tests are conducted at a location. If the values from the tests are consistent, record the average value. If the values vary significantly, additional readings should be taken until a consistent pattern of results is obtained.

Since the test is relatively rapid, a number of test locations can be chosen for each wall. The values from the tests are converted into compressive strength using tables prepared by the manufacturer of the rebound hammer.

| | |
|---|--|
|  |  |
| <p>Photo 25: Use of Rebound hammer</p> | <p>Photo 26: Rebound hammer</p> |

Personal Qualification

A technician with minimal training can operate the rebound hammer. An engineer experienced with rebound hammer data should be available to supervise to verify that any anomalous values can be explained.

Reporting Requirements

The personnel conducting the tests should provide sketches of the wall, indicating the location of the tests and the findings. The sketch should include the following information:

- Mark the location of the test marked on either a floor plan or wall elevation.
- Record the number of tests conducted at a given location.
- Report either the average of actual readings or the average values converted into compressive strength along with the method used to convert the values into compressive strength.
- Report the type of rebound hammer used along with the date of last calibration.
- Record the date of the test.
- List the responsible engineer overseeing the test and the name of the company conducting the test.

Limitations

The rebound hammer does not give a precise value of compressive strength, but rather an estimate of strength that can be used for comparison. Frequent calibration of the unit is required (ACI, 1994). Although manufacturers’ tables can be used to estimate the concrete strength, better estimates can be obtained by removing core samples at selected locations where the rebound testing has been performed. The core samples are then subjected to compression tests. The rebound values from other

areas can be compared with the rebound values that correspond to the measured core compressive strength.

The results of the rebound hammer tests are sensitive to the quality of the concrete on the outer several inches of the wall. More reproducible results can be obtained from formed surfaces rather than from finished surfaces. Surface moisture and roughness can also affect the readings. The impact from the rebound hammer can produce a slight dimple in the surface of the wall. Do not take more than one reading at the same spot, since the first impact can affect the surface, and thus affect the results of a subsequent test.

When using the rebound hammer on masonry, the hammer should be placed at the centre of the masonry unit. The values of the tests on masonry reflect the strength of the masonry unit and the mortar. This method is only useful in assessing the strength of the outer wythe of a multi-wythe wall.
Rebound Hammer Test

4.9.2 Rebar Detection Test

Description

Cover-meter is the general term for a rebar detector used to determine the location and size of reinforcing steel in a concrete or masonry wall. The basic principle of most rebar detectors is the interaction between the reinforcing bar and a low frequency magnetic field. If used properly, many types of rebar detectors can also identify the amount of cover for the bar and/or the size of the bar. Rebar detection is useful for verifying the construction of the wall, if drawings are available, and in preparing as-built data if no previous construction information is available.

Equipment

Several types and brands of rebar detectors are commercially available. The two general classes are those based on the principle of magnetic reluctance and those based on the principle of eddy. The various models can have a variety of features including analogue or digital readout, audible signal, one handed operation, and readings for reinforcing bars and *prestressing* tendons. Some models can store the data on floppy disks to be imported into computer programs for plotting results.

Conducting Test


The unit is held away from metallic objects and calibrated to zero reading. After calibration, the unit is placed against the surface of the wall. The orientation of the probe should be in the direction of the rebar that is being detected. The probe is slid slowly along the wall, perpendicular to the orientation of the probe, until an audible or visual spike in the readout is encountered.

The probe is passed back and forth over the region of the spike to find the location of the maximum reading, which should correspond to the location of the rebar. This location is then marked on the wall. The procedure is repeated for the perpendicular direction of reinforcing.

If size of the bar is known, the cover-meter readout can be used to determine the depth of the reinforcing bar. If the depth of the bar is known, the readout can be used to determine the size of the bar. If neither quantity is known, most rebar detectors can be used to determine both the size and the depth using a spacer technique.

The process involves recording the peak reading at a bar and then introducing a spacer of known thickness between the probe and the surface of the wall. A second reading is then taken. The two readings are compared to estimate the bar size and depth. Intrusive testing can be used to help

interpret the data from the detector readings. Selective removal of portions of the wall can be performed to expose the reinforcing bars. The rebar detector can be used adjacent to the area of removal to verify the accuracy of the readings.



Personnel Qualifications

The personnel operating the equipment should be trained and experienced with the use of the particular model of cover-meter being used and should understand the limitations of the unit.

Reporting Requirements

The personnel conducting the tests should provide a sketch of the wall indicating the location of the testing and the findings. The sketch should include the following information:

- Mark the locations of the test on either a floor plan or wall elevation.
- Report the results of the test, including bar size and spacing and whether the size was verified.
- List the type of rebar detector used.
- Report the date of the test.
- List the responsible engineer overseeing the test and the name of the company conducting the test.

Limitations

Pulse-velocity measurements require access to both sides of the wall. The wall surfaces need to be relatively smooth. Rough areas can be ground smooth to improve the acoustic coupling. *Couplant* must be used to fill the air space between the transducer and the surface of the wall. If air voids exist between the transducer and the surface, the travel time of the pulse will increase, causing incorrect readings.

Some *couplant* materials can stain the wall surface. Non-staining gels are available, but should be checked in an inconspicuous area to verify that it will not disturb the appearance.

Embedded reinforcing bars, oriented in the direction of travel of the pulse, can affect the results, since the ultrasonic pulses travel through steel at a faster rate than will significantly affect the results. The moisture content of the concrete also has a slight effect (up to about 2 percent) on the pulse velocity.

Pulse-velocity measurements can detect the presence of voids or discontinuities within a wall; however, these measurements cannot determine the depth of the voids.

4.9.3 In-Situ Testing In-Place Shear

Description

The shear strength of unreinforced masonry construction depends largely on the strength of the mortar used in the wall. An in-place shear test is the preferred method for determining the strength of existing mortar. The results of these tests are used to determine the shear strength of the wall.

Equipment

- Chisels and grinders are needed to remove the bricks and mortar adjacent to the test area.
- A hydraulic ram, calibrated and capable of displaying the applied load.
- A dial gauge, calibrated to 0.001 inch.

Execution

Prepare the test location by removing the brick, including the mortar, on one side of the brick to be tested. The head joint on the opposite side of the brick to be tested is also removed. Care must be exercised so that the mortar joint above or below the brick to be tested is not damaged.

The hydraulic ram is inserted in the space where the brick was removed. A steel loading block is placed between the ram and the brick to be tested so that the ram will distribute its load over the end face of the brick. The dial gauge can also be inserted in the space.

The brick is then loaded with the ram until the first indication of cracking or movement of the brick. The ram force and associated deflection on the dial gage are recorded to develop a force-deflection plot on which the first cracking or movement should be indicated. A dial gauge can be used to calculate a rough estimate of shear stiffness.

Inspect the collar joint and estimate the percentage of the collar joint that was effective in resisting the force from the ram. The brick that was removed should then be replaced and the joints repointed.



Photo 29-30: Test set up for In-situ Shear test

Personnel Qualifications

The technician conducting this test should have previous experience with the technique and should be familiar with the operation of the equipment. Having a second technician at the site is useful for recording the data and watching for the first indication of cracking or movement. The structural engineer or designee should choose test locations that provide a representative sampling of conditions.

Reporting Results

The personnel conducting the tests should provide a written report of the findings to the evaluating engineer. The results for the in-place shear tests should contain, at a minimum, the following information for each test location:

- Describe test location or give the identification number provided by the engineer.
- Specify the length and width of the brick that was tested, and its cross-sectional area.
- Give the maximum mortar strength value measured during the test, in terms of force and stress.
- Estimate the effective area of the bond between the brick and the grout at the collar joint.
- Record the deflection of the brick at the point of peak applied force.
- Record the date of the test.
- List the responsible engineer overseeing the test and the name of the company conducting the test.

Limitations

This test procedure is only capable of measuring the shear strength of the mortar in the outer wythe of a multi-wythe wall. The engineer should verify that the exterior wythe being tested is a part of the structural wall, by checking for the presence of header courses. This test should not be conducted on veneer wythes.

Test values from exterior wythes may produce lower values when compared with tests conducted on inner wythes. The difference can be due to weathering of the mortar on the exterior wythes. The exterior brick may also have a reduced depth of mortar for aesthetic purposes.

The test results can only be qualitatively adjusted to account for the presence of mortar in the collar joints. If mortar is present in the collar joint, the engineer or technician conducting the test is not able to discern how much of that mortar actually resisted the force from the ram.

The personnel conducting the tests must carefully watch the brick during the test to accurately determine the ram force at which first cracking or movement occurs. First cracking or movement indicates the maximum force, and thus the maximum shear strength. If this peak is missed, the values obtained will be based only on the sliding friction contribution of the mortar, which will be less than the bond strength contribution.


4.10 Detail Evaluation

Detail evaluation form is given in **Annex IV** of this guideline. Form should be filled in reference with section 4.1 to 4.9 mentioned above. The detail evaluation should also recommend different grade of damage. The damage grade goes from damage grade 1 to damage grade 5. Different level of damage grades with photographs for masonry and reinforced concrete buildings are given in section 4.11 of this guideline.



4.11 Identification of Damage Levels

4.11.1.1 Earthquake damage grades of Masonry buildings with flexible floor and roof

Damage Grade 1

| | |
|--|---|
|  | |
| <p>Thin cracks in plaster, falling of plaster bits in limited parts, fall of loose stone from upper part of building in rare cases</p> | <p>Building need not be vacated, only architectural repairs needed, Seismic strengthening advised</p> |

Damage Grade 2

| | |
|--|--|
|  |  |
| <p>Thin cracks in many walls, falling of plaster in last bits over large area, damage to non-structural parts like chimney, projecting cornices; The load carrying capacity s not reduced appreciably.</p> | <p>Architecture repairs needed, Seismic strengthening advised.</p> |

Damage Grade 3



Large and extensive cracks in most walls, roof tiles detach, tilting or falling of chimneys, failure of individual non-structural elements such as partition/ gable walls. Load carrying capacity of structure is partially reduced.

Cracks in wall need grouting, architectural repairs required, Seismic strengthening advised



Damage Grade 4



Gaps occur in walls, walls collapse, partial structural failure of floor/ roof, Building takes a dangers state.


Vacate the building, demolish and construct or extensive restoration and strengthening

Damage Grade 5



| | |
|---|--|
|  |  |
| <p>Total or near total collapse</p> | <p>Clear the site and reconstruction</p> |

4.11.1.2 Earthquake damage grades of Masonry buildings with rigid floor and roof


Damage Grade 1

| | |
|--|---|
|  | |
| <p>Thin cracks in plaster, falling of plaster bits in limited parts, fall of loose stone from upper part of building in rare cases</p> | <p>Building need not be vacated, only architectural repairs needed, Seismic strengthening advised</p> |



Damage Grade 2

| | |
|---|--|
|  |  |
| <p>Thin cracks in many walls, falling of plaster in last bits over large area, damage to non-structural parts like chimney, projecting cornices; The load carrying capacity is not reduced appreciably.</p> | <p>Architecture repairs needed, Seismic strengthening advised.</p> |


Damage Grade 3

| | |
|---|--|
|  | |
| <p>Large and extensive cracks in most walls, roof tiles detach, tilting or falling of chimneys, failure of individual non-structural elements such as partition/ gable walls. Load carrying capacity of structure is partially reduced.</p> | <p>Cracks in wall need grouting, architectural repairs required, Seismic strengthening advised</p> |

Damage Grade 4

| | |
|--|---|
|  |  |
| <p>Gaps occur in walls, walls collapse, partial structural failure of floor/ roof, Building takes a dangers state.</p> | <p>Vacate the building, demolish and construct or extensive restoration and strengthening</p> |



Damage Grade 5

| | |
|---|--|
|  | |
| <p>Total or near total collapse</p> | <p>Clear the site and reconstruction</p> |


4.11.1.3

4.11.1.4 Earthquake damage grades of Reinforced Concrete Buildings

Damage Grade 1

| | |
|--|--|
|  |  |
| <p>Fine cracks in plaster over frame members or in walls at the base, Fine cracks in partitions and infill</p> | <p>Building need not be vacated, only architectural repairs needed, Seismic strengthening advised.</p> |

Damage Grade 2

| | | |
|---|---|--|
|  | <p>Cracks in columns and beams of frame and in structural walls, Cracks in partition and infill walls, fall of brittle plaster and cladding, falling mortar from joints of wall panel</p> | <p>Architecture repairs needed, Seismic strengthening advised.</p> |
|---|---|--|

Damage Grade 3



Cracks in column and beam at the base, spalling of concrete covers, buckling of steel bars, Large cracks in partitions and infill walls, failure of individual infill panels

Cracks in wall need grouting, architectural repairs required, Seismic strengthening advised



Damage Grade 4



Large cracks in structural elements with compression failure of concrete and fracture of rebars, bond failure of beam bars, tilting of columns, collapse of few columns or single upper floor

Vacate the building, demolish and construct or extensive restoration and strengthening

Damage Grade 5

| | |
|---|--|
|  |  |
| <p>Collapse of ground floor or parts of the building</p> | <p>Clear the site and reconstruction</p> |

5. References


18. Arya, A. S. et al; 1986, Guidelines for Earthquake Resistant Non-engineered Construction, International Association for Earthquake Engineering.
19. Bothara, J. K., Pandey, B. H., Guragain, R., 2004, Retrofitting of Low Strength Masonry School Buildings, NZSEE,
20. Building Construction under Seismic conditions in Balkan Region, 1983, Repair and Strengthening of Reinforced Concrete, Stone, Brick-masonry Buildings, UNDP/ UNIDO/RER 79/015, Vienna.
21. Central Public Works Department, Indian Building Congress in association with Indian Institute of Technology Madras, Handbook on “Seismic Retrofit of Buildings”, 2008
22. EMS, 1998, *European Macro-seismic Scale*, ONLINE,
http://www.gfz-potsdam.de/pb5/pb53/projekt/ems/core/ems_cor.htm
23. Federal Emergency Management Agency, (FEMA 273), NEHRP Guidelines For The Seismic Rehabilitation Of Buildings, Building Seismic Safety Council, Washington D. C., 1988.
24. Federal Emergency Management Agency, (FEMA 274), NEHRP Commentary On the Guidelines For The Seismic Rehabilitation Of Buildings, Building Seismic Safety Council, Washington D. C., 1988.
25. Federal Emergency Management Agency, (FEMA 356), Pre-standard and Commentary for the Seismic Rehabilitation of Buildings, Building Seismic Safety Council, Washington D. C., 2000.
26. IS 1893:2002; Criteria for earthquake resistant design of structures, Bureau of Indian Standard.
27. JICA, 2002, *The Study on Earthquake Disaster Mitigation in the Kathmandu Valley, Kingdom of Nepal*, Japan International Corporation Agency and Ministry of Home Affairs, GoN.

28. NBC 105-1994, Seismic Design of Buildings in Nepal, Govt. of Nepal, Ministry of Housing and Physical Planning, Department of Buildings, Nepal, 1995.
29. NBC 203-1994, Guidelines for Earthquake Resistant Building Construction: Low Strength Masonry, Govt. of Nepal, Ministry of Housing and Physical Planning, Department of Buildings, Nepal, 1995.
30. New Zealand National Society for Earthquake Engineering, 1995, Guidelines for Assessing and Strengthening Earthquake Risk Building: Unreinforced Masonry (Draft Copy), New Zealand National Society for Earthquake Engineering.
31. Procedure for post-earthquake safety evaluation of buildings, (ATC 20), Applied technology council, 3 Twin Dolphin Drive, Suite 275 Redwood City, California 94065
32. Federal Emergency Management Agency, (FEMA 154), Rapid Visual Screening of Buildings for Potential Seismic Hazards: A Handbook. Second Edition, Building Seismic Safety Council, Washington D. C., 1988.
33. Federal Emergency Management Agency, (FEMA 306), Evaluation of Earthquake Damaged Concrete and Masonry Wall Buildings: Basic Procedures Manual, Building Seismic Safety Council, Washington D. C., 1988.
34. Federal Emergency Management Agency, (FEMA 307), Evaluation of Earthquake Damaged Concrete and Masonry Wall Buildings: Technical Resources, Building Seismic Safety Council, Washington D. C., 1988.

35.

ANNEXES

Annex I: Examples of Rapid Evaluation






Annex II: Examples of Detailed Evaluated Buildings



Annex III: Rapid Evaluation Form

| Rapid Evaluation Safety Assessment Form | | | | |
|---|--|--|--|--|
| Inspection | | | | |
| Inspector ID: _____ | Inspection date and time: _____ | <input type="checkbox"/> AM | <input type="checkbox"/> PM | |
| Organization: _____ | Areas inspected: <input type="checkbox"/> Exterior only | <input type="checkbox"/> Exterior and interior | | |
| Building Description | | Address: _____ | | |
| Building Name: _____ | | District: _____ | | |
| Building contact/phone: _____ | | Municipality/VDC: _____ | | |
| Approx. "Footprint area" (sq. ft): _____ | | Ward No: _____ Toile: _____ | | |
| Type of Construction | | | | |
| <input type="checkbox"/> Adobe | <input type="checkbox"/> Stone in mud | <input type="checkbox"/> Stone in cement | <input type="checkbox"/> Brick in cement | <input type="checkbox"/> Wood frame |
| <input type="checkbox"/> Bamboo | <input type="checkbox"/> Brick in mud | <input type="checkbox"/> Brick in cement | <input type="checkbox"/> R.C frame | <input type="checkbox"/> Others: _____ |
| Type of Floor | | Primary Occupancy: | | |
| <input type="checkbox"/> Flexible | <input type="checkbox"/> Rigid | <input type="checkbox"/> Residential | <input type="checkbox"/> Hospital | <input type="checkbox"/> Government office |
| Type of Roof | | <input type="checkbox"/> Educational | <input type="checkbox"/> Industry | <input type="checkbox"/> Office Institute |
| <input type="checkbox"/> Flexible | <input type="checkbox"/> Rigid | <input type="checkbox"/> Commercial | <input type="checkbox"/> Club | <input type="checkbox"/> Hotel/Restaurant |
| | | <input type="checkbox"/> Others: _____ | | |
| Evaluation | | | | |
| Observed Conditions: | Minor/None | Moderate | Severe | Estimated Building Damage (excluding contents) |
| ➤ Collapsed, partially collapsed, or moved off its foundation | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> None |
| ➤ Building or any story is out of plumb | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> 0-1% |
| ➤ Damage to primary structural members, cracking of walls, or other signs of distress present | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> 1-10% |
| ➤ Parapet, chimney, or other falling hazard | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> 10-30% |
| ➤ Large fissures in ground, massive ground movement, or slope displacement present | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> 30-60% |
| ➤ Other hazard (Specify) e.g tree, power line etc: | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> 60-100% |
| _____ | | | | <input type="checkbox"/> 100% |
| Comments: _____ | | | | |
| _____ | | | | |
| Posting Choose a posting based on the evaluation and team judgment. Severe conditions endangering the overall building are grounds for an Unsafe posting. Localized Severe and overall Moderate conditions may allow a Restricted Use posting. Post INSPECTED placed at main entrance. Post RESTRICTED USE and UNSAFE placards at all entrances. | | | | |
| <input type="checkbox"/> INSPECTED (Green placard) | <input type="checkbox"/> RESTRICTED USE (Yellow placard) | <input type="checkbox"/> UNSAFE (Red placard) | | |
| Record any use and entry restrictions exactly as written on placard: _____ | | | | |
| _____ | | | | |
| Further Actions Check the boxes below only if further actions are needed. | | | | |
| <input type="checkbox"/> Barricades needed in the following areas: | | | | |
| <input type="checkbox"/> Detailed evaluation recommended: | <input type="checkbox"/> Structural | <input type="checkbox"/> Geotechnical | <input type="checkbox"/> Other _____ | |
| Comments: _____ | | | | |
| _____ | | | | |

Annex IV: Detail Evaluation Form

| Detailed Evaluation Safety Assessment Form | |
|--|--|
| Inspection | |
| Inspector ID: _____ | Inspection date and time: _____ <input type="checkbox"/> AM <input type="checkbox"/> PM |
| Organization: _____ | Areas inspected: <input type="checkbox"/> Exterior only <input type="checkbox"/> Exterior and interior |
| Building Description | |
| Building Name: _____ | Address: _____ |
| Building contact/phone: _____ | District: _____ |
| Municipality/VDC: _____ | Ward No: _____ Toile: _____ |
| Approx. "Footprint area" (sq. ft): _____ | |
| Type of Construction | |
| <input type="checkbox"/> Adobe | <input type="checkbox"/> Stone in mud |
| <input type="checkbox"/> Bamboo | <input type="checkbox"/> Brick in mud |
| <input type="checkbox"/> Stone in cement | <input type="checkbox"/> Brick in cement |
| <input type="checkbox"/> Brick in cement | <input type="checkbox"/> R.C frame |
| <input type="checkbox"/> Wood frame | <input type="checkbox"/> Others: _____ |
| Type of Floor | |
| <input type="checkbox"/> Flexible | <input type="checkbox"/> Rigid |
| Primary Occupancy: | |
| <input type="checkbox"/> Residential | <input type="checkbox"/> Hospital |
| <input type="checkbox"/> Educational | <input type="checkbox"/> Industry |
| <input type="checkbox"/> Commercial | <input type="checkbox"/> Club |
| <input type="checkbox"/> Government office | <input type="checkbox"/> Office Institute |
| <input type="checkbox"/> Police station | <input type="checkbox"/> Hotel/Restaurant |
| <input type="checkbox"/> Mix | <input type="checkbox"/> Others: _____ |
| Type of Roof | |
| <input type="checkbox"/> Flexible | <input type="checkbox"/> Rigid |
| Sketch (Optional) | |
| <p>Provide a sketch of the building or damage portions, Indicate damage points.</p> <p>Estimated Building Damage</p> <p>If requested by the jurisdiction, estimate building damage (repair cost ÷ replacement cost, excluding contents).</p> <p><input type="checkbox"/> None</p> <p><input type="checkbox"/> 0-1%</p> <p><input type="checkbox"/> 1-10%</p> <p><input type="checkbox"/> 10-30%</p> <p><input type="checkbox"/> 30-60%</p> <p><input type="checkbox"/> 60-100%</p> <p><input type="checkbox"/> 100%</p> |  |

